

Pipe Master Data

Location

Drainage Area		Street	TREMONT AVE
Pipe Segment Ref.	MASDCB001-MSADFT001	City	MASSILON
Location Code			
Location Details			

Pipe

Pipe Use	Stormwater Pipe
Height (Diameter)	30 in
Width	
Shape	Circular
Material	Vitrified Clay Pipe
Lining Method	
Coating Method	
Pipe Joint Length	
Total Length	62.300 ft
Year Constructed	
Year Renewed	

Manholes

Upstream

Downstream

Number	
Rim to Invert	
Rim to Grade	
Grade to Invert	
Northing	
Easting	
Elevation	
Coordinate System	
Vertical Datum	
GPS Accuracy	

PACP Inspection Report

General information

Project	P/O Number	Reviewed by
Owner	Work Order No. TV0202	Certificate No.
Customer CITY OF MASSILON		
Purpose of Survey Routine Assessment		
COF		
Pressure Value		
Surveyed by BRANDON LUERS	Date 10/4/2024	Weather Dry - No precipitation during survey
Certificate No. U-0420-703R4106	Time 09:05	Pre-Cleaning No Pre-Cleaning
Inspection Status Complete Inspection	Date Cleaned	
Inspection Tech. CCTV	Flow Control	
Direction of Survey Downstream		

Location

Drainage Area	Street	TREMONT AVE
Pipe Segment Ref. MASDCB001-MSADFT001	City	MASSILON
Location Code		
Location Details		

Pipe

Pipe Use Stormwater Pipe
Height (Diameter) 30 in
Width
Shape Circular
Material Vitrified Clay Pipe
Lining Method
Coating Method
Pipe Joint Length
Total Length 62.300 ft
Length Surveyed 62.300 ft
Year Constructed
Year Renewed

Manholes

Upstream

Downstream

Number
Rim to Invert
Rim to Grade
Grade to Invert

Northing
Easting
Elevation

Coordinate System
Vertical Datum
GPS Accuracy

Distance	Video Ref.	Code	Description	Cont. Defect	Value			Grade	Joint	Circumferential Location		Image	Remarks
					Dimension		%			From	To		
					1st	2nd							
0.00	00:00:04	ACB	Access Point Catch Basin									001	MASDCB001
0.00	00:00:29	MWL	Miscellaneous Water Level			5						002	
2.10	00:00:42	TF	Tap Factory		24					03		003	
62.30	00:03:11	ATC	Access Point Tee Connection							06		004	

Quick Rating

QSR **QMR** **QOR**
0000 0000 0000

Overall Rating (OR)

Structural **O&M**
0 0

Rating Index (RI)

Structural **O&M**
0.0 0.0


Segment Grade

	1	2	3	4	5
Structural	0	0	0	0	0
O&M	0	0	0	0	0

Pipe Segment Graphics

General information				Location	
Project				Drainage Area	
Owner				Pipe Segment Ref. MASDCB001-MSADFT001	
Surveyed by		BRANDON LUERS		Location Code	
Date		10/4/2024	Time	09:05	Street
Direction of Survey		Downstream		TREMONT AVE	
				City	
				MASSILON	
Pipe					
Pipe Use		Stormwater Pipe		Total Length	62.300 ft
Dimension [in]		30		Length Surveyed	62.300 ft
Shape		Circular		Upstream MH	
Material		Vitrified Clay Pipe		Downstream MH	
Quick Rating			Overall Rating (OR)		Rating Index (RI)
Segment Grade			1		2
3			4		5
QSR	QMR	QOR	Structural	O&M	Structural
0000	0000	0000	0	0	0
					O&M
					0

Drawing direction: In inspection direction



Pipe Segment Images

Surveyed by	BRANDON LUERS	Date	10/4/2024	Pipe Segment Ref.	MASDCB001-MSA
Owner				Upstream Manhole	
Pipe Use	Stormwater Pipe			Downstream Manhole	
Dimension [in]	30				

Access Point Catch Basin,
MASDCB001

Image Ref. **001**

Video 00:00:04
Dist. downstream 0.00 ft
Code ACB
C. Location



Miscellaneous Water Level, Water
level = 5 %

Image Ref. **002**

Video 00:00:29
Dist. downstream 0.00 ft
Code MWL
C. Location



Pipe Segment Images

Surveyed by	BRANDON LUERS	Date	10/4/2024	Pipe Segment Ref.	MASDCB001-MSA
Owner				Upstream Manhole	
Pipe Use	Stormwater Pipe			Downstream Manhole	
Dimension [in]	30				

Tap Factory at 3 o'clock, Diameter = 24 in.

Image Ref. 003

Video 00:00:42
Dist. downstream 2.10 ft
Code TF
C. Location 03



Access Point Tee Connection

Image Ref. 004

Video 00:03:11
Dist. downstream 62.30 ft
Code ATC
C. Location 06

