

Pipe Master Data

Location

Drainage Area		Street	TREMONT AVE
Pipe Segment Ref.	MASDMH005-MASDMH004	City	MASSILON
Location Code			
Location Details			

Pipe

Pipe Use	Stormwater Pipe
Height (Diameter)	12 in
Width	
Shape	Circular
Material	Vitrified Clay Pipe
Lining Method	
Coating Method	
Pipe Joint Length	
Total Length	202.900 ft
Year Constructed	
Year Renewed	

Manholes

Upstream

Downstream

Number	
Rim to Invert	
Rim to Grade	
Grade to Invert	
Northing	
Easting	
Elevation	
Coordinate System	
Vertical Datum	
GPS Accuracy	

PACP Inspection Report

General information

Project	P/O Number	Reviewed by
Owner	Work Order No. TV0202	Certificate No.
Customer CITY OF MASSILON		
Purpose of Survey Routine Assessment		
COF		
Pressure Value		
Surveyed by BRANDON LUERS	Date 10/4/2024	Weather Dry - No precipitation during survey
Certificate No. U-0420-703R4106	Time 10:15	Pre-Cleaning No Pre-Cleaning
Inspection Status Complete Inspection	Date Cleaned	
Inspection Tech. CCTV	Flow Control	
Direction of Survey Downstream		

Location

Drainage Area	Street	TREMONT AVE
Pipe Segment Ref. MASDMH005-MASDMH004	City	MASSILON
Location Code		
Location Details		

Pipe

Pipe Use Stormwater Pipe
Height (Diameter) 12 in
Width
Shape Circular
Material Vitrified Clay Pipe
Lining Method
Coating Method
Pipe Joint Length
Total Length 202.900 ft
Length Surveyed 202.900 ft
Year Constructed
Year Renewed

Manholes

Upstream

Downstream

Number
Rim to Invert
Rim to Grade
Grade to Invert

Northing
Easting
Elevation

Coordinate System
Vertical Datum
GPS Accuracy

Distance	Video Ref.	Code	Description	Cont. Defect	Value		%	Grade	Joint	Circumferential Location		Image	Remarks
					Dimension					From	To		
					1st	2nd							
0.00	00:00:01	AMH	Access Point Manhole									031	MASDMH005
0.00	00:00:02	MWL	Miscellaneous Water Level				5					032	
202.90	00:03:39	AMH	Access Point Manhole									033	REACHED MASDMH004

Quick Rating

QSR **QMR** **QOR**
0000 0000 0000

Overall Rating (OR)

Structural **O&M**
0 0

Rating Index (RI)

Structural **O&M**
0.0 0.0


Segment Grade

	1	2	3	4	5
Structural	0	0	0	0	0
O&M	0	0	0	0	0

Pipe Segment Graphics

General information				Location									
Project				Drainage Area									
Owner				Pipe Segment Ref. MASDMH005-MASDMH004									
Surveyed by		BRANDON LUERS		Location Code									
Date		10/4/2024	Time		10:15								
Direction of Survey		Downstream											
Pipe													
Pipe Use			Stormwater Pipe		Total Length	202.900 ft							
Dimension [in]			12		Length Surveyed	202.900 ft							
Shape			Circular		Upstream MH								
Material			Vitrified Clay Pipe		Downstream MH								
Quick Rating			Overall Rating (OR)		Rating Index (RI)		Segment Grade		1	2	3	4	5
QSR	QMR	QOR	Structural	O&M	Structural	O&M	Structural	0	0	0	0	0	0
0000	0000	0000	0	0	0.0	0.0	O&M	0	0	0	0	0	0

Drawing direction: In inspection direction



Pipe Segment Images

Surveyed by	BRANDON LUERS	Date	10/4/2024	Pipe Segment Ref.	MASDMH005-MAS
Owner				Upstream Manhole	
Pipe Use	Stormwater Pipe			Downstream Manhole	
Dimension [in]	12				

Access Point Manhole,
MASDMH005

Image Ref. **031**

Video 00:00:01
Dist. downstream 0.00 ft
Code AMH
C. Location



Miscellaneous Water Level, Water
level = 5 %

Image Ref. **032**

Video 00:00:02
Dist. downstream 0.00 ft
Code MWL
C. Location



Pipe Segment Images

Surveyed by	BRANDON LUERS	Date	10/4/2024	Pipe Segment Ref.	MASDMH005-MAS
Owner				Upstream Manhole	
Pipe Use	Stormwater Pipe			Downstream Manhole	
Dimension [in]	12				

Access Point Manhole, REACHED
MASDMH004

Image Ref. **033**

Video 00:03:39

Dist. downstream 202.90 ft

Code AMH

C. Location

