



			Pipes Inspected, Massillon Levee					
Size (Inches)	Material	Length (Feet)	Location					
18	RCP	103	West of RR with Flap Gate					
12	RCP?	175	Could not locate/unknown/does not exist					
42	RCP	95	Culvert through West Bank Levee opposite of Croose Avenue, 1000 ft					
			upstream of Cherry Rd.					
66	RCP	93	Culvert through East Bank Levee near control weir					
42	RCP	360	At inlet to siphon control weir					
			James Avenue Pump Station Gravity Outlet					
			Discharge from James Avenue Pump Station					
		100	Discharge from James Avenue Pump Station					
30	CIP	100	Discharge from James Avenue Pump Station					
			Federal Avenue Pump Station Outlet					
			Federal Avenue Pump Station Outlet					
			Discharge from Federal Avenue Pump Station					
		141	Discharge from Federal Avenue Pump Station					
30	CIP	141	Discharge from Federal Avenue Pump Station					
		120	Sippo Creek Pump Station					
			Discharge from Sippo Creek Pump Station					
			Discharge from Sippo Creek Pump Station					
24	CIP	20	Discharge from Sippo Creek Pump Station					
			Gravity Arch Avenue Pump Station					
			Gravity Arch Avenue Pump Station					
			Discharge from Arch Avenue Pump Station					
			Discharge from Arch Avenue Pump Station					
			Discharge from Arch Avenue Pump Station					
			Gravity Conduit through levee					
48	СМР	317	Gravity Conduit MH upstream of Levee					
2.4	DID	450	Caritana Cinhan Candait Breakfald I					
			Sanitary Siphon-Conduit-Brookfield Interceptor					
			Sanitary Siphon-Conduit-Brookfield Interceptor					
20	אוטן	460	Sanitary Siphon-Conduit-Brookfield Interceptor					
18	DIP	460	Sanitary Siphon-Conduit-Wooster Trunk					
			Sanitary Siphon-Conduit-Wooster Trunk					
			Sanitary Siphon-Conduit-Wooster Trunk					
13	DIF	+00	paintary Siphon-Conduit-Wooster Hullk					
Q	VCD	450	Sanitary Siphon-Conduit-Tuscarawas River					
			Sanitary Siphon-Conduit-Tuscarawas River Sanitary Siphon-Conduit-Tuscarawas River					
	18 12 42 66	18 RCP 12 RCP? 42 RCP? 42 RCP 66 RCP 42 RCP 48 RCP 30 CIP 30 CIP 30 CIP 60 RCP 60 RCP 30 CIP 30 CIP 30 CIP 30 CIP 48 RCP 48 RCP 49 RCP 40 RCP 41 RCP 41 RCP 42 RCP 42 RCP 43 RCP 44 RCP 45 RCP 46 RCP 47 RCP 48 RCP	18 RCP 103 12 RCP? 175 42 RCP 95 66 RCP 93 42 RCP 360 48 RCP 97 30 CIP 100 30 CIP 100 30 CIP 100 60 RCP 135 30 CIP 141 15'X10' RCP 120 24 CIP 5 24 CIP 20 6'X6' RCB 87 24 CIP 85 24 CIP 85 48 RCP 90					

Army Corp of Engineers Rating Guidelines for Levee Inspection

Levee Embankments

For use during Initial and Continuing Eligibility Inspections of levee systems

_		
	There are no breaks, holes, cracks in the discharge pipes/ culverts that would result in significant water leakage. The pipe shape is still essentially circular. All joints appear to be closed and the soil tight. Corrugated metal pipes, if present, are in good condition with 100% of the original coating still in place (either asphalt or galvanizing) or have been relined with appropriate material, which is still in good condition. Condition of pipes has been verified using television camera video taping or visual inspection methods within the past five years, and the report for every pipe is available for review by the inspector.	
	There are a small number of corrosion pinholes or cracks that could leak water and need to be repaired, but the entire length of pipe is still structurally sound and is not in danger of collapsing. Pipe shape may be ovalized in some locations but does not appear to be approaching a curvature reversal. A limited number of joints may have opened and soil loss may be beginning. Any open joints should be repaired prior to the next inspection. Corrugated metal pipes, if present, may be showing corrosion and pinholes but there are no areas with total section loss. Condition of pipes has been verified using television camera video taping or visual inspection methods within the past five years, and the report for every pipe is available for review by the inspector.	
	Culvert has deterioration and/or has significant leakage; it is in danger of collapsing or as already begun to collapse. Corrugated metal pipes have suffered 100% section loss in the invert. HOWEVER: Even if pipes appear to be in good condition, as judged by an external visual inspection, an Unacceptable Rating will be assigned if the condition of pipes has not been verified using television camera video taping or visual inspection methods within the past five years, and reports for all pipes are not available for review by the inspector. N/A There are no discharge pipes/culverts	
		soil tight. Corrugated metal pipes, if present, are in good condition with 100% of the original coating still in place (either asphalt or galvanizing) or have been relined with appropriate material, which is still in good condition. Condition of pipes has been verified using television camera video taping or visual inspection methods within the past five years, and the report for every pipe is available for review by the inspector. There are a small number of corrosion pinholes or cracks that could leak water and need to be repaired, but the entire length of pipe is still structurally sound and is not in danger of collapsing. Pipe shape may be ovalized in some locations but does not appear to be approaching a curvature reversal. A limited number of joints may have opened and soil loss may be beginning. Any open joints should be repaired prior to the next inspection. Corrugated metal pipes, if present, may be showing corrosion and pinholes but there are no areas with total section loss. Condition of pipes has been verified using television camera video taping or visual inspection methods within the past five years, and the report for every pipe is available for review by the inspector. Culvert has deterioration and/or has significant leakage; it is in danger of collapsing or as already begun to collapse. Corrugated metal pipes have suffered 100% section loss in the invert. HOWEVER: Even if pipes appear to be in good condition, as judged by an external visual inspection, an Unacceptable Rating will be assigned if the condition of pipes has not been verified using television camera video taping or visual inspection methods within the past five years, and

Key: A = Acceptable. M = Minimally Acceptable; Maintenance is required. U = Unacceptable. N/A = Not Applicable. FDR = Flood Damage Reduction



¹ The decision on whether or not USACE inspectors should enter a pipe to perform a detailed inspection must be made at the USACE District level. This decision should be made in conjunction with the District Safety Office, as pipes may be considered confined spaces. This decision should consider the age of the pipe, the diameter of the pipe, the apparent condition of the pipe, and the length of the pipe. If a pipe is entered for the purposes of inspection, the inspector should record observations with a video camera in order that the condition of the entire pipe, including all joints, can later be assessed. Additionally, the video record provides a baseline to which future inspections can be compared.

Interior Drainage System

For use during Initial and Continuing Eligibility Inspections of interior drainage systems

Rated Item	Rating		Rating Guidelines	Location/ Remarks/ Recommendations
8. Monolith Joints		A	The joint material is in good condition. The exterior joint sealant is intact and cracking/ desiccation is minimal. Joint filler material and/or waterstop is not visible at any point.	
		М	The joint material has appreciable deterioration to the point where joint filler material and/or waterstop is visible in some locations. This needs to be repaired or replaced to prevent spalling and cracking during freeze/ thaw cycles, and to ensure water tightness of the joint.	
		U	The joint material is severely deteriorated or the concrete adjacent to the monolith joints has spalled and cracked, damaging the waterstop; in either case damage has occurred to the point where it is apparent that the joint is no longer watertight and will not provide the intended level of protection during a flood.	
		N/A	There are no monolith joints in the interior drainage system.	
9. Culverts/Disch arge Pipes ¹		A	There are no breaks, holes, cracks in the discharge pipes/ culverts that would result in significant water leakage. The pipe shape is still essentially circular. All joints appear to be closed and the soil tight. Corrugated metal pipes, if present, are in good condition with 100% of the original coating still in place (either asphalt or galvanizing) or have been relined with appropriate material, which is still in good condition. Condition of pipes has been verified using television camera video taping or visual inspection methods within the past five years, and the report for every pipe is available for review by the inspector.	
		М	There are a small number of corrosion pinholes or cracks that could leak water and need to be repaired, but the entire length of pipe is still structurally sound and is not in danger of collapsing. Pipe shape may be ovalized in some locations but does not appear to be approaching a curvature reversal. A limited number of joints may have opened and soil loss may be beginning. Any open joints should be repaired prior to the next inspection. Corrugated metal pipes, if present, may be showing corrosion and pinholes but there are no areas with total section loss. Condition of pipes has been verified using television camera video taping or visual inspection methods within the past five years, and the report for every pipe is available for review by the inspector.	
		U	Culvert has deterioration and/or has significant leakage; it is in danger of collapsing or as already begun to collapse. Corrugated metal pipes have suffered 100% section loss in the invert. HOWEVER: Even if pipes appear to be in good condition, as judged by an external visual inspection, an Unacceptable Rating will be assigned if the condition of pipes has not been verified using television camera video taping or visual inspection methods within the past five years, and reports for all pipes are not available for review by the inspector.	
			There are no discharge pipes/ culverts.	

Key: A = Acceptable. M = Minimally Acceptable; Maintenance is required. U = Unacceptable. N/A = Not Applicable. FDR = Flood Damage Reduction

Interior Drainage System



¹ The decision on whether or not USACE inspectors should enter a pipe to perform a detailed inspection must be made at the USACE District level. This decision should be made in conjunction with the District Safety Office, as pipes may be considered confined spaces. This decision should consider the age of the pipe, the diameter of the pipe, the apparent condition of the pipe, and the length of the pipe. If a pipe is entered for the purposes of inspection, the inspector should record observations with a video camera in order that the condition of the entire pipe, including all joints, can later be assessed. Additionally, the video record provides a baseline to which future inspections can be compared.

Pump Stations

For use during Initial and Continuing Eligibility Inspections of pump stations

Rated Item	Rating		Rating Guidelines	Location/ Remarks/ Recommendations
17. Intake and Discharge		A	Intake and discharge pipelines have no corrosion and paint is intact, except for minor touch up required. Pipe couplings and anchors have no leakage or corrosion.	
Pipelines		М	Intake and discharge pipelines have minor corrosion and repair and painting is required. Pipe coupling with anchors have minor leakage, corrosion and require bolts to be tightened.	
		U	Intake and discharge pipelines have major corrosion and replacement is required. Pipe coupling with anchors have major leakage and is heavily corroded and requires replacement.	
18. Sluice/ Slide Gates ¹		A	Gates open and close freely to a tight seal or minor leakage. Gate operators are in good working condition and are properly maintained. Sill is free of sediment and other obstructions. Gates and lifters have been maintained and are free of corrosion. Documentation provided during the inspection.	
		М	Gates and/or operators have been damaged or have minor corrosion, and open and close with resistance or binding. Leakage quantity is controllable, but maintenance is required. Sill is free of sediment and other obstructions.	
		U	Gates do not open or close and/or operators do not function. Gate, stem, lifter and/or guides may be damaged or have major corrosion.	
		N/A	There are no sluice/ slide gates.	
19. Flap Gates/ Flap Valves/		A	Gates/ valves open and close easily with minimal leakage, have no corrosion damage, and have been exercised and lubricated as required.	
Pinch Valves ²		М	Gates/ valves will not fully open or close because of obstructions that can be easily removed, or have minor corrosion damage that requires maintenance.	
		U	Gates/valves are missing, have been damaged, or have deteriorated to the point that they need to be replaced.	
		N/A	There are no gates on discharge lines from pump station.	
20. Cranes ²		A	Cranes operational and have been inspected and load tested in accordance with applicable standards within the last year. Documentation is on hand.	
		М	Cranes have not been inspected or operationally tested within the past year, or there are visible signs of corrosion, oil leakage, etc, requiring maintenance.	
		U	Cranes are not operational, and this may prevent the pump station from functioning as required. No documentation available on cranes.	
		N/A	There are no cranes.	
21. Other Metallic Items		A	All metal parts are protected from corrosion damage and show no rust, damage, or deterioration that would cause a safety concern.	
(Equipment,		M	Corrosion seen on metallic parts appears to be maintainable.	
Ladders, Platform		U	Metallic parts are severely corroded and require replacement to prevent failure, equipment damage, or safety issues.	
Anchors, etc)		N/A	There are no other significant metallic items.	

Key: A = Acceptable. M = Minimally Acceptable; Maintenance is required. U = Unacceptable. N/A = Not Applicable. FDR = Flood Damage Reduction

² Proper operation of this item must be demonstrated during the inspection.



¹ Proper operation of the gates (full open and closed) must be demonstrated during the inspection if no documentation is available. Be aware of both manual and electrical operators.

PACP Coding

Grading of Defects

- All PACP defects assigned a grade from 1 to 5
 - 5 Immediate Attention Defect requires immediate attention
 - 4 Poor Severe defects that will become Grade 5 defects within the near future
 - 3 Fair Moderate defects that will continue to deteriorate
 - 2 Good Defects that have not begun to deteriorate
 - 1 Excellent Minor defects.

<u>Defect Grades – Express Likelihood of Failure</u>

- 5 Pipe has failed or will likely fail within the next 5 years
- 4 Pipe will probably fail in 5 to 10 years
- 3 Pipe may fail in 10 to 20 years
- 2 Pipe unlikely to fail for at least 20 years
- 1 Failure unlikely in the foreseeable future

Pipe Inspection Summary

Pipes Inspected, Massillon Levee

	Size				Corp	PACP		Т		
Pipes	(Inches)	Material	Length (Feet)	Location	Rating	Rating	Summary	Discussion/Recommedations		
23	18	RCP	103	West of RR with Flap Gate	U	5	Outlet manhole severely deteriorated, partially collapsed during testing, significant amount of root intrusion, several joints offset throughout the structure.	Manhole severely deteriorated and needs to be replaced. Roots need to be removed and pipe needs to be sealed/grouted or lined.		
24	12	RCP?	175	Could not locate/unknown/does not exist						
25	42	RCP	95	Culvert through West Bank Levee opposite of Croose Avenue, 1000 ft upstream of Cherry Rd.		5	Inlet was completely buried and plugged. Significant joint leakage was occurring at the third joint from the inlet. Water continued to discharge from the joint for several weeks after cleaning.	Consideration should be given to adding a box and drop grate near at the inlet, or grated inlet. Joint should be sealed. Water source infiltrating into the structure should be located.		
26	66	RCP	93	Culvert through East Bank Levee near control weir	М	5	Several joints offset throughout the structure, several joints broken, moisture present at several joints, pipe possibly starting show distress from water moving outside the structure.	Pipe joint should be sealed, damaged joint should be repaired. Structure may need to b lined.		
27	42	DIP to RCP	360	At inlet to siphon control weir	U	5	DIP moderately corroded, several stained and leaking joints in RCP pipe. Heavy flow from joint at 173 feet. Radial and diagonal cracking noted in several areas along upstream side of the structure.	Manual entry was limited due to low oxygen levels in the pipe at the time of the inspection, unsure on voids at joints, Inlet grate severely corroded, no coating on the DIP, several stained in RCP. Inlet grate should be repaired, DIP should be recoated, and the joints in the RCP should be patched and sealed. Soundings should be conducted in areas of high infiltration.		
28	48	RCP	97	James Avenue Pump Station Gravity Outlet	M	4	Sagging visible from inlet to gatewell, joint more open on bottom, several joint weeping water.	Pipe joints should be sealed.		
29	30	CIP	100	Discharge from James Avenue Pump Station	M	4	All three pipes have moderate to severe corrosion at the joints. Missing protective	Recommend air pressure testing to verify the integrity of the joints, areas of missing		
30	30	CIP	100	Discharge from James Avenue Pump Station	M	4	coating was missing not only at the joints but in flat areas and sharp bends. It appears that point repairs of the protective coating	protective coating should be repaired prior t additional degradation.		
31	30	CIP	100	Discharge from James Avenue Pump Station	M	4	have been made in sections.			


Pipes	Size (Inches)	Material	Length (Feet)	Location	Corp Rating	PACP Rating	Summary	Discussion/Recommedations
32	60	RCP	135	Federal Avenue Pump Station Outlet	A-M	3 to 4	0-42 feet CMP, CMP bituminous coating missing in haunches, moderate corrosion, RCP 42 to gatewell appears to be in good condition, moisture present at some of the joints.	The CMP is starting to show signs of moderate to significant corrosion in areas, most of the paved invert is missing.
33	60	RCP	135	Federal Avenue Pump Station Outlet	A-M	3 to 4	0-42 feet CMP, CMP bituminous coating missing in haunches, moderate corrosion, RCP 42 to gatewell appears to be in good condition, moisture present at some of the joints.	
34	30	CIP	141	Discharge from Federal Avenue Pump Station	М	4	All three pipes have moderate to severe corrosion at the joints,	be repaired prior to additional
35	30	CIP	141	Discharge from Federal Avenue Pump Station	М	4	missing protective coating also noted in flat areas and bends. It appears in	
36	30	CIP	141	Discharge from Federal Avenue Pump Station	М	4	some sections point repairs have been made on the protective coating.	degradation.
37	15'X10'	RCB	120	Sippo Creek Pump Station	M	3 to 4	Most of the joints appear to have some weeping and/or signs of staining at the joints. Invert is rough in areas indicating moderate scouring. Rebar exposed and some spalling noticed in areas.	Recommend that the joints be repaired and sealed.
38	24	CIP	5	Discharge from Sippo Creek Pump Station	M	4	All three pipes have moderate to severe corrosion at the joints,	Recommend air pressure testing to verify the integrity of the joints, areas
39	24	CIP	10	Discharge from Sippo Creek Pump Station	М	4	missing protective coating also noted in the inverts and haunches of the	of missing protective coating should be repaired prior to additional
40	24	CIP	20	Discharge from Sippo Creek Pump Station	M	4	pipes. Pipe #39 has a severe offset joint with potential leakage.	degradation.

lines	Size	Matarial	Longth (Foot)	Location	Carn Dating	PACP	Summary.	Discussion/Decommodations	
ipes	(Inches)	Material	Length (Feet)	Location	Corp Rating	Rating	Summary	Discussion/Recommedations	
11	6'X6'	RCB	87	Gravity Arch Avenue Pump Station	М	3 to 4	Offset joint in crown of box at 23 ft, spalling in crown near gatewell, last section of pipe at (80 ft) outlet is offset and leaking, signs of potential soil movement.	All joints should be cleaned, resealed, and repaired if need. Offset joints should be evaluated for potential voids and pressure grouted if necessary.	
12	6'X6'	RCB	87	Gravity Arch Avenue Pump Station	М	3 to 4	Water movement at entrance in crown and headwall, open joints between barrels, moisture present in some of the joints, offset joint in box at gatewell, last section of pipe at outlet is offset and leaking, signs of potential soil movement.	All joints should be cleaned, resealed, and repaired if need. Offset joints should be evaluated for potential voids and pressure grouted if necessary.	
13	24	CIP	85	Discharge from Arch Avenue Pump Station	М	4	All three pipes have moderate to severe corrosion at the joints, missing protective	Recommend air pressure testing to verify the integrity of the joints, areas of missing	
14	24	CIP	85	Discharge from Arch Avenue Pump Station	М	4	coating also noted in the flat areas and flat bends.	protective coating should be repaired prior to additional degradation.	
15	24	CIP	85	Discharge from Arch Avenue Pump Station	М	4		-	
16	48	RCP	90	Gravity Conduit through levee	A-M	3	Pipe is showing some signs of settlement could be due to movement of water under neath the structure caused by the up gradient CMP structure.	The CMP upstream line should be replaced or lined. Concern is that settlement is noticeable in the down stream line under the levee. Unsure if water moving outside the CMP may	
16b	48	СМР	317	Gravity Conduit MH upstream of Levee	U	5	CMP structure is severely corroded, invert missing, pipe starting to deflect. Unsure how much water is moving outside/under the structure.	be flowing around the manhole and under the downstream structure potential causing the observed settlement.	
17	24	DIP	460	Siphon-Conduit-Brookfield Interceptor	A-M	3	Minor corrosion at the joints, protective coating coming off in sheets in several areas.	off in sheets. System design did not allow for	
18	14	DIP	460	Siphon-Conduit-Brookfield Interceptor	A-M	3	No gate valves/cut off valves were installed		
19	20	DIP	460	Siphon-Conduit-Brookfield Interceptor	A-M	3	on the system.	Sonar or entire pipe to be camera inspected. is anticipated that additional heavy cleaning would degrade the life of the pipe through removal of the protective coating.	
50	18	DIP	460	Siphon-Conduit-Wooster Trunk	M-U	4	Gate valves for Pipe No. 51 and 52 were frozen mid position, Gate valve for No. 50	Due to the limited inspection and the poor condition of the pipe that was inspected, and	
51	10	DIP	460	Siphon-Conduit-Wooster Trunk	M-U	4	difficult to turn. Pipe 51 and 52 could not be	the difficulties of maintaining and inspecting	
52	15	DIP	460	Siphon-Conduit-Wooster Trunk	M-U	4	inspected. Pipe not 50 was severely corroded above the waterline.	the siphons consideration of replacing the siphon with a pump station should be weighed vs repairing several of the siphons.	
53	o	VCP	450	Siphon-Conduit-Tuscarawas River	M-U	5	Cata valvas wara brakas as bath sinas	Due to the limited inspection and the near	
55	o	VCP	450	pipilon-conduit-ruscarawas kiver	ivi-U	ס	Gate valves were broken on both pipes, diversion board on inlet was rotted through. Metal pipe at gate valves severely corroded.	Due to the limited inspection and the poor condition of the pipe that was inspected, and the difficulties of maintaining and inspecting	
54	10	VCP	450	Siphon-Conduit-Tuscarawas River	M-U	4	Significant offset/and or debris build up at outlet of Pipe 53, several offset joints in Pipe No. 54.	the siphons consideration of replacing the siphons with a pump station should be weighed vs repairing several of the siphons.	

Pipe No. 23 18-Inch Storm Drain



			Pipes Inspected, Ma	assillon Levee
Pipes	Size (Inches)	Material	Length (Feet)	Location
23	18	RCP	103	West of RR with Flap Gate
24	12	RCP?	175	Could not locate/unknown/does not exist
25	42	RCP	95	Culvert through West Bank Levee opposite of Croose Avenue
26	66	RCP	93	Culvert through East Bank Levee near control weir
27	42	RCP	360	At inlet to siphon control weir
20	40	0.00	0.7	
28	48	RCP	97	James Avenue Pump Station Gravity Outlet
29	30	CIP	100	Discharge from James Avenue Pump Station
30	30	CIP	100	Discharge from James Avenue Pump Station
31	30	CIP	100	Discharge from James Avenue Pump Station
32	60	RCP	135	Federal Avenue Pump Station Outlet
33	60	RCP	135	Federal Avenue Pump Station Outlet
34	30	CIP	141	Discharge from Federal Avenue Pump Station
35	30	CIP	141	Discharge from Federal Avenue Pump Station
36	30	CIP	141	Discharge from Federal Avenue Pump Station
			111	pisonal ge from Federal Altrende Family Station
37	15'X10'	RCP	120	Sippo Avenue Pump Station
38	24	CIP	5	Discharge from Sippo Avenue Pump Station
39	24	CIP	10	Discharge from Sippo Avenue Pump Station
40	24	CIP	20	Discharge from Sippo Avenue Pump Station
41	6'X6'	RCB	87	Gravity Arch Avenue Pump Station
42	6'X6'	RCB	87	Gravity Arch Avenue Pump Station
43	24	CIP	85	Discharge from Arch Avenue Pump Station
44	24	CIP	85	Discharge from Arch Avenue Pump Station
45	24	CIP	85	Discharge from Arch Avenue Pump Station
46	48	RCP	90	Gravity Conduit through levee
46b	48	СМР	317	Gravity Conduit MH upstream of Levee
4.7	2.4	010	460	
47	24	DIP	460	Siphon-Conduit-Brookfield Interceptor
48	14	DIP	460	Siphon-Conduit-Brookfield Interceptor
49	20	DIP	460	Siphon-Conduit-Brookfield Interceptor
50	18	DIP	460	Siphon-Conduit-Wooster Trunk
51	10	DIP	460	Siphon-Conduit-Wooster Trunk
52	15	DIP	460	Siphon-Conduit-Wooster Trunk
	15		100	Signal Conduit Wooder Halls
53	8	VCP	450	Siphon-Conduit-Tuscarawas River
54	10	VCP	450	Siphon-Conduit-Tuscarawas River







HUNTINGTON DISTRICT

U.S. ARMY CORPS OF ENGINEERS

CONTRACT NO. W91237-09-P-0133

CCTV AND LASER PROFILE INSPECTION SUMMARY PIPES UNDER LEVEES

PIPE NO: 23 PIPE SIZE: 18" LENGTH INSPECTED: Approximately 103ft

PROJECT: Massillon Levee TYPE: RCP or Clay INSPECTION DATE: 9/16/09

OVERALL CONDITION: NASSCO Grade 5: Manhole is currently failing/failed

GENERAL INSPECTION FINDING: Manhole severely deteriorated. Manhole partially collapsed during testing. Significant amount of root intrusion towards the inlet end of the structure. Several joint throughout the structure offset.

MAJOR DEFECTS

Pipe #23 West of Rail Road						
Feet	Defect					
2.2ft	Offset joint at invert					
3.8ft	Roots coming through joints at invert					
4.7ft	Roots coming through joint at approx. 9 o'clock					
11.2ft	Roots completely covering joint at right haunch, approx. 2" joint separation at invert					
19.8ft	1.5" joint separation at left haunch					
76.5ft	2" joint separation at approx. 3 o'clock					
80.8ft	Sediment covering invert					
88.3ft	1.5" joint separation at approx. 3 o'clock					
94.3ft	Approx. 2" joint separation right haunch					
103 ft	Manhole, significant deterioration					
<u> </u>						



Levee Embankments

For use during Initial and Continuing Eligibility Inspections of levee systems

Rated Item	Rating		Rating Guidelines	Location/ Remarks/ Recommendations
11. Culverts/ Discharge Pipes ¹ (This item includes both concrete and		A	There are no breaks, holes, cracks in the discharge pipes/ culverts that would result in significant water leakage. The pipe shape is still essentially circular. All joints appear to be closed and the soil tight. Corrugated metal pipes, if present, are in good condition with 100% of the original coating still in place (either asphalt or galvanizing) or have been relined with appropriate material, which is still in good condition. Condition of pipes has been verified using television camera video taping or visual inspection methods within the past five years, and the report for every pipe is available for review by the inspector.	
corrugated metal pipes.)		М	There are a small number of corrosion pinholes or cracks that could leak water and need to be repaired, but the entire length of pipe is still structurally sound and is not in danger of collapsing. Pipe shape may be ovalized in some locations but does not appear to be approaching a curvature reversal. A limited number of joints may have opened and soil loss may be beginning. Any open joints should be repaired prior to the next inspection. Corrugated metal pipes, if present, may be showing corrosion and pinholes but there are no areas with total section loss. Condition of pipes has been verified using television camera video taping or visual inspection methods within the past five years, and the report for every pipe is available for review by the inspector.	
		U	Culvert has deterioration and/or has significant leakage; it is in danger of collapsing or as already begun to collapse. Corrugated metal pipes have suffered 100% section loss in the invert. HOWEVER: Even if pipes appear to be in good condition, as judged by an external visual inspection, an Unacceptable Rating will be assigned if the condition of pipes has not been verified using television camera video taping or visual inspection methods within the past five years, and reports for all pipes are not available for review by the inspector.	
			There are no discharge pipes/ culverts.	


Key: A = Acceptable. M = Minimally Acceptable; Maintenance is required. U = Unacceptable. N/A = Not Applicable. FDR = Flood Damage Reduction




¹ The decision on whether or not USACE inspectors should enter a pipe to perform a detailed inspection must be made at the USACE District level. This decision should be made in conjunction with the District Safety Office, as pipes may be considered confined spaces. This decision should consider the age of the pipe, the diameter of the pipe, the apparent condition of the pipe, and the length of the pipe. If a pipe is entered for the purposes of inspection, the inspector should record observations with a video camera in order that the condition of the entire pipe, including all joints, can later be assessed. Additionally, the video record provides a baseline to which future inspections can be compared.


NASSCO PACP Condition Grading System Code Matrix


Family	Group	Descriptor	Modifier	Code	Structural Grade	O&M Grade
		Other (Z)		DNZ		<=10% - 2, <=20% - 3, <=30% - 4, >30% - 5
0014	Deets / D\	Fine (F)	Barrel (B)	RFB		2
O&M	Roots (R)	rille (r)	Lateral (L)	RFL		1
			Connection (C)	RFC		1
	Roots (R) at a Joint		N/A	RF		1
	Hools (h) at a Joint	Tap (T)	Barrel (B)	RTB		3
		ταρ (τ)	Lateral (L)	RTL		2
			Connection (C)	RTC		2
	Reets (R) at a Joint		NI/A	RT		2
	Hoots (11) at a source	Medium (M)	Barrel (B)	RMB		4
		The state of the s	Lateral (L)	RIVIL		3
			Connection (C)	RMC		3
	Roots (R) at a Joint		N/A	RM		3
		Ball (B)	Barrel (B)	RBB		5
		N 2	Lateral (L)	RBL		4
			Connection (C)	RBC		4
	Roots (R) at a Joint		N/A	RB		4
O&M	Infiltration (I)	Weeper (W)		IW		2
	No.	Dripper (D)		ID		3
		Runner (R)		IR		4
		Gusher (G)		IG		5
O&M	Obstacles/Obstructions (OB)	Brick or Masonry (B)		OBB		<=10% - 2, <=20% - 3, <=30% - 4, >30% - 5
		Pipe Material in Invert (M)		ОВМ		<=10% - 2, <=20% - 3, <=30% - 4, >30% - 5
		Object Protruding Thru Wall (I)		ОВІ		<=10% - 2, <=20% - 3, <=30% - 4, >30% - 5
		Object Wedged in Joint (J)		ОВЈ		<=10% - 2, <=20% - 3, <=30% - 4, >30% - 5
		Object Thru Connection (C)		ОВС		<=10% - 2, <=20% - 3, <=30% - 4, >30% - 5




































































Pipe No. 25 42-Inch RCP Storm Drain



Pipes Inspected, Massillon Levee						
Pipes	Size (Inches)	Material	Length (Feet)	Location		
23	18	RCP	103	West of RR with Flap Gate		
24	12	RCP?	175	Could not locate/unknown/does not exist		
25	42	RCP	95	Culvert through West Bank Levee opposite of Croose Avenue		
26	66	RCP	93	Culvert through East Bank Levee near control weir		
27	42	RCP	360	At inlet to siphon control weir		
28	48	RCP	97	James Avenue Pump Station Gravity Outlet		
29	30	CIP	100	Discharge from James Avenue Pump Station		
30	30	CIP	100	Discharge from James Avenue Pump Station		
31	30	CIP	100	Discharge from James Avenue Pump Station		
32	60	RCP	135	Federal Avenue Pump Station Outlet		
33	60	RCP	135	Federal Avenue Pump Station Outlet		
34	30	CIP	141	Discharge from Federal Avenue Pump Station		
35	30	CIP	141	Discharge from Federal Avenue Pump Station		
36	30	CIP	141	Discharge from Federal Avenue Pump Station		
37	15'X10'	RCB	120	Sippo Creek Pump Station		
38	24	CIP	5	Discharge from Sippo Creek Pump Station		
39	24	CIP	10	Discharge from Sippo Creek Pump Station		
40	24	CIP	20	Discharge from Sippo Creek Pump Station		
41	6'X6'	RCB	87	Gravity Arch Avenue Pump Station		
42	6'X6'	RCB	87	Gravity Arch Avenue Pump Station		
43	24	CIP	85	Discharge from Arch Avenue Pump Station		
44	24	CIP	85	Discharge from Arch Avenue Pump Station		
45	24	CIP	85	Discharge from Arch Avenue Pump Station		
46	48	RCP	90	Gravity Conduit through levee		
46b	48	CMP	317	Gravity Conduit MH upstream of Levee		
47	24	DIP	460	Siphon-Conduit-Brookfield Interceptor		
48	14	DIP	460	Siphon-Conduit-Brookfield Interceptor		
49	20	DIP	460	Siphon-Conduit-Brookfield Interceptor		
50	18	DIP	460	Siphon-Conduit-Wooster Trunk		
51	10	DIP	460	Siphon-Conduit-Wooster Trunk		
52	15	DIP	460	Siphon-Conduit-Wooster Trunk		
53	8	VCP	450	Siphon-Conduit-Tuscarawas River		
54	10	VCP	450	Siphon-Conduit-Tuscarawas River		



HUNTINGTON DISTRICT U.S. ARMY CORPS OF ENGINEERS CONTRACT NO. W91237-09-P-0133

CCTV AND LASER PROFILE INSPECTION SUMMARY PIPES UNDER LEVEES

PIPE NO: 25 PIPE SIZE: 42" LENGTH INSPECTED: Approximately 95ft

PROJECT: Massillon Levee TYPE: RCP INSPECTION DATE: 10/30/09

OVERALL CONDITION: NASSCO Grade 5 - Defect requires immediate attention

GENERAL INSPECTION FINDING: Inlet was completely buried and plugged. Significant joint leakage was occurring at the third joint from the inlet. Water continued to discharge from the joint for several weeks, Unsure of the water source. Joint material rolled from joint in several areas. Invert to springline appears to be grouted. Outlet end from gatewell to headwall could not be inspected.

MAJOR DEFECTS

Pipe #25				
Feet	Defect			
3.7ft	Offset joint, gasket rolled			
10.8ft	Significant leakage at joint, running for several			
	weeks			
15.1ft	Staining at joint			
19 1ft	Diagonal crack in hell			
22.4ft	Staining at joint			
31ft	Staining at joint			
46.9 ft	Gasket rolled			
78.9ft	Crack through bell			



NASSCO PACP Condition Grading System Code Matrix

Family	Group	Descriptor	Modifier	Code	Structural Grade	O&M Grade
		Other (Z)		DNZ		<=10% - 2, <=20% - 3 <=30% - 4, >30% - 5
M&C	Roots (R)	Fine (F)	Barrel (B)	RFB		2
Odivi	11000 (11)		Lateral (L)	RFL		1
			Connection (C)	RFC		1
	Roots (R) at a Joint		N/A	RF		1
	riodio (Ti) di di dionini	Tap (T)	Barrel (B)	RTB		3
			Lateral (L)	RTL		2
			Connection (C)	RTC		2
	Roots (R) at a Joint		N/A	RT		2
	Trooto (Tr) at a some	Medium (M)	Barrel (B)	RMB		4
		The state of the s	Lateral (L)	RML		3
			Connection (C)	RMC		3
	Roots (R) at a Joint		N/A	RM		3
	riodo (ri) ara osini	Ball (B)	Barrel (B)	RBB		5
			Lateral (L)	RBL		4
			Connection (C)	RBC		4
	Roots (R) at a Joint		N/A	RB		4
O&M	Infiltration (I)	Weeper (W)		IW		2
	miniation (i)	Dripper (D)		ID		3
		Runner (R)		IR		4
		Gusher (G)		IG		5
O&M	Obstacles/Obstructions (OB)	Brick or Masonry (B)		OBB		<=10% - 2, <=20% - 3 <=30% - 4, >30% - 5
		Pipe Material in Invert (M)		ОВМ		<=10% - 2, <=20% - 3 <=30% - 4, >30% - 5
		Object Protruding Thru Wall (I)		OBI		<=10% - 2, <=20% - 3 <=30% - 4, >30% - 5
		Object Wedged in Joint (J)		OBJ		<=10% - 2, <=20% - 3 <=30% - 4, >30% - 5
		Object Thru Connection (C)		OBC		<=10% - 2, <=20% - 3 <=30% - 4, >30% - 5

Levee Embankments

For use during Initial and Continuing Eligibility Inspections of levee systems

Rated Item	Rating	Rating Guidelines	Location/ Remarks/ Recommendations
11. Culverts/ Discharge Pipes ¹ (This item includes both concrete and		There are no breaks, holes, cracks in the discharge pipes/ culverts that would result in significant water leakage. The pipe shape is still essentially circular. All joints appear to be closed and the soil tight. Corrugated metal pipes, if present, are in good condition with 100% of the original coating still in place (either asphalt or galvanizing) or have been relined with appropriate material, which is still in good condition. Condition of pipes has been verified using television camera video taping or visual inspection methods within the past five years, and the report for every pipe is available for review by the inspector.	
corrugated metal pipes.)		There are a small number of corrosion pinholes or cracks that could leak water and need to be repaired, but the entire length of pipe is still structurally sound and is not in danger of collapsing. Pipe shape may be ovalized in some locations but does not appear to be approaching a curvature reversal. A limited number of joints may have opened and soil loss may be beginning. Any open joints should be repaired prior to the next inspection. Corrugated metal pipes, if present, may be showing corrosion and pinholes but there are no areas with total section loss. Condition of pipes has been verified using television camera video taping or visual inspection methods within the past five years, and the report for every pipe is available for review by the inspector.	
		Culvert has deterioration and/or has significant leakage; it is in danger of collapsing or as already begun to collapse. Corrugated metal pipes have suffered 100% section loss in the invert. HOWEVER: Even if pipes appear to be in good condition, as judged by an external visual inspection, an Unacceptable Rating will be assigned if the condition of pipes has not been verified using television camera video taping or visual inspection methods within the past five years, and reports for all pipes are not available for review by the inspector. N/A There are no discharge pipes/ culverts.	

Key: A = Acceptable. M = Minimally Acceptable; Maintenance is required. U = Unacceptable. N/A = Not Applicable. FDR = Flood Damage Reduction



¹ The decision on whether or not USACE inspectors should enter a pipe to perform a detailed inspection must be made at the USACE District level. This decision should be made in conjunction with the District Safety Office, as pipes may be considered confined spaces. This decision should consider the age of the pipe, the diameter of the pipe, the apparent condition of the pipe, and the length of the pipe. If a pipe is entered for the purposes of inspection, the inspector should record observations with a video camera in order that the condition of the entire pipe, including all joints, can later be assessed. Additionally, the video record provides a baseline to which future inspections can be compared.




































INSPECTION SETUP === ON: PRO NO. W91237-09-P-0133 LUERT THRU WEST SIPHON NSCREEN: 2" STORM WEST BA Pipe after 5 heavy cleaning passes
























Joint leaking 3.7 FT. 42" RCP #25 OPP. GROOSE AVE " RCP #25 OPP. GROOSE AVE



Staining at joint in crown

22.4 FT.

42" RCP #25 OPP. GROOSE AVE





Pipe grouted to springline, photo inverted 38.8 FT. OPP. GROOSE AVE 42" RCP #25







78.9 FT. 42" RCP #25 OPP. GROOSE AVE







Pipe No. 26 66-Inch RCP Storm Drain



	Pipes Inspected, Massillon Levee				
Pipes	Size (Inches)	Material	Length (Feet)	Location	
23	18	RCP	103	West of RR with Flap Gate	
24	12	RCP?	175	Could not locate/unknown/does not exist	
25	42	RCP	95	Culvert through West Bank Levee opposite of Croose Avenue	
26	66	RCP	93	Culvert through East Bank Levee near control weir	
27	42	RCP	360	At inlet to siphon control weir	
28	48	RCP	97	James Avenue Pump Station Gravity Outlet	
29	30	CIP	100	Discharge from James Avenue Pump Station	
30	30	CIP	100	Discharge from James Avenue Pump Station	
31	30	CIP	100	Discharge from James Avenue Pump Station	
32	60	RCP	135	Federal Avenue Pump Station Outlet	
33	60	RCP	135	Federal Avenue Pump Station Outlet	
34	30	CIP	141	Discharge from Federal Avenue Pump Station	
35	30	CIP	141	Discharge from Federal Avenue Pump Station	
36	30	CIP	141	Discharge from Federal Avenue Pump Station	
37	15'X10'	RCB	120	Sippo Creek Pump Station	
38	24	CIP	5	Discharge from Sippo Creek Pump Station	
39	24	CIP	10	Discharge from Sippo Creek Pump Station	
40	24	CIP	20	Discharge from Sippo Creek Pump Station	
41	6'X6'	RCB	87	Gravity Arch Avenue Pump Station	
42	6'X6'	RCB	87	Gravity Arch Avenue Pump Station	
43	24	CIP	85	Discharge from Arch Avenue Pump Station	
44	24	CIP	85	Discharge from Arch Avenue Pump Station	
45	24	CIP	85	Discharge from Arch Avenue Pump Station	
46	48	RCP	90	Gravity Conduit through levee	
46b	48	СМР	317	Gravity Conduit MH upstream of Levee	
47	24	DIP	460	Siphon-Conduit-Brookfield Interceptor	
48	14	DIP	460	Siphon-Conduit-Brookfield Interceptor	
49	20	DIP	460	Siphon-Conduit-Brookfield Interceptor	
50	18	DIP	460	Siphon-Conduit-Wooster Trunk	
51	10	DIP	460	Siphon-Conduit-Wooster Trunk	
52	15	DIP	460	Siphon-Conduit-Wooster Trunk	
53	8	VCP	450	Siphon-Conduit-Tuscarawas River	
54	10	VCP	450	Siphon-Conduit-Tuscarawas River	



HUNTINGTON DISTRICT

U.S. ARMY CORPS OF ENGINEERS

CONTRACT NO. W91237-09-P-0133

CCTV AND LASER PROFILE INSPECTION SUMMARY

PIPES UNDER LEVEES

PIPE NO: 26 PIPE SIZE: 5.5' LENGTH INSPECTED: Approximately 93ft

PROJECT: Massillon Levee TYPE: RCP INSPECTION DATE: 9/16/09

OVERALL CONDITION: NASSCO Grade 5 - Defects required immediate attention

GENERAL INSPECTION FINDING: Several joints offset throughout the structure, several joints broken, moisture present at several joints, pipes starting to show possible distress from water moving outside the structure.

MAJOR DEFECTS

Pipe # 26					
Feet	Defect				
Start-Outlet	Invert of headwall scoured/eroded and missing, 17" across. 4"				
	depth of invert missing				
ft Offset joint, cracked, spalled, scoured					
12ft	Concrete missing from invert of pipe, entrance into gatewell				
21ft	Busted, broken joint. Piece missing from joint/scouring/ 4"				
	joint separation, offset joint , backfill visible				
22ft	Spalling/joint				
35ft	Moisture/water flowing @haunch				
42ft	Deterioration of joint at invert				
46ft	Offset Joint				
52ft	1" offset joint				
57ft	Spalling at joint				
62ft	Seal exposed and being pushed from joint				
67ft	Joint seal deteriorating, moisture present at joint				
67ft	Wet joint left haunch				
73ft	1 1/2" joint separation left haunch, moisture present				
73ft	4" penetration left haunch				
78ft	Scouring of joint at approx. 11 o'clock				
83ft	Spalled/broken invert/moisture present				
88ft	Spalled/broken invert/moisture present				
93ft	Large piece of headwall missing at invert of inlet approx. 36"				
	across				



Levee Embankments

For use during Initial and Continuing Eligibility Inspections of levee systems

Rated Item	Rating	Rating Guidelines	Location/ Remarks/ Recommendations
11. Culverts/ Discharge Pipes ¹ (This item includes both concrete and		There are no breaks, holes, cracks in the discharge pipes/ culverts that would result in significant water leakage. The pipe shape is still essentially circular. All joints appear to be closed and the soil tight. Corrugated metal pipes, if present, are in good condition with 100% of the original coating still in place (either asphalt or galvanizing) or have been relined with appropriate material, which is still in good condition. Condition of pipes has been verified using television camera video taping or visual inspection methods within the past five years, and the report for every pipe is available for review by the inspector.	
corrugated metal pipes.)		There are a small number of corrosion pinholes or cracks that could leak water and need to be repaired, but the entire length of pipe is still structurally sound and is not in danger of collapsing. Pipe shape may be ovalized in some locations but does not appear to be approaching a curvature reversal. A limited number of joints may have opened and soil loss may be beginning. Any open joints should be repaired prior to the next inspection. Corrugated metal pipes, if present, may be showing corrosion and pinholes but there are no areas with total section loss. Condition of pipes has been verified using television camera video taping or visual inspection methods within the past five years, and the report for every pipe is available for review by the inspector.	
		Culvert has deterioration and/or has significant leakage; it is in danger of collapsing or as already begun to collapse. Corrugated metal pipes have suffered 100% section loss in the invert. HOWEVER: Even if pipes appear to be in good condition, as judged by an external visual inspection, an Unacceptable Rating will be assigned if the condition of pipes has not been verified using television camera video taping or visual inspection methods within the past five years, and reports for all pipes are not available for review by the inspector. N/A There are no discharge pipes/ culverts.	

Key: A = Acceptable. M = Minimally Acceptable; Maintenance is required. U = Unacceptable. N/A = Not Applicable. FDR = Flood Damage Reduction



¹ The decision on whether or not USACE inspectors should enter a pipe to perform a detailed inspection must be made at the USACE District level. This decision should be made in conjunction with the District Safety Office, as pipes may be considered confined spaces. This decision should consider the age of the pipe, the diameter of the pipe, the apparent condition of the pipe, and the length of the pipe. If a pipe is entered for the purposes of inspection, the inspector should record observations with a video camera in order that the condition of the entire pipe, including all joints, can later be assessed. Additionally, the video record provides a baseline to which future inspections can be compared.

NASSCO PACP Condition Grading System Code Matrix

Family	Group	Descriptor	Modifier	Code	Structural Grade	O&M Grade
Structural	Crack (C)	Circumferential (C)		CC	1	
		Longitudinal (L)		CL	2	
		Multiple (M)		CM	3	
		Spiral (S)		CS	2	
Structural	Fracture (F)	Circumferential (C)		FC	2	
		Longitudinal (L)		FL	3	
		Multiple (M)		FM	4	
		Spiral (S)		FS	3	
Structural	Pipe Failures (Silent)	Broken (B)		В	1 clock pos - 3, 2 clock pos - 4, >=3 clock pos - 5	
		Broken (B)	Soil Visible (SV)	BSV	5	
		Broken (B)	Void Visible (V V)	BVV	5	
		Hole (H)		Н	1 clock pos - 3, 2 clock pos - 4, >= 3 clock pos - 5	
		Hole (H)	Soil Visible (SV)	HSV	5	
		Hole (H)	Void Visible (V V)	HVV	5	
Structural	Collapse (X)	Pipe (P)	void violble (v v)	XP	5	
	Conapse (X)	Brick (B)		XB	5	
Structural	Deformed (D)	(Pipe) (P)		D	<=10% - 4,>10% - 5	
	Beleffiled (B)	Brick (B)	Horizontally (H)	DH	5	
		Brick (B)	Vertically (V)	DV	5	
Structural	Joint (J)	Offset (displaced) (O)	Med (M)	JOM	Ĩ	
	··· V-/		Large (L)	JOL	2	
		Separated (open) (S)	Med (M)	JSM	1	
		Total Constitution of the	Large (L)	JSL	2	
		Angular (A)	Med (M)	JAM	1	
			Large (L)	JAL	2	
	Surface Damage Chemical (S)	Roughness Increased (RI)	C	SRIC	1	
		Surface Spalling (SS)	С	SSSC	2	
		Aggregate Visible (AV)	С	SAVC	3	
		Aggregate Projecting (AP)	С	SAPC	3	
		Aggregate Missing (AM)	С	SAMC	4	
		Reinforcement Visible (RV)	C	SRVC	5	
		Reinforcement Corroded (RC)	C	SRCC	5	























































































































Pipe No. 27 42-Inch RCP Storm Drain/Siphon



Pipes Inspected, Massillon Levee				assillon Levee	
Pipes	Size (Inches)	Material	Length (Feet)	Location	
23	18	RCP	103	West of RR with Flap Gate	
24	12	RCP?	175	Could not locate/unknown/does not exist	
25	42	RCP	95	Culvert through West Bank Levee opposite of Croose Avenue	
26	66	RCP	93	Culvert through East Bank Levee near control weir	
27	42	RCP	360	At inlet to siphon control weir	
28	48	RCP	97	James Avenue Pump Station Gravity Outlet	
29	30	CIP	100	Discharge from James Avenue Pump Station	
30	30	CIP	100	Discharge from James Avenue Pump Station	
31	30	CIP	100	Discharge from James Avenue Pump Station	
32	60	RCP	135	Federal Avenue Pump Station Outlet	
33	60	RCP	135	Federal Avenue Pump Station Outlet	
34	30	CIP	141	Discharge from Federal Avenue Pump Station	
35	30	CIP	141	Discharge from Federal Avenue Pump Station	
36	30	CIP	141	Discharge from Federal Avenue Pump Station	
37	15'X10'	RCB	120	Sippo Creek Pump Station	
38	24	CIP	5	Discharge from Sippo Creek Pump Station	
39	24	CIP	10	Discharge from Sippo Creek Pump Station	
40	24	CIP	20	Discharge from Sippo Creek Pump Station	
41	6'X6'	RCB	87	Gravity Arch Avenue Pump Station	
42	6'X6'	RCB	87	Gravity Arch Avenue Pump Station	
43	24	CIP	85	Discharge from Arch Avenue Pump Station	
44	24	CIP	85	Discharge from Arch Avenue Pump Station	
45	24	CIP	85	Discharge from Arch Avenue Pump Station	
46	48	RCP	90	Gravity Conduit through levee	
46b	48	СМР	317	Gravity Conduit MH upstream of Levee	
47	24	DIP	460	Siphon-Conduit-Brookfield Interceptor	
48	14	DIP	460	Siphon-Conduit-Brookfield Interceptor	
49	20	DIP	460	Siphon-Conduit-Brookfield Interceptor	
50	18	DIP	460	Siphon-Conduit-Wooster Trunk	
51	10	DIP	460	Siphon-Conduit-Wooster Trunk	
52	15	DIP	460	Siphon-Conduit-Wooster Trunk	
53	8	VCP	450	Siphon-Conduit-Tuscarawas River	
54	10	VCP	450	Siphon-Conduit-Tuscarawas River	



HUNTINGTON DISTRICT

U.S. ARMY CORPS OF ENGINEERS

CONTRACT NO. W91237-09-P-0133

CCTV AND LASER PROFILE INSPECTION SUMMARY

PIPES UNDER LEVEES

PIPE NO: 27 PIPE SIZE: 42"' LENGTH INSPECTED: Approximately 376 ft


PROJECT: Massillon Levee TYPE: DIP/RCP/DIP INSPECTION DATE: 10/2/09

OVERALL CONDITION: NASSCO Grade 5 - Defects required immediate attention

GENERAL INSPECTION FINDING: DIP moderately corroded, several stained and leaking joints in RCP pipe. Heavy flow from joint at 173 feet. Radial and diagonal cracking noted in several areas along upstream side of the structure.

MAJOR DEFECTS

Pipe # 27					
Feet	Defect				
Start	DIP Pipe, moderately corroded				
2ft-123ft	DIP				
123ft	DIP to RCP				
127ft	Weeping joint				
141ft	Diagonal/Radial Cracking				
155ft	Radial Cracking				
169ft	Offset Joint				
173ft	Leaking Joint/Gushing/flowing				
175ft	Radial Cracking				
177ft	Staining at joint				
193ft	Diagonal/Radial Cracking				
200ft	Staining/moisture at joint				
251ft	Staining/moisture at joint				
262ft	Diagonal cracking at joint				
266ft	RCP to DIP				
376ft	Gatewell				



Levee Embankments

For use during Initial and Continuing Eligibility Inspections of levee systems

Rated Item	Rating	Rating Guidelines	Location/ Remarks/ Recommendations
11. Culverts/ Discharge Pipes ¹ (This item includes both concrete and		There are no breaks, holes, cracks in the discharge pipes/ culverts that would result in significant water leakage. The pipe shape is still essentially circular. All joints appear to be closed and the soil tight. Corrugated metal pipes, if present, are in good condition with 100% of the original coating still in place (either asphalt or galvanizing) or have been relined with appropriate material, which is still in good condition. Condition of pipes has been verified using television camera video taping or visual inspection methods within the past five years, and the report for every pipe is available for review by the inspector.	
corrugated metal pipes.)		There are a small number of corrosion pinholes or cracks that could leak water and need to be repaired, but the entire length of pipe is still structurally sound and is not in danger of collapsing. Pipe shape may be ovalized in some locations but does not appear to be approaching a curvature reversal. A limited number of joints may have opened and soil loss may be beginning. Any open joints should be repaired prior to the next inspection. Corrugated metal pipes, if present, may be showing corrosion and pinholes but there are no areas with total section loss. Condition of pipes has been verified using television camera video taping or visual inspection methods within the past five years, and the report for every pipe is available for review by the inspector.	
		Culvert has deterioration and/or has significant leakage; it is in danger of collapsing or as already begun to collapse. Corrugated metal pipes have suffered 100% section loss in the invert. HOWEVER: Even if pipes appear to be in good condition, as judged by an external visual inspection, an Unacceptable Rating will be assigned if the condition of pipes has not been verified using television camera video taping or visual inspection methods within the past five years, and reports for all pipes are not available for review by the inspector.	
		N/A There are no discharge pipes/ culverts.	


Key: A = Acceptable. M = Minimally Acceptable; Maintenance is required. U = Unacceptable. N/A = Not Applicable. FDR = Flood Damage Reduction




¹ The decision on whether or not USACE inspectors should enter a pipe to perform a detailed inspection must be made at the USACE District level. This decision should be made in conjunction with the District Safety Office, as pipes may be considered confined spaces. This decision should consider the age of the pipe, the diameter of the pipe, the apparent condition of the pipe, and the length of the pipe. If a pipe is entered for the purposes of inspection, the inspector should record observations with a video camera in order that the condition of the entire pipe, including all joints, can later be assessed. Additionally, the video record provides a baseline to which future inspections can be compared.


NASSCO PACP Condition Grading System Code Matrix


Family	Group	Descriptor	Modifier	Code	Structural Grade	O&M Grade
		Other (Z)		DNZ		<=10% - 2, <=20% - 3, <=30% - 4, >30% - 5
O&M	Roots (R)	Fine (F)	Barrel (B)	RFB		2
	riodic (ri)		Lateral (L)	RFL		1
			Connection (C)	RFC		1
	Roots (R) at a Joint		N/A	RF		1
	, , , , , , , , , , , , , , , , , , , ,	Tap (T)	Barrel (B)	RTB		3
			Lateral (L)	RTL		2
			Connection (C)	RTC		2
	Roots (R) at a Joint		N/A	RT		2
	() /	Medium (M)	Barrel (B)	RMB		4
			Lateral (L)	RML		3
			Connection (C)	RMC		3
	Roots (R) at a Joint		N/A	RM		3
	110010 (1.7, 511 01 01 11	Ball (B)	Barrel (B)	RBB		5
			Lateral (L)	RBL		4
			Connection (C)	RBC		4
	Roots (R) at a Joint		N/A	RB		4
O&M	Infiltration (I)	Weeper (W)		IW		2
		Dripper (D)		ID		3
		Runner (R)		IH		4
		Gusher (G)		IG		5
O&M	Obstacles/Obstructions (OB)	Brick or Masonry (B)		OBB		<=10% - 2, <=20% - 3, <=30% - 4, >30% - 5
		Pipe Material in Invert (M)		ОВМ		<=10% - 2, <=20% - 3, <=30% - 4, >30% - 5
		Object Protruding Thru Wall (I)		ОВІ		<=10% - 2, <=20% - 3, <=30% - 4, >30% - 5
		Object Wedged in Joint (J)		ОВЈ		<=10% - 2, <=20% - 3, <=30% - 4, >30% - 5
		Object Thru Connection (C)		OBC		<=10% - 2, <=20% - 3, <=30% - 4, >30% - 5



































































































Pipe No. 28 James Avenue Pump Station 48-inch RCP Gravity Outlet



Pipes Inspected, Massillon Levee					
Size (Inches)	Material	Length (Feet)	Location		
18	RCP	103	West of RR with Flap Gate		
12	RCP?	175	Could not locate/unknown/does not exist		
42	RCP	95	Culvert through West Bank Levee opposite of Croose Avenue		
66	RCP	93	Culvert through East Bank Levee near control weir		
42	RCP	360	At inlet to siphon control weir		
40	D.C.D.	0.7	James Avenue Brown Chaties Consider Outlet		
			James Avenue Pump Station Gravity Outlet		
			Discharge from James Avenue Pump Station		
			Discharge from James Avenue Pump Station		
30	CIP	100	Discharge from James Avenue Pump Station		
60	RCP	135	Federal Avenue Pump Station Outlet		
			Federal Avenue Pump Station Outlet		
			Discharge from Federal Avenue Pump Station		
			Discharge from Federal Avenue Pump Station		
			Discharge from Federal Avenue Pump Station		
	<u> </u>	<u> </u>	promise norm ediction to the particle.		
15'X10'	RCB	120	Sippo Creek Pump Station		
24	CIP	5	Discharge from Sippo Creek Pump Station		
24	CIP	10	Discharge from Sippo Creek Pump Station		
24	CIP	20	Discharge from Sippo Creek Pump Station		
6'X6'	RCB	87	Gravity Arch Avenue Pump Station		
6'X6'	RCB	87	Gravity Arch Avenue Pump Station		
24	CIP	85	Discharge from Arch Avenue Pump Station		
24	CIP	85	Discharge from Arch Avenue Pump Station		
24	CIP	85	Discharge from Arch Avenue Pump Station		
48	RCP	90	Gravity Conduit through levee		
48	СМР	317	Gravity Conduit MH upstream of Levee		
			Siphon-Conduit-Brookfield Interceptor		
			Siphon-Conduit-Brookfield Interceptor		
20	DIP	460	Siphon-Conduit-Brookfield Interceptor		
18	DIP	460	Siphon-Conduit-Wooster Trunk		
			Siphon-Conduit-Wooster Trunk		
			Siphon-Conduit-Wooster Trunk		
15		T-00	Signori Conduit Wooder Trank		
Q	VCP	450	Siphon-Conduit-Tuscarawas River		
			Siphon-Conduit-Tuscarawas River		
	12 42 66 42 48 30 30 30 30 30 30 30 30 30 30	18 RCP 12 RCP? 42 RCP 66 RCP 42 RCP 48 RCP 30 CIP 30 CIP 60 RCP 60 RCP 60 RCP 30 CIP 30 CIP 30 CIP 15'X10' RCB 24 CIP 25 CIP 48 RCP 48 RCP 48 RCP 48 RCP 48 DIP 10 DIP 15 DIP	Size (Inches) Material Length (Feet)		



HUNTINGTON DISTRICT

U.S. ARMY CORPS OF ENGINEERS

CONTRACT NO. W91237-09-P-0133

CCTV AND LASER PROFILE INSPECTION SUMMARY

PIPES UNDER LEVEES

PIPE NO: 28 PIPE SIZE: 48"' LENGTH INSPECTED: Approximately 97 ft

PROJECT: Massillon Levee TYPE: RCP INSPECTION DATE: 9/17/09

OVERALL CONDITION: NASSCO Grade 4 - Severe defects that will become Grade 5 in near future


GENERAL INSPECTION FINDING: Sagging was visible from inlet to gatewell. Joints more open on the bottom.

Several joints were weeping water.

MAJOR DEFECTS

Pipe # 28					
Feet	Defect				
7.7ft	Pipe sagging, approx. 2"+ joint separation at 4 o'clock				
23.5ft	Pipe sagging, approx. 1 1/2" joint separation right haunch				
39.4ft	Pipe sagging, 1.3" joint separation at approx. 3 o'clock				
70ft	Weeping joint at approx. 9 o'clock, near gatewell				
76.6ft	Gatewell				
81.5ft	Weeping joint at approx. 3 o'clock				
86.6ft	Weeping joint at approx. 3 o'clock				
91.2ft	Weeping joint				
96 1ft	loint tight				

*Inspected inlet to out



Levee Embankments

For use during Initial and Continuing Eligibility Inspections of levee systems

Rated Item	Rating		Rating Guidelines	Location/ Remarks/ Recommendations		
11. Culverts/ Discharge Pipes ¹ (This item includes both concrete and		A	There are no breaks, holes, cracks in the discharge pipes/ culverts that would result in significant water leakage. The pipe shape is still essentially circular. All joints appear to be closed and the soil tight. Corrugated metal pipes, if present, are in good condition with 100% of the original coating still in place (either asphalt or galvanizing) or have been relined with appropriate material, which is still in good condition. Condition of pipes has been verified using television camera video taping or visual inspection methods within the past five years, and the report for every pipe is available for review by the inspector.			
corrugated metal pipes.)			There are a small number of corrosion pinholes or cracks that could leak water and need to be repaired, but the entire length of pipe is still structurally sound and is not in danger of collapsing. Pipe shape may be ovalized in some locations but does not appear to be approaching a curvature reversal. A limited number of joints may have opened and soil loss may be beginning. Any open joints should be repaired prior to the next inspection. Corrugated metal pipes, if present, may be showing corrosion and pinholes but there are no areas with total section loss. Condition of pipes has been verified using television camera video taping or visual inspection methods within the past five years, and the report for every pipe is available for review by the inspector.			
			Culvert has deterioration and/or has significant leakage; it is in danger of collapsing or as already begun to collapse. Corrugated metal pipes have suffered 100% section loss in the invert. HOWEVER: Even if pipes appear to be in good condition, as judged by an external visual inspection, an Unacceptable Rating will be assigned if the condition of pipes has not been verified using television camera video taping or visual inspection methods within the past five years, and reports for all pipes are not available for review by the inspector.			
	N/A There are no discharge pipes/ culverts.					

Key: A = Acceptable. M = Minimally Acceptable; Maintenance is required. U = Unacceptable. N/A = Not Applicable. FDR = Flood Damage Reduction



¹ The decision on whether or not USACE inspectors should enter a pipe to perform a detailed inspection must be made at the USACE District level. This decision should be made in conjunction with the District Safety Office, as pipes may be considered confined spaces. This decision should consider the age of the pipe, the diameter of the pipe, the apparent condition of the pipe, and the length of the pipe. If a pipe is entered for the purposes of inspection, the inspector should record observations with a video camera in order that the condition of the entire pipe, including all joints, can later be assessed. Additionally, the video record provides a baseline to which future inspections can be compared.

NASSCO PACP Condition Grading System Code Matrix

Family	Group	Descriptor	Modifier	Code	Structural Grade	O&M Grade
		Other (Z)		DNZ		<=10% - 2, <=20% - 3, <=30% - 4, >30% - 5
						Y
O&M	Roots (R)	Fine (F)	Barrel (B)	RFB		2
OXIVI	Hoots (H)	Time (T)	Lateral (L)	RFL		1
			Connection (C)	RFC		1
	Roots (R) at a Joint		N/A	RF		1
	Hoots (11) at a John	Tap (T)	Barrel (B)	RTB		3
		ταρ (1)	Lateral (L)	RTL		2
			Connection (C)	RTC		2
	Roots (R) at a Joint		N/A	RT		2
	ricots (11) at a cont	Medium (M)	Barrel (B)	RMB		4
		Wicaram (W)	Lateral (L)	RML		3
			Connection (C)	RMC		3
	Roots (R) at a Joint		N/A	RM		3
	riodis (Ti) di di donit	Ball (B)	Barrel (B)	RBB		5
		(-)	Lateral (L)	RBL		4
			Connection (C)	RBC		4
	Roots (R) at a Joint		N/A	RB		4
O&M	Infiltration (I)	Weeper (W)		IW		2
	mmmanan (i)	Dripper (D)		ID		3
		Runner (R)		IR		4
		Gusher (G)		IG		5
O&M	Obstacles/Obstructions (OB)	Brick or Masonry (B)		OBB		<=10% - 2, <=20% - 3, <=30% - 4, >30% - 5
		Pipe Material in Invert (M)		ОВМ		<=10% - 2, <=20% - 3, <=30% - 4, >30% - 5
		Object Protruding Thru Wall (I)		ОВІ		<=10% - 2, <=20% - 3, <=30% - 4, >30% - 5
		Object Wedged in Joint (J)		OBJ		<=10% - 2, <=20% - 3, <=30% - 4, >30% - 5
		Object Thru Connection (C)		OBC		<=10% - 2, <=20% - 3, <=30% - 4, >30% - 5

E-9
















































Looking from pipe #26 towards James Avenue







Pipe No. 29, 30, 31 30-Inch DIP Discharge Pipes



Pipes Inspected, Massillon Levee				
Size (Inches)	Material	Length (Feet)	Location	
18	RCP	103	West of RR with Flap Gate	
12	RCP?	175	Could not locate/unknown/does not exist	
42	RCP	95	Culvert through West Bank Levee opposite of Croose Avenue	
66	RCP	93	Culvert through East Bank Levee near control weir	
42	RCP	360	At inlet to siphon control weir	
			James Avenue Pump Station Gravity Outlet	
			Discharge from James Avenue Pump Station	
			Discharge from James Avenue Pump Station	
30	CIP	100	Discharge from James Avenue Pump Station	
60	RCP	135	Federal Avenue Pump Station Outlet	
			Federal Avenue Pump Station Outlet	
			Discharge from Federal Avenue Pump Station	
			Discharge from Federal Avenue Pump Station	
			Discharge from Federal Avenue Pump Station	
30	CII	171	bischarge from Federal / Wende Famp Station	
15'X10'	RCB	120	Sippo Creek Pump Station	
24	CIP	5	Discharge from Sippo Creek Pump Station	
24	CIP	10	Discharge from Sippo Creek Pump Station	
24	CIP	20	Discharge from Sippo Creek Pump Station	
6'X6'	RCB	87	Gravity Arch Avenue Pump Station	
6'X6'	RCB	87	Gravity Arch Avenue Pump Station	
24	CIP	85	Discharge from Arch Avenue Pump Station	
24	CIP	85	Discharge from Arch Avenue Pump Station	
24	CIP	85	Discharge from Arch Avenue Pump Station	
48	RCP	90	Gravity Conduit through levee	
48	СМР	317	Gravity Conduit MH upstream of Levee	
		100		
			Siphon-Conduit-Brookfield Interceptor	
			Siphon-Conduit-Brookfield Interceptor	
20	DIP	460	Siphon-Conduit-Brookfield Interceptor	
18	DIP	460	Siphon-Conduit-Wooster Trunk	
			Siphon-Conduit-Wooster Trunk	
			Siphon-Conduit-Wooster Trunk	
15		T-00	Signori Conduit Wooder Trank	
Q	VCP	450	Siphon-Conduit-Tuscarawas River	
			Siphon-Conduit-Tuscarawas River Siphon-Conduit-Tuscarawas River	
	12 42 66 42 48 30 30 30 30 30 30 30 30 30 30	18 RCP 12 RCP? 42 RCP 66 RCP 42 RCP 48 RCP 30 CIP 30 CIP 30 CIP 60 RCP 60 RCP 60 RCP 30 CIP 30 CIP 30 CIP 30 CIP 44 CIP 24 CIP 25 CIP 26 CIP 27 CIP 28 CIP 29 CIP 29 CIP 20 DIP 10 DIP 11 DIP 11 DIP 11 DIP 11 DIP	Size (Inches) Material Length (Feet) 18	

HUNTINGTON DISTRICT

U.S. ARMY CORPS OF ENGINEERS

CONTRACT NO. W91237-09-P-0133

CCTV AND LASER PROFILE INSPECTION SUMMARY

PIPES UNDER LEVEES

PIPE NO: James Avenue, Pump Pipes (29, 30, 31) PIPE SIZE: 30" LENGTH INSPECTED: 100 ft.

PROJECT: Massillon Levee TYPE: Coated DIP INSPECTI ON DATE: 9/17/09

OVERALL CONDITION: NASSCO Grade 4: Pipe will probably fail in 5 to 10 years. Pipe rated at a more serious condition due to that it is a pump line going through a levee.

GENERAL INSPECTION FINDING: GENERAL INSPECTION FINDINGS: All three pipes have moderate to severe corrosion at the joints. Bellies have formed in the flat areas of the pipe at the beginning and the end of the runs toward the pump station. Missing protective coating and corrosion was also noted in flat areas and sharp bends. It appears in some sections that point repairs have been made on the protective coating. Recommend air pressure testing to verify integrity of the joints.

*Note: Pipe #29 has severe loss of lining from air-release valve to pump station on the downward grade

MAJOR DEFECTS

Feet	Defect	
0-100 ft	All three pipes have moderate to severe corrosion at the joints. Bellies have formed in the flat areas of the pipe at the beginning and the end of the runs toward the pump station. Missing protective coating and corrosion was also noted in flat areas and sharp bends. It appears in some sections that point repairs have been made on the protective coating. Recommend air pressure testing to verify integrity of the joints.	



Levee Embankments

For use during Initial and Continuing Eligibility Inspections of levee systems

Rated Item	Rating	Rating Guidelines	Location/ Remarks/ Recommendations
11. Culverts/ Discharge Pipes ¹ (This item includes both concrete and		There are no breaks, holes, cracks in the discharge pipes/ culverts that would result in significant water leakage. The pipe shape is still essentially circular. All joints appear to be closed and the soil tight. Corrugated metal pipes, if present, are in good condition with 100% of the original coating still in place (either asphalt or galvanizing) or have been relined with appropriate material which is still in good condition. Condition of pipes has been verified using television camera video taping or visual inspection methods within the past five years, and the report for every pipe is available for review by the inspector.	
corrugated metal pipes.)		There are a small number of corrosion pinholes or cracks that could leak water and need to be repaired, but the entire length of pipe is still structurally sound and is not in danger of collapsing. Pipe shape may be ovalized in some locations but does not appear to be approaching a curvature reversal. A limited number of joints may have opened and soil loss may be beginning. Any open joints should be repaired prior to the next inspection. Corrugated metal pipes, if present, may be showing corrosion and pinholes but there are no areas with total section loss. Condition of pipes has been verified using television camera video taping or visual inspection methods within the past five years, and the report for every pipe is available for review by the inspector.	
		Culvert has deterioration and/or has significant leakage; it is in danger of collapsing or as already begun to collapse. Corrugated metal pipes have suffered 100% section loss in the invert. HOWEVER: Even if pipes appear to be in good condition, as judged by an external visual inspection, an Unacceptable Rating will be assigned if the condition of pipes has not been verified using television camera video taping or visual inspection methods within the past five years, and reports for all pipes are not available for review by the inspector. N/A There are no discharge pipes/ culverts.	

Key: A = Acceptable. M = Minimally Acceptable; Maintenance is required. U = Unacceptable. N/A = Not Applicable. FDR = Flood Damage Reduction



¹ The decision on whether or not USACE inspectors should enter a pipe to perform a detailed inspection must be made at the USACE District level. This decision should be made in conjunction with the District Safety Office, as pipes may be considered confined spaces. This decision should consider the age of the pipe, the diameter of the pipe, the apparent condition of the pipe, and the length of the pipe. If a pipe is entered for the purposes of inspection, the inspector should record observations with a video camera in order that the condition of the entire pipe, including all joints, can later be assessed. Additionally, the video record provides a baseline to which future inspections can be compared.



Siphon Breakerss on Levee, James Avenue Pump Station

Massillon, Ohio James Avenue Pump Station Pipe #29, North Discharge Pipe



















































Massillon, Ohio James Avenue Pump Station Pipe #30, Center Discharge Pipe
















































Massillon, Ohio James Avenue Pump Station Pipe #31, South Pipe











































































	Pipes Inspected, Massillon Levee				
Pipes	Size (Inches)	Material	Length (Feet)	Location	
23	18	RCP	103	West of RR with Flap Gate	
24	12	RCP?	175	Could not locate/unknown/does not exist	
25	42	RCP	95	Culvert through West Bank Levee opposite of Croose Avenue	
26	66	RCP	93	Culvert through East Bank Levee near control weir	
27	42	RCP	360	At inlet to siphon control weir	
28	48	RCP	97	James Avenue Pump Station Gravity Outlet	
29	30	CIP	100	Discharge from James Avenue Pump Station	
30	30	CIP	100	Discharge from James Avenue Pump Station	
31	30	CIP	100	Discharge from James Avenue Pump Station	
32	60	RCP	135	Federal Avenue Pump Station Outlet	
33	60	RCP	135	Federal Avenue Pump Station Outlet	
34	30	CIP	141	Discharge from Federal Avenue Pump Station	
35	30	CIP	141	Discharge from Federal Avenue Pump Station	
36	30	CIP	141	Discharge from Federal Avenue Pump Station	
50	50	CIF	141	Discharge Hoff Federal Avenue Fullip Station	
37	15'X10'	RCB	120	Sippo Creek Pump Station	
38	24	CIP	5	Discharge from Sippo Creek Pump Station	
39	24	CIP	10	Discharge from Sippo Creek Pump Station	
40	24	CIP	20	Discharge from Sippo Creek Pump Station	
41	6'X6'	RCB	87	Gravity Arch Avenue Pump Station	
42	6'X6'	RCB	87	Gravity Arch Avenue Pump Station	
43	24	CIP	85	Discharge from Arch Avenue Pump Station	
44	24	CIP	85	Discharge from Arch Avenue Pump Station	
45	24	CIP	85	Discharge from Arch Avenue Pump Station	
46	48	RCP	90	Gravity Conduit through levee	
46b	48	СМР	317	Gravity Conduit MH upstream of Levee	
47	24	DID	460	Sinhan Canduit Draakfield Intercents	
47 49	24	DIP DIP	460 460	Siphon-Conduit-Brookfield Interceptor	
48	14			Siphon-Conduit-Brookfield Interceptor	
49	20	DIP	460	Siphon-Conduit-Brookfield Interceptor	
50	18	DIP	460	Siphon-Conduit-Wooster Trunk	
51	10	DIP	460	Siphon-Conduit-Wooster Trunk	
52	15	DIP	460	Siphon-Conduit-Wooster Trunk	
53	8	VCP	450	Siphon-Conduit-Tuscarawas River	
54	10	VCP	450	Siphon-Conduit-Tuscarawas River	















Massillon, Ohio Federal Avenue 60-Inch RCP Gravity Outlet Pipe #32 (South Pipe)



Pipes Inspected, Massillon Levee					
Size (Inches)	Material	Length (Feet)	Location		
18	RCP	103	West of RR with Flap Gate		
12	RCP?	175	Could not locate/unknown/does not exist		
42	RCP	95	Culvert through West Bank Levee opposite of Croose Avenue		
66	RCP	93	Culvert through East Bank Levee near control weir		
42	RCP	360	At inlet to siphon control weir		
			James Avenue Pump Station Gravity Outlet		
			Discharge from James Avenue Pump Station		
			Discharge from James Avenue Pump Station		
30	CIP	100	Discharge from James Avenue Pump Station		
60	RCP	135	Federal Avenue Pump Station Outlet		
			Federal Avenue Pump Station Outlet		
			Discharge from Federal Avenue Pump Station		
			Discharge from Federal Avenue Pump Station		
			Discharge from Federal Avenue Pump Station		
50	CIF	141	Discharge from Federal Avenue Fump Station		
15'X10'	RCB	120	Sippo Creek Pump Station		
24	CIP	5	Discharge from Sippo Creek Pump Station		
24	CIP	10	Discharge from Sippo Creek Pump Station		
24	CIP	20	Discharge from Sippo Creek Pump Station		
6'X6'	RCB	87	Gravity Arch Avenue Pump Station		
6'X6'	RCB	87	Gravity Arch Avenue Pump Station		
24	CIP	85	Discharge from Arch Avenue Pump Station		
24	CIP	85	Discharge from Arch Avenue Pump Station		
24	CIP	85	Discharge from Arch Avenue Pump Station		
48	RCP	90	Gravity Conduit through levee		
48	СМР	317	Gravity Conduit MH upstream of Levee		
		100			
			Siphon-Conduit-Brookfield Interceptor		
			Siphon-Conduit-Brookfield Interceptor		
20	DIP	460	Siphon-Conduit-Brookfield Interceptor		
18	DIP	460	Siphon-Conduit-Wooster Trunk		
			Siphon-Conduit-Wooster Trunk		
			Siphon-Conduit-Wooster Trunk		
10		тоо	Signori Conduit Wooder Trank		
8	VCP	450	Siphon-Conduit-Tuscarawas River		
			Siphon-Conduit-Tuscarawas River Siphon-Conduit-Tuscarawas River		
	12 42 66 42 48 30 30 30 30 30 30 30 30 30 30	18 RCP 12 RCP? 42 RCP 66 RCP 42 RCP 48 RCP 30 CIP 30 CIP 30 CIP 60 RCP 60 RCP 60 RCP 30 CIP 30 CIP 31 CIP 32 CIP 34 CIP 24 CIP 25 CIP 26 CIP 27 CIP 48 RCP 48 RCP 48 CMP 10 DIP 11 DIP 10 DIP 15 DIP	Size (Inches) Material Length (Feet) 18		



HUNTINGTON DISTRICT

U.S. ARMY CORPS OF ENGINEERS

CONTRACT NO. W91237-09-P-0133

CCTV AND LASER PROFILE INSPECTION SUMMARY

PIPES UNDER LEVEES

PIPE NO: 32 PIPE SIZE: 60" LENGTI I INSPECTED: Approximately 135 ft

PROJECT: Massillon Levee TYPE: CMP to RCP INSPECTION DATE: 10/1/09

OVERALL CONDITION: NASSCO Grade 3 - Moderate defects that will continue to deteriorate

GENERAL INSPECTION FINDING: O to 42 feet CMP, CMP bituminous coating missing in haunches, moderately corroded. RCP 42 ft to gatewell appears to be in good condition. Moisture present at some of the joints.

MAJOR DEFECTS

Pipe # 32	2, Federal Avenue South Gravity
Feet	Defect
2.0	Bituminous coating missing in haunch, moderately corroded
16.5	Bituminous coating missing in haunch, moderately corroded
19.7	Moisture at joint, 4 O'clock
22.0	Moisture at joint, 1.75" joint separation
42ft	Offset joint where CMP meets concrete, approx. 3" right side.
	Severely separated joint at crown.
53ft	Wet joint at approx. 3 o'clock
67ft	Staining at joint in crown
68ft	Rock in invert, could not move
79ft	Wet joint at approx. 3 o'clock
92ft	Staining at joint in crown
111ft	Wet joint at 9 o'clock
127ft	Approx. 1" joint separation, staining at 1:00
135ft	Gatewell



Levee Embankments

For use during Initial and Continuing Eligibility Inspections of levee systems

Rated Item	Rating	Rating Guidelines	Location/ Remarks/ Recommendations		
11. Culverts/ Discharge Pipes ¹ (This item includes both concrete and		There are no breaks, holes, cracks in the discharge pipes/ culverts that would result in significant water leakage. The pipe shape is still essentially circular. All joints appear to be closed and the soil tight. Corrugated metal pipes, if present, are in good condition with 100% of the original coating still in place (either asphalt or galvanizing) or have been relined with appropriate material, which is still in good condition. Condition of pipes has been verified using television camera video taping or visual inspection methods within the past five years, and the report for every pipe is available for review by the inspector.			
corrugated metal pipes.)		There are a small number of corrosion pinholes or cracks that could leak water and need to be repaired, but the entire length of pipe is still structurally sound and is not in danger of collapsing. Pipe shape may be ovalized in some locations but does not appear to be approaching a curvature reversal. A limited number of joints may have opened and soil loss may be beginning. Any open joints should be repaired prior to the next inspection. Corrugated metal pipes, if present, may be showing corrosion and pinholes but there are no areas with total section loss. Condition of pipes has been verified using television camera video taping or visual inspection methods within the past five years, and the report for every pipe is available for review by the inspector.			
		Culvert has deterioration and/or has significant leakage; it is in danger of collapsing or as already begun to collapse. Corrugated metal pipes have suffered 100% section loss in the invert. HOWEVER: Even if pipes appear to be in good condition, as judged by an external visual inspection, an Unacceptable Rating will be assigned if the condition of pipes has not been verified using television camera video taping or visual inspection methods within the past five years, and reports for all pipes are not available for review by the inspector.			
		N/A There are no discharge pipes/ culverts.			

Key: A = Acceptable. M = Minimally Acceptable; Maintenance is required. U = Unacceptable. N/A = Not Applicable. FDR = Flood Damage Reduction




¹ The decision on whether or not USACE inspectors should enter a pipe to perform a detailed inspection must be made at the USACE District level. This decision should be made in conjunction with the District Safety Office, as pipes may be considered confined spaces. This decision should consider the age of the pipe, the diameter of the pipe, the apparent condition of the pipe, and the length of the pipe. If a pipe is entered for the purposes of inspection, the inspector should record observations with a video camera in order that the condition of the entire pipe, including all joints, can later be assessed. Additionally, the video record provides a baseline to which future inspections can be compared.


NASSCO PACP Condition Grading System Code Matrix

Family	Group	Descriptor	Modifier	Code	Structural Grade	O&M Grade
		Missing Wall (MW)	C	SMWC	5	
		Other (Z)	C	SZC		
	Surface Damage Mechanical (M)		M	SRIM	1	
		Surface Spalling (SS)	M	SSSM	2	
		Aggregate Visible (AV)	M	SAVM	3	
		Aggregate Projecting (AP)	M	SAPM	3	
		Aggregate Missing (AM)	M	SAMM	4	
		Reinforcement Visible (RV)	M	SRVM	5	
		Reinforcement Corroded (RC)	M	SRCM	5	
		Missing Wall (MW)	M	SMWM	5	
		Other (Z)	M	SZM	N/A	
	Surface Damage Not Evident (Z)	Roughness Increased (RI)	Z	SRIZ	1	
		Surface Spalling (SS)	Z	SSSZ	2	
		Aggregate Visible (AV)	Z	SAVZ	3	
		Aggregate Projecting (AP)	Z	SAPZ	3	
		Aggregate Missing (AM)	Z	SAMZ	4	
		Reinforcement Visible (RV)	Z	SRVZ	5	
		Reinforcement Corroded (RC)	Z	SRCZ	5	
		Missing Wall (MW)	Z	SMWZ	5	
		Other (Z)	7	S77	N/A	
	Surface Damage (Metal Pipes)	Corrosion (CP)		SCP	3	
Structural	Lining Failure (LF)	Detached (D)		LFD	3	
		Defective End (DE)		LFDE	3	
		Blistered (B)		LFB	3	
		Service Cut Shifted (CS)		LFCS	3	
	16	Abandoned Connection (AC)		LFAC		
		Overcut Service (OC)		LFOC	3	
		Undercut Service (UC)		LFUC	3	
		Buckled (BK)		LFBK	3	
		Wrinkled (W)		LFW	3	
		Other (Z)		LFZ		
Structural	Weld Failure (WF)	Circumfrential (C)		WFC	2	
		Longitudinal (L)		WFL	2	
		Multiple (M)		WFM	3	
		Spiral (S)		WFS	2	
Structural	Point Repair (RP)	Localized Lining (L)		RPL		
		Localized Lining (L)	Defective (D)	RPLD	4	
		Patch Repair (P)		RPP		




View of entrance at Federal Avenue south pipe

























































Joint separated, 1-inch, staining at 8:00- 127ft











Massillon, Ohio Federal Avenue 60-Inch RCP Gravity Outlet Pipe #33 (North Pipe)



HUNTINGTON DISTRICT

U.S. ARMY CORPS OF ENGINEERS

CONTRACT NO. W91237-09-P-0133

CCTV AND LASER PROFILE INSPECTION SUMMARY

PIPES UNDER LEVEES

PIPE NO: 33 PIPE SIZE: 60" LENGTI I INSPECTED: Approximately 135 ft

PROJECT: Massillon Levee TYPE: CMP to RCP INSPECTION DATE: 10/1/09

OVERALL CONDITION: NASSCO Grade 3 - Moderate defects that will continue to deteriorate

GENERAL INSPECTION FINDING: O to 42 feet CMP, CMP bituminous coating missing in haunches, moderately corroded. RCP 42 ft to gatewell appears to be in good condition. Moisture present at some of the joints.

MAJOR DEFECTS

Pipe # 3	3, Federal Avenue North Gravity		
Feet	Defect		
2.0ft	Bituminous coating missing along haunch		
23ft	Offset joint, moisture and corrosion at joint, moderate corrosion left haunch		
23ft	Rust coming from joint at 4 o'clock		
39.4ft	Offset joint CMP to RCP		
128ft	Joint separation 1-inch		
134.4ft	Joint separation 2.2-inches		
135.0ft	Gatewell		



Levee Embankments

For use during Initial and Continuing Eligibility Inspections of levee systems

Rated Item	Rating	Rating Guidelines	Location/ Remarks/ Recommendations	
11. Culverts/ Discharge Pipes ¹ (This item includes both concrete and corrugated metal pipes.)		There are no breaks, holes, cracks in the discharge pipes/ culverts that would result in significant water leakage. The pipe shape is still essentially circular. All joints appear to be closed and the soil tight. Corrugated metal pipes, if present, are in good condition with 100% of the original coating still in place (either asphalt or galvanizing) or have been relined with appropriate material, which is still in good condition. Condition of pipes has been verified using television camera video taping or visual inspection methods within the past five years, and the report for every pipe is available for review by the inspector.		
		There are a small number of corrosion pinholes or cracks that could leak water and need to be repaired, but the entire length of pipe is still structurally sound and is not in danger of collapsing. Pipe shape may be ovalized in some locations but does not appear to be approaching a curvature reversal. A limited number of joints may have opened and soil loss may be beginning. Any open joints should be repaired prior to the next inspection. Corrugated metal pipes, if present, may be showing corrosion and pinholes but there are no areas with total section loss. Condition of pipes has been verified using television camera video taping or visual inspection methods within the past five years, and the report for every pipe is available for review by the inspector.		
		Culvert has deterioration and/or has significant leakage; it is in danger of collapsing or as already begun to collapse. Corrugated metal pipes have suffered 100% section loss in the invert. HOWEVER: Even if pipes appear to be in good condition, as judged by an external visual inspection, an Unacceptable Rating will be assigned if the condition of pipes has not been verified using television camera video taping or visual inspection methods within the past five years, and reports for all pipes are not available for review by the inspector.		
		N/A There are no discharge pipes/ culverts.		


Key: A = Acceptable. M = Minimally Acceptable; Maintenance is required. U = Unacceptable. N/A = Not Applicable. FDR = Flood Damage Reduction



¹ The decision on whether or not USACE inspectors should enter a pipe to perform a detailed inspection must be made at the USACE District level. This decision should be made in conjunction with the District Safety Office, as pipes may be considered confined spaces. This decision should consider the age of the pipe, the diameter of the pipe, the apparent condition of the pipe, and the length of the pipe. If a pipe is entered for the purposes of inspection, the inspector should record observations with a video camera in order that the condition of the entire pipe, including all joints, can later be assessed. Additionally, the video record provides a baseline to which future inspections can be compared.

NASSCO PACP Condition Grading System Code Matrix


Family	Group	Descriptor	Modifier	Code	Structural Grade	O&M Grade
		Missing Wall (MW)	C	SMWC	5	
		Other (Z)	C	SZC		
	Surface Damage Mechanical (M)		M	SRIM	1	
		Surface Spalling (SS)	M	SSSM	2	
		Aggregate Visible (AV)	M	SAVM	3	
		Aggregate Projecting (AP)	M	SAPM	3	
		Aggregate Missing (AM)	M	SAMM	4	
		Reinforcement Visible (RV)	M	SRVM	5	
		Reinforcement Corroded (RC)	M	SRCM	5	
		Missing Wall (MW)	M	SMWM	5	
		Other (Z)	M	SZM	N/A	
	Surface Damage Not Evident (Z)	Roughness Increased (RI)	Z	SRIZ	1	
		Surface Spalling (SS)	Z	SSSZ	2	
		Aggregate Visible (AV)	Z	SAVZ	3	
		Aggregate Projecting (AP)	Z	SAPZ	3	
		Aggregate Missing (AM)	Z	SAMZ	4	
		Reinforcement Visible (RV)	Z	SRVZ	5	
		Reinforcement Corroded (RC)	Z	SRCZ	5	
		Missing Wall (MW)	Z	SMWZ	5	
		Other (Z)	7	S77	N/A	
	Surface Damage (Metal Pipes)	Corrosion (CP)		SCP	3	
Structural Lining Failure (LF)	Lining Failure (LF)	Detached (D)		LFD	3	
		Defective End (DE)		LFDE	3	
		Blistered (B)		LFB	3	
		Service Cut Shifted (CS)		LFCS	3	
	16	Abandoned Connection (AC)		LFAC		
		Overcut Service (OC)		LFOC	3	
		Undercut Service (UC)		LFUC	3	
		Buckled (BK)		LFBK	3	
		Wrinkled (W)		LFW	3	
		Other (Z)		LFZ		
	Weld Failure (WF)	Circumfrential (C)		WFC	2	
		Longitudinal (L)		WFL	2	
		Multiple (M)		WFM	3	
		Spiral (S)		WFS	2	
Structural	Point Repair (RP)	Localized Lining (L)		RPL		
		Localized Lining (L)	Defective (D)	RPLD	4	
		Patch Repair (P)		RPP		





























Offset joint at 4:00 where CMP meets RCP (approx. 2")
































Massillon, Ohio Federal Avenue Pump Station Pipe #34, 35, and 36



Pipes Inspected, Massillon Levee					
Pipes	Size (Inches)	Material	Length (Feet)	Location	
23	18	RCP	103	West of RR with Flap Gate	
24	12	RCP?	175	Could not locate/unknown/does not exist	
25	42	RCP	95	Culvert through West Bank Levee opposite of Croose Avenue	
26	66	RCP	93	Culvert through East Bank Levee near control weir	
27	42	RCP	360	At inlet to siphon control weir	
28	48	RCP	97	James Avenue Pump Station Gravity Outlet	
29	30	CIP	100	Discharge from James Avenue Pump Station	
30	30	CIP	100	Discharge from James Avenue Pump Station	
31	30	CIP	100	Discharge from James Avenue Pump Station	
32	60	RCP	135	Federal Avenue Pump Station Outlet	
33	60	RCP	135	Federal Avenue Pump Station Outlet	
34	30	CIP	141	Discharge from Federal Avenue Pump Station	
35	30	CIP	141	Discharge from Federal Avenue Pump Station	
36	30	CIP	141	Discharge from Federal Avenue Pump Station	
50	50	CIF	141	Discharge Holli Federal Avenue Fullip Station	
37	15'X10'	RCB	120	Sippo Creek Pump Station	
38	24	CIP	5	Discharge from Sippo Creek Pump Station	
39	24	CIP	10	Discharge from Sippo Creek Pump Station	
40	24	CIP	20	Discharge from Sippo Creek Pump Station	
41	6'X6'	RCB	87	Gravity Arch Avenue Pump Station	
42	6'X6'	RCB	87	Gravity Arch Avenue Pump Station	
43	24	CIP	85	Discharge from Arch Avenue Pump Station	
44	24	CIP	85	Discharge from Arch Avenue Pump Station	
45	24	CIP	85	Discharge from Arch Avenue Pump Station	
46	48	RCP	90	Gravity Conduit through levee	
46b	48	СМР	317	Gravity Conduit MH upstream of Levee	
47	2.4	DID	460	Sinhan Canduit Dynalfield Intercents	
47	24	DIP	460	Siphon-Conduit-Brookfield Interceptor	
48	14	DIP	460	Siphon-Conduit-Brookfield Interceptor	
49	20	DIP	460	Siphon-Conduit-Brookfield Interceptor	
50	18	DIP	460	Siphon-Conduit-Wooster Trunk	
51	10	DIP	460	Siphon-Conduit-Wooster Trunk	
52	15	DIP	460	Siphon-Conduit-Wooster Trunk	
53	8	VCP	450	Siphon-Conduit-Tuscarawas River	
54	10	VCP	450	Siphon-Conduit-Tuscarawas River	

HUNTINGTON DISTRICT

U.S. ARMY CORPS OF ENGINEERS

CONTRACT NO. W91237-09-P-0133

CCTV AND LASER PROFILE INSPECTION SUMMARY

PIPES UNDER LEVEES

PIPE NO: Federal Avenue, Pump Pipes (34, 35, 36) PIPE SIZE: 30" LENGTH INSPECTED: 141 ft.

PROJECT: Massillon Levee TYPE: Coated DIP INSPECTI ON DATE: 9/15/09

OVERALL CONDITION: NASSCO Grade 4: Pipe will probably fail in 5 to 10 years. Pipe rated at a more serious condition due to that it is a pump line going through a levee.

GENERAL INSPECTION FINDINGS: All three pipes have moderate to severe corrosion at the joints. Missing protective coating and corrosion was also noted in flat areas and sharp bends. It appears in some sections that point repairs have been made on the protective coating. Recommend air pressure testing to verify integrity of the joints.

*Note: Pipe #35 has severe loss of lining from air-release valve to pump station on the downward grade section of pipe.

MAJOR DEFECTS

0-141 ft All three pipes have moderate to severe corrosion at the joints. Missing protective coating and corrosion was also noted in flat areas and sharp bends. It appears in some sections that point repairs have been made on the protective coating. Recommend air pressure testing to verify integrity of the	Feet	Defect
joints. *Note: Pipe #35 has severe loss of lining from air-release valve to pump station on the downward grade section of pipe.	0-141 ft	corrosion at the joints. Missing protective coating and corrosion was also noted in flat areas and sharp bends. It appears in some sections that point repairs have been made on the protective coating. Recommend air pressure testing to verify integrity of the joints. *Note: Pipe #35 has severe loss of lining from air-release valve to pump station on the



Levee Embankments


For use during Initial and Continuing Eligibility Inspections of levee systems

Rated Item	Rating		Rating Guidelines	Location/ Remarks/ Recommendations
11. Culverts/ Discharge Pipes ¹ (This item includes both concrete and	A		There are no breaks, holes, cracks in the discharge pipes/ culverts that would result in significant water leakage. The pipe shape is still essentially circular. All joints appear to be closed and the soil tight. Corrugated metal pipes, if present, are in good condition with 100% of the original coating still in place (either asphalt or galvanizing) or have been relined with appropriate material, which is still in good condition. Condition of pipes has been verified using television camera video taping or visual inspection methods within the past five years, and the report for every pipe is available for review by the inspector.	
corrugated metal pipes.)		М	There are a small number of corrosion pinholes or cracks that could leak water and need to be repaired, but the entire length of pipe is still structurally sound and is not in danger of collapsing. Pipe shape may be ovalized in some locations but does not appear to be approaching a curvature reversal. A limited number of joints may have opened and soil loss may be beginning. Any open joints should be repaired prior to the next inspection. Corrugated metal pipes, if present, may be showing corrosion and pinholes but there are no areas with total section loss. Condition of pipes has been verified using television camera video taping or visual inspection methods within the past five years, and the report for every pipe is available for review by the inspector.	
		U	Culvert has deterioration and/or has significant leakage; it is in danger of collapsing or as already begun to collapse. Corrugated metal pipes have suffered 100% section loss in the invert. HOWEVER: Even if pipes appear to be in good condition, as judged by an external visual inspection, an Unacceptable Rating will be assigned if the condition of pipes has not been verified using television camera video taping or visual inspection methods within the past five years, and reports for all pipes are not available for review by the inspector.	
			There are no discharge pipes/ culverts.	

Key: A = Acceptable. M = Minimally Acceptable; Maintenance is required. U = Unacceptable. N/A = Not Applicable. FDR = Flood Damage Reduction




¹ The decision on whether or not USACE inspectors should enter a pipe to perform a detailed inspection must be made at the USACE District level. This decision should be made in conjunction with the District Safety Office, as pipes may be considered confined spaces. This decision should consider the age of the pipe, the diameter of the pipe, the apparent condition of the pipe, and the length of the pipe. If a pipe is entered for the purposes of inspection, the inspector should record observations with a video camera in order that the condition of the entire pipe, including all joints, can later be assessed. Additionally, the video record provides a baseline to which future inspections can be compared.

















Massillon, Ohio Federal Avenue Pump Station Pipe #34 (South Pipe)















































































Massillon, Ohio Federal Avenue Pump Station Pipe #35 (Center Pipe)
























































































Massillon, Ohio Federal Avenue Pump Station Pipe #36 (North Pipe)

















































































Massillon, Ohio Sippo Creek 15'x10' RCB Pipe #37



	Pipes Inspected, Massillon Levee					
Pipes	Size (Inches)	Material	Length (Feet)	Location		
23	18	RCP	103	West of RR with Flap Gate		
24	12	RCP?	175	Could not locate/unknown/does not exist		
25	42	RCP	95	Culvert through West Bank Levee opposite of Croose Avenue		
26	66	RCP	93	Culvert through East Bank Levee near control weir		
27	42	RCP	360	At inlet to siphon control weir		
28	48	RCP	97	James Avenue Pump Station Gravity Outlet		
29	30	CIP	100	Discharge from James Avenue Pump Station		
30	30	CIP	100	Discharge from James Avenue Pump Station		
31	30	CIP	100	Discharge from James Avenue Pump Station		
32	60	RCP	135	Federal Avenue Pump Station Outlet		
33	60	RCP	135	Federal Avenue Pump Station Outlet		
34	30	CIP	141	Discharge from Federal Avenue Pump Station		
35	30	CIP	141	Discharge from Federal Avenue Pump Station		
36	30	CIP	141	Discharge from Federal Avenue Pump Station		
50	50	CII	171	Discharge from Federal Avenue Famp Station		
37	15'X10'	RCB	120	Sippo Creek Pump Station		
38	24	CIP	5	Discharge from Sippo Creek Pump Station		
39	24	CIP	10	Discharge from Sippo Creek Pump Station		
40	24	CIP	20	Discharge from Sippo Creek Pump Station		
41	6'X6'	RCB	87	Gravity Arch Avenue Pump Station		
42	6'X6'	RCB	87	Gravity Arch Avenue Pump Station		
43	24	CIP	85	Discharge from Arch Avenue Pump Station		
44	24	CIP	85	Discharge from Arch Avenue Pump Station		
45	24	CIP	85	Discharge from Arch Avenue Pump Station		
46	48	RCP	90	Gravity Conduit through levee		
46b	48	СМР	317	Gravity Conduit MH upstream of Levee		
4.7	2.4	DID	460	Cimbon Conduit Dunalifield Intercenter		
47	24 14	DIP DIP	460 460	Siphon-Conduit-Brookfield Interceptor		
48				Siphon-Conduit-Brookfield Interceptor		
49	20	DIP	460	Siphon-Conduit-Brookfield Interceptor		
50	18	DIP	460	Siphon-Conduit-Wooster Trunk		
51	10	DIP	460	Siphon-Conduit-Wooster Trunk		
52	15	DIP	460	Siphon-Conduit-Wooster Trunk		
53	8	VCP	450	Siphon-Conduit-Tuscarawas River		
54	10	VCP	450	Siphon-Conduit-Tuscarawas River		



HUNTINGTON DISTRICT

U.S. ARMY CORPS OF ENGINEERS

CONTRACT NO. W91237-09-P-0133

CCTV AND LASER PROFILE INSPECTION SUMMARY

PIPES UNDER LEVEES

PIPE NO: Sippo Avenue Box #37 PIPE SIZE: 15' X 10' LENGTH INSPECTED: 202 ft.

PROJECT: Massillon Levee TYPE: RCP INSPECTION DATE: 11/12/09

OVERALL CONDITION: NASSCO Rating 3: Moderate defects that will continue to deteriorate.

GENERAL INSPECTION FINDINGS: Most of the joints appear to have some weeping and/or signs of staining at the joints. Invert is rough in areas indicating moderate scouring. Rebar exposed and some spalling noticed in areas.

MAJOR DEFECTS

Sippo Avenue 15' X 10' Box #37					
Feet	Defect				
28ft	Spalling at joint				
30ft	Reinforcing steel exposed in crown				
39ft	Reinforcing steel exposed in crown				
56ft	Weeping and stained joint. Rebar exposed from				
	deteriorating joint.				
76ft	Rebar exposed from deteriorating joint .				
83ft	Weeping and stained joint. Rebar exposed from				
	deteriorating joint.				
98ft	Significant weeping and stained joint				
110ft	Weeping and stained joint. Rebar exposed from				
	deteriorating joint.				
118ft	4" scour hole left haunch				
Outlet-Pump Pipes	Invert under water, rough in areas, indicating				
	moderate scour in the invert.				



Levee Embankments


For use during Initial and Continuing Eligibility Inspections of levee systems

Rated Item	Rating		Rating Guidelines	Location/ Remarks/ Recommendations
11. Culverts/ Discharge Pipes ¹ (This item includes both concrete and		A	There are no breaks, holes, cracks in the discharge pipes/ culverts that would result in significant water leakage. The pipe shape is still essentially circular. All joints appear to be closed and the soil tight. Corrugated metal pipes, if present, are in good condition with 100% of the original coating still in place (either asphalt or galvanizing) or have been relined with appropriate material, which is still in good condition. Condition of pipes has been verified using television camera video taping or visual inspection methods within the past five years, and the report for every pipe is available for review by the inspector.	
corrugated metal pipes.)		М	There are a small number of corrosion pinholes or cracks that could leak water and need to be repaired, but the entire length of pipe is still structurally sound and is not in danger of collapsing. Pipe shape may be ovalized in some locations but does not appear to be approaching a curvature reversal. A limited number of joints may have opened and soil loss may be beginning. Any open joints should be repaired prior to the next inspection. Corrugated metal pipes, if present, may be showing corrosion and pinholes but there are no areas with total section loss. Condition of pipes has been verified using television camera video taping or visual inspection methods within the past five years, and the report for every pipe is available for review by the inspector.	
		U	Culvert has deterioration and/or has significant leakage; it is in danger of collapsing or as already begun to collapse. Corrugated metal pipes have suffered 100% section loss in the invert. HOWEVER: Even if pipes appear to be in good condition, as judged by an external visual inspection, an Unacceptable Rating will be assigned if the condition of pipes has not been verified using television camera video taping or visual inspection methods within the past five years, and reports for all pipes are not available for review by the inspector.	
			There are no discharge pipes/ culverts.	

Key: A = Acceptable. M = Minimally Acceptable; Maintenance is required. U = Unacceptable. N/A = Not Applicable. FDR = Flood Damage Reduction



¹ The decision on whether or not USACE inspectors should enter a pipe to perform a detailed inspection must be made at the USACE District level. This decision should be made in conjunction with the District Safety Office, as pipes may be considered confined spaces. This decision should consider the age of the pipe, the diameter of the pipe, the apparent condition of the pipe, and the length of the pipe. If a pipe is entered for the purposes of inspection, the inspector should record observations with a video camera in order that the condition of the entire pipe, including all joints, can later be assessed. Additionally, the video record provides a baseline to which future inspections can be compared.


































4- inch penetration in right side of box- outlet of box























Weeping joint left side, starts upper corner-56ft








Weeping joint, exposed rebar at right side-56ft























































































Massillon, Ohio Sippo Creek 24" DIP Pump Pipes Pipe #38, 39, 40



Pipes Inspected, Massillon Levee					
Pipes	Size (Inches)	Material	Length (Feet)	Location	
23	18	RCP	103	West of RR with Flap Gate	
24	12	RCP?	175	Could not locate/unknown/does not exist	
25	42	RCP	95	Culvert through West Bank Levee opposite of Croose Avenue	
26	66	RCP	93	Culvert through East Bank Levee near control weir	
27	42	RCP	360	At inlet to siphon control weir	
28	48	RCP	97	James Avenue Pump Station Gravity Outlet	
29	30	CIP	100	Discharge from James Avenue Pump Station	
30	30	CIP	100	Discharge from James Avenue Pump Station	
31	30	CIP	100	Discharge from James Avenue Pump Station	
32	60	RCP	135	Federal Avenue Pump Station Outlet	
33	60	RCP	135	Federal Avenue Pump Station Outlet	
34	30	CIP	141	Discharge from Federal Avenue Pump Station	
35	30	CIP	141	Discharge from Federal Avenue Pump Station	
36	30	CIP	141	Discharge from Federal Avenue Pump Station	
50	50	CIF	141	Discharge from Federal Avenue Fump Station	
37	15'X10'	RCB	120	Sippo Creek Pump Station	
38	24	CIP	5	Discharge from Sippo Creek Pump Station	
39	24	CIP	10	Discharge from Sippo Creek Pump Station	
40	24	CIP	20	Discharge from Sippo Creek Pump Station	
41	6'X6'	RCB	87	Gravity Arch Avenue Pump Station	
42	6'X6'	RCB	87	Gravity Arch Avenue Pump Station	
43	24	CIP	85	Discharge from Arch Avenue Pump Station	
44	24	CIP	85	Discharge from Arch Avenue Pump Station	
45	24	CIP	85	Discharge from Arch Avenue Pump Station	
46	48	RCP	90	Gravity Conduit through levee	
46b	48	СМР	317	Gravity Conduit MH upstream of Levee	
4.7	2.4	DID	460	Cimbon Conduit Depolational Interceptor	
47	24	DIP	460	Siphon-Conduit-Brookfield Interceptor	
48	14	DIP	460	Siphon-Conduit-Brookfield Interceptor	
49	20	DIP	460	Siphon-Conduit-Brookfield Interceptor	
50	18	DIP	460	Siphon-Conduit-Wooster Trunk	
51	10	DIP	460	Siphon-Conduit-Wooster Trunk	
52	15	DIP	460	Siphon-Conduit-Wooster Trunk	
53	8	VCP	450	Siphon-Conduit-Tuscarawas River	
54	10	VCP	450	Siphon-Conduit-Tuscarawas River	



HUNTINGTON DISTRICT

U.S. ARMY CORPS OF ENGINEERS

CONTRACT NO. W91237-09-P-0133

CCTV AND LASER PROFILE INSPECTION SUMMARY

PIPES UNDER LEVEES

PIPE NO: Sippo Avenue, Pump Pipes (38, 39, 40) PIPE SIZE: 24" LENGTH INSPECTED: 5, 10, 20

PROJECT: Massillon Levee TYPE: Coated DIP INSPECTION DATE: 9/17/09

OVERALL CONDITION: NASSCO Grade 4: Pipe will properly fail in 5 to 10 years. Pipe rated at a more serious condition due to that it is a pump line going through a levee.


GENERAL INPECTION FINDINGS: All three pipes have moderate to severe corrosion and rust at the joints and pipe walls. Missing protective coating was predominately around the haunches and inverts of the pipe. Recommend air pressure testing to verify integrity of the joints.

*Note: Pipe #39 (center) at 9.3ft has a severe offset/separated joint with potential leakage.

*Note: Punch list read total line footage at 120' per line. Actual footage: #38) approximately 5ft, #39) approximately 10ft, #40) approximately 20ft.

MAJOR DEFECTS

Feet	Defect
5, 10, 20 ft	All three pipes have moderate to severe corrosion and rust at the joints and pipe walls. Missing protective coating was predominately around the haunches and inverts of the pipe.
	Recommend air pressure testing to verify integrity of the joints.
	*Note: Pipe #39 (center) at 9.3ft has a severe offset/separated joint with potential leakage.



Levee Embankments

For use during Initial and Continuing Eligibility Inspections of levee systems

Rated Item	Rating	Rating Guidelines	Location/ Remarks/ Recommendations
11. Culverts/ Discharge Pipes ¹ (This item includes both concrete and		There are no breaks, holes, cracks in the discharge pipes/ culverts that would result in significant water leakage. The pipe shape is still essentially circular. All joints appear to be closed and the soil tight. Corrugated metal pipes, if present, are in good condition with 100% of the original coating still in place (either asphalt or galvanizing) or have been relined with appropriate material which is still in good condition. Condition of pipes has been verified using television camera video taping or visual inspection methods within the past five years, and the report for every pipe is available for review by the inspector.	Location Remarks Recommendations
corrugated metal pipes.)		There are a small number of corrosion pinholes or cracks that could leak water and need to be repaired, but the entire length of pipe is still structurally sound and is not in danger of collapsing. Pipe shape may be ovalized in some locations but does not appear to be approaching a curvature reversal. A limited number of joints may have opened and soil loss may be beginning. Any open joints should be repaired prior to the next inspection. Corrugated metal pipes, if present, may be showing corrosion and pinholes but there are no areas with total section loss. Condition of pipes has been verified using television camera video taping or visual inspection methods within the past five years, and the report for every pipe is available for review by the inspector.	
		Culvert has deterioration and/or has significant leakage; it is in danger of collapsing or as already begun to collapse. Corrugated metal pipes have suffered 100% section loss in the invert. HOWEVER: Even if pipes appear to be in good condition, as judged by an external visual inspection, an Unacceptable Rating will be assigned if the condition of pipes has not been verified using television camera video taping or visual inspection methods within the past five years, and reports for all pipes are not available for review by the inspector. N/A There are no discharge pipes/ culverts.	

Key: A = Acceptable. M = Minimally Acceptable; Maintenance is required. U = Unacceptable. N/A = Not Applicable. FDR = Flood Damage Reduction



¹ The decision on whether or not USACE inspectors should enter a pipe to perform a detailed inspection must be made at the USACE District level. This decision should be made in conjunction with the District Safety Office, as pipes may be considered confined spaces. This decision should consider the age of the pipe, the diameter of the pipe, the apparent condition of the pipe, and the length of the pipe. If a pipe is entered for the purposes of inspection, the inspector should record observations with a video camera in order that the condition of the entire pipe, including all joints, can later be assessed. Additionally, the video record provides a baseline to which future inspections can be compared.


















Massillon, Ohio Sippo Creek Pump Station Outlet Pipe #38 (West Pipe)






















Massillon, Ohio Sippo Creek Pump Station Outlet Pipe #39 (Center Pipe)




















Massillon, Ohio Sippo Creek Pump Station Outlet Pipe #40 (East Pipe)






































			Pipes Inspected, Ma	assillon Levee
Pipes	Size (Inches)	Material	Length (Feet)	Location
23	18	RCP	103	West of RR with Flap Gate
24	12	RCP?	175	Could not locate/unknown/does not exist
25	42	RCP	95	Culvert through West Bank Levee opposite of Croose Avenue
26	66	RCP	93	Culvert through East Bank Levee near control weir
27	42	RCP	360	At inlet to siphon control weir
28	48	RCP	97	James Avenue Pump Station Gravity Outlet
29	30	CIP	100	Discharge from James Avenue Pump Station
30	30	CIP	100	Discharge from James Avenue Pump Station
31	30	CIP	100	Discharge from James Avenue Pump Station
32	60	RCP	135	Federal Avenue Pump Station Outlet
33	60	RCP	135	Federal Avenue Pump Station Outlet
34	30	CIP	141	Discharge from Federal Avenue Pump Station
35	30	CIP	141	Discharge from Federal Avenue Pump Station
36	30	CIP	141	Discharge from Federal Avenue Pump Station
30	50	CIF	141	Discharge Hoff Federal Avenue Fullip Station
37	15'X10'	RCB	120	Sippo Creek Pump Station
38	24	CIP	5	Discharge from Sippo Creek Pump Station
39	24	CIP	10	Discharge from Sippo Creek Pump Station
40	24	CIP	20	Discharge from Sippo Creek Pump Station
41	6'X6'	RCB	87	Gravity Arch Avenue Pump Station
42	6'X6'	RCB	87	Gravity Arch Avenue Pump Station
43	24	CIP	85	Discharge from Arch Avenue Pump Station
44	24	CIP	85	Discharge from Arch Avenue Pump Station
45	24	CIP	85	Discharge from Arch Avenue Pump Station
46	48	RCP	90	Gravity Conduit through levee
46b	48	СМР	317	Gravity Conduit MH upstream of Levee
47	24	DIP	460	Siphon-Conduit-Brookfield Interceptor
48	14	DIP	460	Siphon-Conduit-Brookfield Interceptor
49	20	DIP	460	Siphon-Conduit-Brookfield Interceptor
F.O.	18	DIP	460	Siphon-Conduit-Wooster Trunk
50 51	10	DIP	460	
51 52	15	DIP	460 460	Siphon-Conduit-Wooster Trunk
D4	12	UIY	400	Siphon-Conduit-Wooster Trunk
F.2	0	L/CD	450	Cinhan Canduit Turagranus Dinar
53	8	VCP	450	Siphon-Conduit-Tuscarawas River
54	10	VCP	450	Siphon-Conduit-Tuscarawas River



















Massillon, Ohio Arch Avenue 6'x6'RCB Pipe #41 (North Box)



			Pipes Inspected, Ma	assillon Levee
Pipes	Size (Inches)	Material	Length (Feet)	Location
23	18	RCP	103	West of RR with Flap Gate
24	12	RCP?	175	Could not locate/unknown/does not exist
25	42	RCP	95	Culvert through West Bank Levee opposite of Croose Avenue
26	66	RCP	93	Culvert through East Bank Levee near control weir
27	42	RCP	360	At inlet to siphon control weir
28	48	RCP	97	James Avenue Pump Station Gravity Outlet
29	30	CIP	100	Discharge from James Avenue Pump Station
30	30	CIP	100	Discharge from James Avenue Pump Station
31	30	CIP	100	Discharge from James Avenue Pump Station
32	60	RCP	135	Federal Avenue Pump Station Outlet
33	60	RCP	135	Federal Avenue Pump Station Outlet
34	30	CIP	141	Discharge from Federal Avenue Pump Station
35	30	CIP	141	Discharge from Federal Avenue Pump Station
36	30	CIP	141	Discharge from Federal Avenue Pump Station
30	50	CIF	141	Discharge Hoff Federal Avenue Fullip Station
37	15'X10'	RCB	120	Sippo Creek Pump Station
38	24	CIP	5	Discharge from Sippo Creek Pump Station
39	24	CIP	10	Discharge from Sippo Creek Pump Station
40	24	CIP	20	Discharge from Sippo Creek Pump Station
41	6'X6'	RCB	87	Gravity Arch Avenue Pump Station
42	6'X6'	RCB	87	Gravity Arch Avenue Pump Station
43	24	CIP	85	Discharge from Arch Avenue Pump Station
44	24	CIP	85	Discharge from Arch Avenue Pump Station
45	24	CIP	85	Discharge from Arch Avenue Pump Station
46	48	RCP	90	Gravity Conduit through levee
46b	48	СМР	317	Gravity Conduit MH upstream of Levee
47	24	DIP	460	Siphon-Conduit-Brookfield Interceptor
48	14	DIP	460	Siphon-Conduit-Brookfield Interceptor
49	20	DIP	460	Siphon-Conduit-Brookfield Interceptor
50	18	DIP	460	Siphon-Conduit-Wooster Trunk
50 51	10	DIP	460	Siphon-Conduit-Wooster Trunk
52	15	DIP	460	Siphon-Conduit-Wooster Trunk
D4	12	UIY	400	Siphon-Conduit-wooster frunk
Г2	0	VCP	450	Ciphon Conduit Turgarayas Diyar
53	8		450	Siphon-Conduit-Tuscarawas River
54	10	VCP	450	Siphon-Conduit-Tuscarawas River



HUNTINGTON DISTRICT

U.S. ARMY CORPS OF ENGINEERS

CONTRACT NO. W91237-09-P-0133

CCTV AND LASER PROFILE INSPECTION SUMMARY

PIPES UNDER LEVEES

PIPE NO: Arch Avenue Box #41 PIPE SIZE: 6' X 6'

LENGTH INSPECTED: 87 ft.

PROJECT: Massillon Levee

TYPE: RCP

INSPECTION DATE: 11/12/09


OVERALL CONDITION: NASSCO Rating 3: Moderate defects that will continue to deteriorate.

GENERAL INSPECTION FINDINGS: Some of the joints are starting to become offset, possible soil movement is starting to occur in some areas.

MAJOR DEFECTS

Arch Avenue Box #41				
Feet	Defect			
5 ft	Rebar/nails visible in crown			
23ft	Slight spalling/ offset joint in crown			
32ft	Hairline cracking			
46ft	Open joint between North and South barrel			
68ft	Scouring/Staining in crown			
80ft	Right haunch, offset joint approx. 2", possible soil penetration			
85ft	Spalling/ cracking at headwall			

*First part of the structure from the inlet to gatewell is RCB, gatewell to outlet is RCP



Levee Embankments


For use during Initial and Continuing Eligibility Inspections of levee systems

Rated Item	Rating		Rating Guidelines	Location/ Remarks/ Recommendations
11. Culverts/ Discharge Pipes¹ (This item includes both concrete and corrugated metal pipes.)		A	There are no breaks, holes, cracks in the discharge pipes/ culverts that would result in significant water leakage. The pipe shape is still essentially circular. All joints appear to be closed and the soil tight. Corrugated metal pipes, if present, are in good condition with 100% of the original coating still in place (either asphalt or galvanizing) or have been relined with appropriate material, which is still in good condition. Condition of pipes has been verified using television camera video taping or visual inspection methods within the past five years, and the report for every pipe is available for review by the inspector.	
		М	There are a small number of corrosion pinholes or cracks that could leak water and need to be repaired, but the entire length of pipe is still structurally sound and is not in danger of collapsing. Pipe shape may be ovalized in some locations but does not appear to be approaching a curvature reversal. A limited number of joints may have opened and soil loss may be beginning. Any open joints should be repaired prior to the next inspection. Corrugated metal pipes, if present, may be showing corrosion and pinholes but there are no areas with total section loss. Condition of pipes has been verified using television camera video taping or visual inspection methods within the past five years, and the report for every pipe is available for review by the inspector.	
		U	Culvert has deterioration and/or has significant leakage; it is in danger of collapsing or as already begun to collapse. Corrugated metal pipes have suffered 100% section loss in the invert. HOWEVER: Even if pipes appear to be in good condition, as judged by an external visual inspection, an Unacceptable Rating will be assigned if the condition of pipes has not been verified using television camera video taping or visual inspection methods within the past five years, and reports for all pipes are not available for review by the inspector.	
N/A There are no discharge pipes/ culverts.				


Key: A = Acceptable. M = Minimally Acceptable; Maintenance is required. U = Unacceptable. N/A = Not Applicable. FDR = Flood Damage Reduction



¹ The decision on whether or not USACE inspectors should enter a pipe to perform a detailed inspection must be made at the USACE District level. This decision should be made in conjunction with the District Safety Office, as pipes may be considered confined spaces. This decision should consider the age of the pipe, the diameter of the pipe, the apparent condition of the pipe, and the length of the pipe. If a pipe is entered for the purposes of inspection, the inspector should record observations with a video camera in order that the condition of the entire pipe, including all joints, can later be assessed. Additionally, the video record provides a baseline to which future inspections can be compared.

















Possible hairline crack at 31.9 feet

31.9 FT.


#41 NORTH PIPE
























































Massillon, Ohio Arch Avenue 6'x6'RCB Pipe #42 (South Box)



HUNTINGTON DISTRICT

U.S. ARMY CORPS OF ENGINEERS

CONTRACT NO. W91237-09-P-0133

CCTV AND LASER PROFILE INSPECTION SUMMARY

PIPES UNDER LEVEES

PIPE NO: Arch Avenue Box #42 PIPE SIZE: 6' X 6' LENG

LENGTH INSPECTED: 87 ft.

PROJECT: Massillon Levee

TYPE: RCP

INSPECTION DATE: 11/12/09

OVERALL CONDITION: NASSCO Rating 3: Moderate defects that will continue to deteriorate.


GENERAL INSPECTION FINDINGS: GENERAL INSPECTION FINDINGS: Some of the joints are starting to become

offset, possible soil movement is starting to occur in some areas.

MAJOR DEFECTS

Arch Avenue Box #42				
Feet Defect				
Oft-2ft	Spalling, staining, and moisture at joint			
13ft	Nails/Rebar in crown			
18ft	Spalling at joint right side			
23ft	10- inch penetration right side			
46ft	Open joint between barrels/ 8- inch penetration in crown/ 6- inch penetration left side/ erosion of joint at invert			
52ft	Moisture in joint			
68ft-70ft	Spalling/staining of joint, deterioration and scouring at haunch			
79ft	Scouring at joint in left haunch, missing mortar in joint, as well as soil/rust penetrating through joint			
84ft	Radial cracking near joint/ cracking at joint and exposed rebar at 11 o'clock			

^{*}First part of the structure from the inlet to gatewell is RCB, gatewell to outlet is RCP



Levee Embankments

For use during Initial and Continuing Eligibility Inspections of levee systems

Rated Item	Rating		Rating Guidelines	Location/ Remarks/ Recommendations	
11. Culverts/ Discharge Pipes¹ (This item includes both concrete and corrugated metal pipes.)		A	There are no breaks, holes, cracks in the discharge pipes/ culverts that would result in significant water leakage. The pipe shape is still essentially circular. All joints appear to be closed and the soil tight. Corrugated metal pipes, if present, are in good condition with 100% of the original coating still in place (either asphalt or galvanizing) or have been relined with appropriate material, which is still in good condition. Condition of pipes has been verified using television camera video taping or visual inspection methods within the past five years, and the report for every pipe is available for review by the inspector.		
		М	There are a small number of corrosion pinholes or cracks that could leak water and need to be repaired, but the entire length of pipe is still structurally sound and is not in danger of collapsing. Pipe shape may be ovalized in some locations but does not appear to be approaching a curvature reversal. A limited number of joints may have opened and soil loss may be beginning. Any open joints should be repaired prior to the next inspection. Corrugated metal pipes, if present, may be showing corrosion and pinholes but there are no areas with total section loss. Condition of pipes has been verified using television camera video taping or visual inspection methods within the past five years, and the report for every pipe is available for review by the inspector.		
	U N/A	Culvert has deterioration and/or has significant leakage; it is in danger of collapsing or as already begun to collapse. Corrugated metal pipes have suffered 100% section loss in the invert. HOWEVER: Even if pipes appear to be in good condition, as judged by an external visual inspection, an Unacceptable Rating will be assigned if the condition of pipes has not been verified using television camera video taping or visual inspection methods within the past five years, and reports for all pipes are not available for review by the inspector.			
	N/A There are no discharge pipes/ culverts.				

Key: A = Acceptable. M = Minimally Acceptable; Maintenance is required. U = Unacceptable. N/A = Not Applicable. FDR = Flood Damage Reduction




¹ The decision on whether or not USACE inspectors should enter a pipe to perform a detailed inspection must be made at the USACE District level. This decision should be made in conjunction with the District Safety Office, as pipes may be considered confined spaces. This decision should consider the age of the pipe, the diameter of the pipe, the apparent condition of the pipe, and the length of the pipe. If a pipe is entered for the purposes of inspection, the inspector should record observations with a video camera in order that the condition of the entire pipe, including all joints, can later be assessed. Additionally, the video record provides a baseline to which future inspections can be compared.













































































Scouring at joint in left haunch/soil or rust seeping in through joint- 79ft




















Massillon, Ohio Arch Avenue 24" CIP Pump Pipes Pipe #43 (South), 44 (Center), 45 (North)



	Pipes Inspected, Massillon Levee				
Pipes	Size (Inches)	Material	Length (Feet)	Location	
23	18	RCP	103	West of RR with Flap Gate	
24	12	RCP?	175	Could not locate/unknown/does not exist	
25	42	RCP	95	Culvert through West Bank Levee opposite of Croose Avenue	
26	66	RCP	93	Culvert through East Bank Levee near control weir	
27	42	RCP	360	At inlet to siphon control weir	
28	48	RCP	97	James Avenue Pump Station Gravity Outlet	
29	30	CIP	100	Discharge from James Avenue Pump Station	
30	30	CIP	100	Discharge from James Avenue Pump Station	
31	30	CIP	100	Discharge from James Avenue Pump Station	
32	60	RCP	135	Federal Avenue Pump Station Outlet	
33	60	RCP	135	Federal Avenue Pump Station Outlet	
34	30	CIP	141	Discharge from Federal Avenue Pump Station	
35	30	CIP	141	Discharge from Federal Avenue Pump Station	
36	30	CIP	141	Discharge from Federal Avenue Pump Station	
30	50	CIF	141	Discharge Hoff Federal Avenue Fullip Station	
37	15'X10'	RCP	120	Sippo Avenue Pump Station	
38	24	CIP	5	Discharge from Sippo Avenue Pump Station	
39	24	CIP	10	Discharge from Sippo Avenue Pump Station	
40	24	CIP	20	Discharge from Sippo Avenue Pump Station	
41	6'X6'	RCP	87	Gravity Arch Avenue Pump Station	
42	6'X6'	RCP	87	Gravity Arch Avenue Pump Station	
43	24	CIP	85	Discharge from Arch Avenue Pump Station	
44	24	CIP	85	Discharge from Arch Avenue Pump Station	
45	24	CIP	85	Discharge from Arch Avenue Pump Station	
46	48	RCP	90	Gravity Conduit through levee	
46b	48	СМР	317	Gravity Conduit MH upstream of Levee	
47	24	DIP	460	Siphon-Conduit-Brookfield Interceptor	
48	14	DIP	460	Siphon-Conduit-Brookfield Interceptor	
49	20	DIP	460	Siphon-Conduit-Brookfield Interceptor	
50	18	DIP	460	Siphon-Conduit-Wooster Trunk	
50 51	10	DIP	460	Siphon-Conduit-Wooster Trunk	
52	15	DIP	460	Siphon-Conduit-Wooster Trunk	
<u></u>	13	UIF	11 00	piphon-conduit-wooster frunk	
E 2	8	VCP	450	Sinhan Conduit Tuscarawas Pivar	
53 r4				Siphon-Conduit-Tuscarawas River	
54	10	VCP	450	Siphon-Conduit-Tuscarawas River	



HUNTINGTON DISTRICT

U.S. ARMY CORPS OF ENGINEERS

CONTRACT NO. W91237-09-P-0133

CCTV AND LASER PROFILE INSPECTION SUMMARY

PIPES UNDER LEVEES

PIPE NO: Arch Avenue Pump Pipes (43, 44, 45) PIPE SIZE: 24" LENGTH INSPECTED: 85 ft.

PROJECT: Massillon Levee TYPE: CIP INSPECTION DATE: 9/14/09

OVERALL CONDITION: NASSCO Grade 4: Pipe will probably fail in 5 to 10 years. Pipe rated at a more serious condition due to that it is a pump line going through a levee.

GENERAL INSPECTION FINDINGS: All three pipes have moderate to severe corrosion at the joints. Missing protective coating and corrosion was also noted in flat areas and sharp bends. It appears in some sections that point repairs have been made on the protective coating. Recommend air pressure testing to verify integrity of the joints.

MAJOR DEFECTS

Feet	Defect
0-85 ft	All three pipes have moderate to severe corrosion at the joints. Missing protective coating and corrosion was also noted in flat areas and sharp bends. It appears in some sections that point repairs have been made on the protective coating. Recommend air pressure testing to verify integrity of the joints.



Levee Embankments

For use during Initial and Continuing Eligibility Inspections of levee systems


Rated Item	Rating	Rating Guidelines	Location/ Remarks/ Recommendations
11. Culverts/ Discharge Pipes ¹ (This item includes both concrete and		There are no breaks, holes, cracks in the discharge pipes/ culverts that would result in significant water leakage. The pipe shape is still essentially circular. All joints appear to be closed and the soil tight. Corrugated metal pipes, if present, are in good condition with 100% of the original coating still in place (either asphalt or galvanizing) or have been relined with appropriate material which is still in good condition. Condition of pipes has been verified using television camera video taping or visual inspection methods within the past five years, and the report for every pipe is available for review by the inspector.	
corrugated metal pipes.)		There are a small number of corrosion pinholes or cracks that could leak water and need to be repaired, but the entire length of pipe is still structurally sound and is not in danger of collapsing. Pipe shape may be ovalized in some locations but does not appear to be approaching a curvature reversal. A limited number of joints may have opened and soil loss may be beginning. Any open joints should be repaired prior to the next inspection. Corrugated metal pipes, if present, may be showing corrosion and pinholes but there are no areas with total section loss. Condition of pipes has been verified using television camera video taping or visual inspection methods within the past five years, and the report for every pipe is available for review by the inspector.	
		Culvert has deterioration and/or has significant leakage; it is in danger of collapsing or as already begun to collapse. Corrugated metal pipes have suffered 100% section loss in the invert. HOWEVER: Even if pipes appear to be in good condition, as judged by an external visual inspection, an Unacceptable Rating will be assigned if the condition of pipes has not been verified using television camera video taping or visual inspection methods within the past five years, and reports for all pipes are not available for review by the inspector. N/A There are no discharge pipes/ culverts.	

Key: A = Acceptable. M = Minimally Acceptable; Maintenance is required. U = Unacceptable. N/A = Not Applicable. FDR = Flood Damage Reduction




¹ The decision on whether or not USACE inspectors should enter a pipe to perform a detailed inspection must be made at the USACE District level. This decision should be made in conjunction with the District Safety Office, as pipes may be considered confined spaces. This decision should consider the age of the pipe, the diameter of the pipe, the apparent condition of the pipe, and the length of the pipe. If a pipe is entered for the purposes of inspection, the inspector should record observations with a video camera in order that the condition of the entire pipe, including all joints, can later be assessed. Additionally, the video record provides a baseline to which future inspections can be compared.

Massillon, Ohio Arch Avenue Pump Station Pipe #43 (South Pipe)






























Massillon, Ohio Arch Avenue Pump Station Pipe #44 (Center Pipe)




























Massillon, Ohio Arch Avenue Pump Station Pipe #45 (North Pipe)





















Massillon, Ohio Arch Avenue Gravity-RCP Pipe #46 (MH downgrade through levee)



			Pipes Inspected, Ma	assillon Levee
Pipes	Size (Inches)	Material	Length (Feet)	Location
23	18	RCP	103	West of RR with Flap Gate
24	12	RCP?	175	Could not locate/unknown/does not exist
25	42	RCP	95	Culvert through West Bank Levee opposite of Croose Avenue
26	66	RCP	93	Culvert through East Bank Levee near control weir
27	42	RCP	360	At inlet to siphon control weir
28	48	RCP	97	James Avenue Pump Station Gravity Outlet
29	30	CIP	100	Discharge from James Avenue Pump Station
30	30	CIP	100	Discharge from James Avenue Pump Station
31	30	CIP	100	Discharge from James Avenue Pump Station
32	60	RCP	135	Federal Avenue Pump Station Outlet
33	60	RCP	135	Federal Avenue Pump Station Outlet
34	30	CIP	141	Discharge from Federal Avenue Pump Station
35	30	CIP	141	Discharge from Federal Avenue Pump Station
36	30	CIP	141	Discharge from Federal Avenue Pump Station
30	50	CIF	141	Discharge Hoff Federal Avenue Fullip Station
37	15'X10'	RCB	120	Sippo Creek Pump Station
38	24	CIP	5	Discharge from Sippo Creek Pump Station
39	24	CIP	10	Discharge from Sippo Creek Pump Station
40	24	CIP	20	Discharge from Sippo Creek Pump Station
41	6'X6'	RCB	87	Gravity Arch Avenue Pump Station
42	6'X6'	RCB	87	Gravity Arch Avenue Pump Station
43	24	CIP	85	Discharge from Arch Avenue Pump Station
44	24	CIP	85	Discharge from Arch Avenue Pump Station
45	24	CIP	85	Discharge from Arch Avenue Pump Station
46	48	RCP	90	Gravity Conduit through levee
46b	48	СМР	317	Gravity Conduit MH upstream of Levee
47	24	DIP	460	Siphon-Conduit-Brookfield Interceptor
48	14	DIP	460	Siphon-Conduit-Brookfield Interceptor
49	20	DIP	460	Siphon-Conduit-Brookfield Interceptor
50	18	DIP	460	Siphon-Conduit-Wooster Trunk
51	10	DIP	460	Siphon-Conduit-Wooster Trunk
52	15	DIP	460	Siphon-Conduit-Wooster Trunk
J2	10	DIF	HUU	piphon-conduit-wooster frunk
E 2	8	VCP	450	Sinhan Conduit Tuscarawas Pivar
53 r4				Siphon-Conduit-Tuscarawas River
54	10	VCP	450	Siphon-Conduit-Tuscarawas River



HUNTINGTON DISTRICT

U.S. ARMY CORPS OF ENGINEERS

CONTRACT NO. W91237-09-P-0133

CCTV AND LASER PROFILE INSPECTION SUMMARY

PIPES UNDER LEVEES

PIPE NO: Arch Avenue Pipe #46

PIPE SIZE: 48"

LENGTH INSPECTED: 90 ft.

PROJECT: Massillon Levee

TYPE: RCP

INSPECTION DATE: 9/29/09


OVERALL CONDITION: NASSCO Rating 3: Moderate defects that will continue to deteriorate.

GENERAL INSPECTION FINDINGS: Some of the joints are wider at the bottom, indicating the pipe may have

settled some.

MAJOR DEFECTS

Arch Avenue Pipe #46 (MH to Gatewell/Outlet)				
Feet	Defect			
Oft-90ft	Several joints appear to be wider at the bottom, indicating that the line has some slight settlement.			



Levee Embankments

For use during Initial and Continuing Eligibility Inspections of levee systems

Rated Item	Rating	Rating Guidelines	Location/ Remarks/ Recommendations			
11. Culverts/ Discharge Pipes¹ (This item includes both concrete and		There are no breaks, holes, cracks in the discharge pipes/cul water leakage. The pipe shape is still essentially circular. A soil tight. Corrugated metal pipes, if present, are in good cor coating still in place (either asphalt or galvanizing) or have b which is still in good condition. Condition of pipes has been video taping or visual inspection methods within the past fiv is available for review by the inspector.	l joints appear to be closed and the dition with 100% of the original sen relined with appropriate material, verified using television camera			
corrugated metal pipes.)		There are a small number of corrosion pinholes or cracks that repaired, but the entire length of pipe is still structurally some Pipe shape may be ovalized in some locations but does not a reversal. A limited number of joints may have opened and s joints should be repaired prior to the next inspection. Corrug showing corrosion and pinholes but there are no areas with that been verified using television camera video taping or visions past five years, and the report for every pipe is available for the same content of the s	d and is not in danger of collapsing. Spear to be approaching a curvature soil loss may be beginning. Any open ated metal pipes, if present, may be stal section loss. Condition of pipes at inspection methods within the			
		Culvert has deterioration and/or has significant leakage; it is begun to collapse. Corrugated metal pipes have suffered 100 HOWEVER: Even if pipes appear to be in good condition, a inspection, an Unacceptable Rating will be assigned if the cousing television camera video taping or visual inspection me reports for all pipes are not available for review by the inspection.	% section loss in the invert. judged by an external visual ndition of pipes has not been verified hods within the past five years, and			
	N/A There are no discharge pipes/ culverts.					

Key: A = Acceptable. M = Minimally Acceptable; Maintenance is required. U = Unacceptable. N/A = Not Applicable. FDR = Flood Damage Reduction



¹ The decision on whether or not USACE inspectors should enter a pipe to perform a detailed inspection must be made at the USACE District level. This decision should be made in conjunction with the District Safety Office, as pipes may be considered confined spaces. This decision should consider the age of the pipe, the diameter of the pipe, the apparent condition of the pipe, and the length of the pipe. If a pipe is entered for the purposes of inspection, the inspector should record observations with a video camera in order that the condition of the entire pipe, including all joints, can later be assessed. Additionally, the video record provides a baseline to which future inspections can be compared.






























Arch Avenue Storm manhole upstream of levee

Massillon, Ohio Arch Avenue Gravity-CMP Pipe #46b

(From MH going upstream under road)

HUNTINGTON DISTRICT

U.S. ARMY CORPS OF ENGINEERS

CONTRACT NO. W91237-09-P-0133

CCTV AND LASER PROFILE INSPECTION SUMMARY

PIPES UNDER LEVEES

PIPE NO: Arch Avenue Pipe #46b PIPE SIZE: 48" LENGTH INSPECTED: 31/ft.

PROJECT: Massillon Levee TYPE: CMP INSPECTION DATE: 11/10/09


OVERALL CONDITION: NASSCO Rating 5: Pipe is failing, requires immediate attention.

GENERAL INSPECTION FINDINGS: Invert is missing in several areas, starting to deflect in areas.

MAJOR DEFECTS

Arch Avenue Pipe #46B (MH Upgrade)				
Feet	Defect			
0ft-317ft	Invert is rusted completely through in several areas throughout the pipe, starting to deflect and buckle in areas.			





Interior Drainage System

For use during Initial and Continuing Eligibility Inspections of interior drainage systems


Rated Item	Rating		Rating Guidelines	Location/ Remarks/ Recommendations
8. Monolith Joints		A	The joint material is in good condition. The exterior joint sealant is intact and cracking/ desiccation is minimal. Joint filler material and/or waterstop is not visible at any point.	
		М	The joint material has appreciable deterioration to the point where joint filler material and/or waterstop is visible in some locations. This needs to be repaired or replaced to prevent spalling and cracking during freeze/ thaw cycles, and to ensure water tightness of the joint.	
		U	The joint material is severely deteriorated or the concrete adjacent to the monolith joints has spalled and cracked, damaging the waterstop; in either case damage has occurred to the point where it is apparent that the joint is no longer watertight and will not provide the intended level of protection during a flood.	
		N/A	There are no monolith joints in the interior drainage system.	
9. Culverts/Disch arge Pipes ¹		A	There are no breaks, holes, cracks in the discharge pipes/ culverts that would result in significant water leakage. The pipe shape is still essentially circular. All joints appear to be closed and the soil tight. Corrugated metal pipes, if present, are in good condition with 100% of the original coating still in place (either asphalt or galvanizing) or have been relined with appropriate material, which is still in good condition. Condition of pipes has been verified using television camera video taping or visual inspection methods within the past five years, and the report for every pipe is available for review by the inspector.	
		М	There are a small number of corrosion pinholes or cracks that could leak water and need to be repaired, but the entire length of pipe is still structurally sound and is not in danger of collapsing. Pipe shape may be ovalized in some locations but does not appear to be approaching a curvature reversal. A limited number of joints may have opened and soil loss may be beginning. Any open joints should be repaired prior to the next inspection. Corrugated metal pipes, if present, may be showing corrosion and pinholes but there are no areas with total section loss. Condition of pipes has been verified using television camera video taping or visual inspection methods within the past five years, and the report for every pipe is available for review by the inspector.	
		U	Culvert has deterioration and/or has significant leakage; it is in danger of collapsing or as already begun to collapse. Corrugated metal pipes have suffered 100% section loss in the invert. HOWEVER: Even if pipes appear to be in good condition, as judged by an external visual inspection, an Unacceptable Rating will be assigned if the condition of pipes has not been verified using television camera video taping or visual inspection methods within the past five years, and reports for all pipes are not available for review by the inspector.	
77 0 0 111			There are no discharge pipes/ culverts. Intuitible: Maintenance is required. IL = Unaccentable. N/A = Not Applicable. FDR = Flood Damage.	P. 1. C.

Key: A = Acceptable. M = Minimally Acceptable; Maintenance is required. U = Unacceptable. N/A = Not Applicable. FDR = Flood Damage Reduction


Interior Drainage System



¹ The decision on whether or not USACE inspectors should enter a pipe to perform a detailed inspection must be made at the USACE District level. This decision should be made in conjunction with the District Safety Office, as pipes may be considered confined spaces. This decision should consider the age of the pipe, the diameter of the pipe, the apparent condition of the pipe, and the length of the pipe. If a pipe is entered for the purposes of inspection, the inspector should record observations with a video camera in order that the condition of the entire pipe, including all joints, can later be assessed. Additionally, the video record provides a baseline to which future inspections can be compared.




































































Massillon, Ohio Brookfield and Wooster Sanitary Sewer Siphons




			Pipes Inspected, Ma	assillon Levee
Pipes	Size (Inches)	Material	Length (Feet)	Location
23	18	RCP	103	West of RR with Flap Gate
24	12	RCP?	175	Could not locate/unknown/does not exist
25	42	RCP	95	Culvert through West Bank Levee opposite of Croose Avenue
26	66	RCP	93	Culvert through East Bank Levee near control weir
27	42	RCP	360	At inlet to siphon control weir
20	40	0.00	0.7	
28	48	RCP	97	James Avenue Pump Station Gravity Outlet
29	30	CIP	100	Discharge from James Avenue Pump Station
30	30	CIP	100	Discharge from James Avenue Pump Station
31	30	CIP	100	Discharge from James Avenue Pump Station
32	60	RCP	135	Federal Avenue Pump Station Outlet
33	60	RCP	135	Federal Avenue Pump Station Outlet
34	30	CIP	141	Discharge from Federal Avenue Pump Station
35	30	CIP	141	Discharge from Federal Avenue Pump Station
36	30	CIP	141	Discharge from Federal Avenue Pump Station
			<u> </u>	- Isoma ge nom redetan trende ramp station
37	15'X10'	RCB	120	Sippo Creek Pump Station
38	24	CIP	5	Discharge from Sippo Creek Pump Station
39	24	CIP	10	Discharge from Sippo Creek Pump Station
40	24	CIP	20	Discharge from Sippo Creek Pump Station
41	6'X6'	RCB	87	Gravity Arch Avenue Pump Station
42	6'X6'	RCB	87	Gravity Arch Avenue Pump Station
43	24	CIP	85	Discharge from Arch Avenue Pump Station
44	24	CIP	85	Discharge from Arch Avenue Pump Station
45	24	CIP	85	Discharge from Arch Avenue Pump Station
46	48	RCP	90	Gravity Conduit through levee
46b	48	СМР	317	Gravity Conduit MH upstream of Levee
47	24	DIP	460	Sanitary Sinhan Conduit Prockfield Intercentor
47 48	14	DIP	460	Sanitary Siphon-Conduit-Brookfield Interceptor Sanitary Siphon-Conduit-Brookfield Interceptor
	20	DIP	460	
49	20	DIP	400	Sanitary Siphon-Conduit-Brookfield Interceptor
50	18	DIP	460	Sanitary Siphon-Conduit-Wooster Trunk
51	10	DIP	460	Sanitary Siphon-Conduit-Wooster Trunk
52	15	DIP	460	Sanitary Siphon-Conduit-Wooster Trunk
53	8	VCP	450	Sanitary Siphon-Conduit-Tuscarawas River
54	10	VCP	450	Sanitary Siphon-Conduit-Tuscarawas River













Massillon, Ohio Brookfield Sanitary Sewer Siphons Pipe #47, 48, 49

	Pipes Inspected, Massillon Levee				
Pipes	Size (Inches)	Material	Length (Feet)	Location	
23	18	RCP	103	West of RR with Flap Gate	
24	12	RCP?	175	Could not locate/unknown/does not exist	
25	42	RCP	95	Culvert through West Bank Levee opposite of Croose Avenue	
26	66	RCP	93	Culvert through East Bank Levee near control weir	
27	42	RCP	360	At inlet to siphon control weir	
28	48	RCP	97	James Avenue Pump Station Gravity Outlet	
29	30	CIP	100	Discharge from James Avenue Pump Station	
30	30	CIP	100	Discharge from James Avenue Pump Station	
31	30	CIP	100	Discharge from James Avenue Pump Station	
32	60	RCP	135	Federal Avenue Pump Station Outlet	
33	60	RCP	135	Federal Avenue Pump Station Outlet	
34	30	CIP	141	Discharge from Federal Avenue Pump Station	
35	30	CIP	141	Discharge from Federal Avenue Pump Station	
36	30	CIP	141	Discharge from Federal Avenue Pump Station	
50	50	CII	141	Discharge from Federal Avenue Fump Station	
37	15'X10'	RCP	120	Sippo Avenue Pump Station	
38	24	CIP	5	Discharge from Sippo Avenue Pump Station	
39	24	CIP	10	Discharge from Sippo Avenue Pump Station	
40	24	CIP	20	Discharge from Sippo Avenue Pump Station	
41	6'X6'	RCP	87	Gravity Arch Avenue Pump Station	
42	6'X6'	RCP	87	Gravity Arch Avenue Pump Station	
43	24	CIP	85	Discharge from Arch Avenue Pump Station	
44	24	CIP	85	Discharge from Arch Avenue Pump Station	
45	24	CIP	85	Discharge from Arch Avenue Pump Station	
46	48	RCP	90	Gravity Conduit through levee	
46b	48	СМР	317	Gravity Conduit MH upstream of Levee	
47	24	DIP	460	Capitan, Ciph an Canduit Brackfield Intercentor	
47	24 14	DIP	460	Sanitary Siphon-Conduit-Brookfield Interceptor	
48		DIP		Sanitary Siphon-Conduit-Brookfield Interceptor Sanitary Siphon-Conduit-Brookfield Interceptor	
49	20	DIP	460	Sanitary Siprion-Conduit-Brookneid Interceptor	
50	18	DIP	460	Sanitary Siphon-Conduit-Wooster Trunk	
51	10	DIP	460	Sanitary Siphon-Conduit-Wooster Trunk	
52	15	DIP	460	Sanitary Siphon-Conduit-Wooster Trunk	
53	8	VCP	450	Sanitary Siphon-Conduit-Tuscarawas River	
54	10	VCP	450	Sanitary Siphon-Conduit-Tuscarawas River	



Massillon, Ohio Brookfield Sanitary Sewer Siphon Pipe #47, 24-inch DIP

	Pipes Inspected, Massillon Levee				
Pipes	Size (Inches)	Material	Length (Feet)	Location	
23	18	RCP	103	West of RR with Flap Gate	
24	12	RCP?	175	Could not locate/unknown/does not exist	
25	42	RCP	95	Culvert through West Bank Levee opposite of Croose Avenue	
26	66	RCP	93	Culvert through East Bank Levee near control weir	
27	42	RCP	360	At inlet to siphon control weir	
28	48	RCP	97	James Avenue Pump Station Gravity Outlet	
29	30	CIP	100	Discharge from James Avenue Pump Station	
30	30	CIP	100	Discharge from James Avenue Pump Station	
31	30	CIP	100	Discharge from James Avenue Pump Station	
32	60	RCP	135	Federal Avenue Pump Station Outlet	
33	60	RCP	135	Federal Avenue Pump Station Outlet	
34	30	CIP	141	Discharge from Federal Avenue Pump Station	
35	30	CIP	141	Discharge from Federal Avenue Pump Station	
36	30	CIP	141	Discharge from Federal Avenue Pump Station	
50	50	CII	141	Discharge from Federal Avenue Fump Station	
37	15'X10'	RCP	120	Sippo Avenue Pump Station	
38	24	CIP	5	Discharge from Sippo Avenue Pump Station	
39	24	CIP	10	Discharge from Sippo Avenue Pump Station	
40	24	CIP	20	Discharge from Sippo Avenue Pump Station	
41	6'X6'	RCP	87	Gravity Arch Avenue Pump Station	
42	6'X6'	RCP	87	Gravity Arch Avenue Pump Station	
43	24	CIP	85	Discharge from Arch Avenue Pump Station	
44	24	CIP	85	Discharge from Arch Avenue Pump Station	
45	24	CIP	85	Discharge from Arch Avenue Pump Station	
46	48	RCP	90	Gravity Conduit through levee	
46b	48	СМР	317	Gravity Conduit MH upstream of Levee	
47	24	DIP	460	Sanitary Sinhan Conduit Prookfield Intercentor	
47 48	14	DIP	460	Sanitary Siphon-Conduit-Brookfield Interceptor Sanitary Siphon-Conduit-Brookfield Interceptor	
		DIP	460		
49	20	DIF	400	Sanitary Siphon-Conduit-Brookfield Interceptor	
50	18	DIP	460	Sanitary Siphon-Conduit-Wooster Trunk	
51	10	DIP	460	Sanitary Siphon-Conduit-Wooster Trunk	
52	15	DIP	460	Sanitary Siphon-Conduit-Wooster Trunk	
53	8	VCP	450	Sanitary Siphon-Conduit-Tuscarawas River	
54	10	VCP	450	Sanitary Siphon-Conduit-Tuscarawas River	

HUNTINGTON DISTRICT U.S. ARMY CORPS OF ENGINEERS CONTRACT NO. W91237-09-P-0133

CCTV AND LASER PROFILE INSPECTION SUMMARY

PIPES UNDER LEVEES

PIPE NO: Brookfield Siphon #47 PIPE SIZE: 24" LENGTH INSPECTED: 400ft

PROJECT: Massillon Levee TYPE: DIP INSPECTION DATE: 10/27/09

OVERALL CONDITION: NASSCO Grade 3: Moderate defects that will continue to deteriorate

GENERAL INSPECTION FINDING: Sheets of the liner coming off in several areas. Some corrosion noted in areas where coating was missing. No gate valves on inlet or outlet. Pipe slopes up on constant grade from inlet to outlet.

MAJOR DEFECTS

Brookfield Siphon 24"- Outlet			
Feet Observation/Defect			
10ft	Corroded joint at crown		
28ft	Approx. 1" joint separation at 7 o'clock, Corroded joint in crown		
45.6ft	Tear in lining at approx. 4o'clock		
78.7ft	Lining peeling away from pipe walls at haunches		
99ft	Rust coming from joint at crown		
134.7ft	Rusting of joint at crown		
146.8ft	Large piece of lining detached from pipe wall		
170.5ft	Minor joint corrosion at crown		
200.7ft	Lining peeling away from pipe wall along joint		
241.7ft	Minor joint separation at approx. 4 o'clock		
273.6ft	Lining peeling away from pipe walls at invert		
277.1ft	Corrosion of joint/ small tear in lining		
330.5ft	Minor joint separation >1/2"		



Levee Embankments

For use during Initial and Continuing Eligibility Inspections of levee systems

Rated Item	Rating	Rating Guidelines	Location/ Remarks/ Recommendations	
11. Culverts/ Discharge Pipes ¹ (This item includes both concrete and		There are no breaks, holes, cracks in the discharge pipes/ culverts that would result in significant water leakage. The pipe shape is still essentially circular. All joints appear to be closed and the soil tight. Corrugated metal pipes, if present, are in good condition with 100% of the original coating still in place (either asphalt or galvanizing) or have been relined with appropriate material, which is still in good condition. Condition of pipes has been verified using television camera video taping or visual inspection methods within the past five years, and the report for every pipe is available for review by the inspector.		
corrugated metal pipes.)		There are a small number of corrosion pinholes or cracks that could leak water and need to be repaired, but the entire length of pipe is still structurally sound and is not in danger of collapsing. Pipe shape may be ovalized in some locations but does not appear to be approaching a curvature reversal. A limited number of joints may have opened and soil loss may be beginning. Any open joints should be repaired prior to the next inspection. Corrugated metal pipes, if present, may be showing corrosion and pinholes but there are no areas with total section loss. Condition of pipes has been verified using television camera video taping or visual inspection methods within the past five years, and the report for every pipe is available for review by the inspector.		
		Culvert has deterioration and/or has significant leakage; it is in danger of collapsing or as already begun to collapse. Corrugated metal pipes have suffered 100% section loss in the invert. HOWEVER: Even if pipes appear to be in good condition, as judged by an external visual inspection, an Unacceptable Rating will be assigned if the condition of pipes has not been verified using television camera video taping or visual inspection methods within the past five years, and reports for all pipes are not available for review by the inspector. N/A There are no discharge pipes/ culverts.		


Key: A = Acceptable. M = Minimally Acceptable; Maintenance is required. U = Unacceptable. N/A = Not Applicable. FDR = Flood Damage Reduction



¹ The decision on whether or not USACE inspectors should enter a pipe to perform a detailed inspection must be made at the USACE District level. This decision should be made in conjunction with the District Safety Office, as pipes may be considered confined spaces. This decision should consider the age of the pipe, the diameter of the pipe, the apparent condition of the pipe, and the length of the pipe. If a pipe is entered for the purposes of inspection, the inspector should record observations with a video camera in order that the condition of the entire pipe, including all joints, can later be assessed. Additionally, the video record provides a baseline to which future inspections can be compared.

INSPECTION SETUP === N: PRO NO. W91237-09-P-0133 SIPHON *Pipe video inspected from outlet to inlet Brookfield Siphon-24" outlet









































Massillon, Ohio Brookfield Sanitary Sewer Siphon Pipe #48, 14-inch DIP

	Pipes Inspected, Massillon Levee				
Pipes	Size (Inches)	Material	Length (Feet)	Location	
23	18	RCP	103	West of RR with Flap Gate	
24	12	RCP?	175	Could not locate/unknown/does not exist	
25	42	RCP	95	Culvert through West Bank Levee opposite of Croose Avenue	
26	66	RCP	93	Culvert through East Bank Levee near control weir	
27	42	RCP	360	At inlet to siphon control weir	
28	48	RCP	97	James Avenue Pump Station Gravity Outlet	
29	30	CIP	100	Discharge from James Avenue Pump Station	
30	30	CIP	100	Discharge from James Avenue Pump Station	
31	30	CIP	100	Discharge from James Avenue Pump Station	
32	60	RCP	135	Federal Avenue Pump Station Outlet	
33	60	RCP	135	Federal Avenue Pump Station Outlet	
34	30	CIP	141	Discharge from Federal Avenue Pump Station	
35	30	CIP	141	Discharge from Federal Avenue Pump Station	
36	30	CIP	141	Discharge from Federal Avenue Pump Station	
50	50	CII	141	Discharge from Federal Avenue Fump Station	
37	15'X10'	RCB	120	Sippo Creek Pump Station	
38	24	CIP	5	Discharge from Sippo Creek Pump Station	
39	24	CIP	10	Discharge from Sippo Creek Pump Station	
40	24	CIP	20	Discharge from Sippo Creek Pump Station	
41	6'X6'	RCB	87	Gravity Arch Avenue Pump Station	
42	6'X6'	RCB	87	Gravity Arch Avenue Pump Station	
43	24	CIP	85	Discharge from Arch Avenue Pump Station	
44	24	CIP	85	Discharge from Arch Avenue Pump Station	
45	24	CIP	85	Discharge from Arch Avenue Pump Station	
46	48	RCP	90	Gravity Conduit through levee	
46b	48	СМР	317	Gravity Conduit MH upstream of Levee	
4.7	2.4	DID	460		
47	24	DIP	460	Sanitary Siphon-Conduit-Brookfield Interceptor	
48	14	DIP	460	Sanitary Siphon-Conduit-Brookfield Interceptor	
49	20	DIP	460	Sanitary Siphon-Conduit-Brookfield Interceptor	
50	18	DIP	460	Sanitary Siphon-Conduit-Wooster Trunk	
51	10	DIP	460	Sanitary Siphon-Conduit-Wooster Trunk	
52	15	DIP	460	Sanitary Siphon-Conduit-Wooster Trunk	
-			155	The second secon	
53	8	VCP	450	Sanitary Siphon-Conduit-Tuscarawas River	
54	10	VCP	450	Sanitary Siphon-Conduit-Tuscarawas River	

HUNTINGTON DISTRICT

U.S. ARMY CORPS OF ENGINEERS

CONTRACT NO. W91237-09-P-0133

CCTV AND LASER PROFILE INSPECTION SUMMARY

PIPES UNDER LEVEES

PIPE NO: Brookfield Siphon #48 PIPE SIZE: 14" LENGTH INSPECTED: 93ft

PROJECT: Massillon Levee TYPE: DIP INSPECTION DATE: 11/09/09


OVERALL CONDITION: NASSCO Grade 3: Moderate defects that will continue to deteriorate

GENERAL INSPECTION FINDING: Large sections of protective coating coming off in several areas.

No gate valves on inlet or outlet. Pipe slopes up on constant grade from inlet to outlet.

MAJOR DEFECTS

Brookfield Siphon 14" – Outlet		
Feet	Remarks/Defects	
58ft	Large sections of protective coating coming off	
75ft	Protective coating coming off	
78ft	Protective coating coming off	
93ft	Protective coating coming off	
93ft	Debris level to high to continue, inspection	
	discontinued.	



Levee Embankments


For use during Initial and Continuing Eligibility Inspections of levee systems

Rated Item	Rating	Rating Guidelines	Location/ Remarks/ Recommendations	
11. Culverts/ Discharge Pipes ¹ (This item includes both concrete and		There are no breaks, holes, cracks in the discharge pipes/ culverts that would result in significant water leakage. The pipe shape is still essentially circular. All joints appear to be closed and the soil tight. Corrugated metal pipes, if present, are in good condition with 100% of the original coating still in place (either asphalt or galvanizing) or have been relined with appropriate material, which is still in good condition. Condition of pipes has been verified using television camera video taping or visual inspection methods within the past five years, and the report for every pipe is available for review by the inspector.		
corrugated metal pipes.)		There are a small number of corrosion pinholes or cracks that could leak water and need to be repaired, but the entire length of pipe is still structurally sound and is not in danger of collapsing. Pipe shape may be ovalized in some locations but does not appear to be approaching a curvature reversal. A limited number of joints may have opened and soil loss may be beginning. Any open joints should be repaired prior to the next inspection. Corrugated metal pipes, if present, may be showing corrosion and pinholes but there are no areas with total section loss. Condition of pipes has been verified using television camera video taping or visual inspection methods within the past five years, and the report for every pipe is available for review by the inspector.		
		Culvert has deterioration and/or has significant leakage; it is in danger of collapsing or as already begun to collapse. Corrugated metal pipes have suffered 100% section loss in the invert. HOWEVER: Even if pipes appear to be in good condition, as judged by an external visual inspection, an Unacceptable Rating will be assigned if the condition of pipes has not been verified using television camera video taping or visual inspection methods within the past five years, and reports for all pipes are not available for review by the inspector. N/A There are no discharge pipes/ culverts.		
Van A = A acceptable				

Key: A = Acceptable. M = Minimally Acceptable; Maintenance is required. U = Unacceptable. N/A = Not Applicable. FDR = Flood Damage Reduction



¹ The decision on whether or not USACE inspectors should enter a pipe to perform a detailed inspection must be made at the USACE District level. This decision should be made in conjunction with the District Safety Office, as pipes may be considered confined spaces. This decision should consider the age of the pipe, the diameter of the pipe, the apparent condition of the pipe, and the length of the pipe. If a pipe is entered for the purposes of inspection, the inspector should record observations with a video camera in order that the condition of the entire pipe, including all joints, can later be assessed. Additionally, the video record provides a baseline to which future inspections can be compared.





















Massillon, Ohio Brookfield Sanitary Sewer Siphon Pipe #49, 20-inch DIP

Pipes Inspected, Massillon Levee				
Size (Inches)	Material	Length (Feet)	Location	
18	RCP	103	West of RR with Flap Gate	
12	RCP?	175	Could not locate/unknown/does not exist	
42	RCP	95	Culvert through West Bank Levee opposite of Croose Avenue	
66	RCP	93	Culvert through East Bank Levee near control weir	
42	RCP	360	At inlet to siphon control weir	
			James Avenue Pump Station Gravity Outlet	
			Discharge from James Avenue Pump Station	
			Discharge from James Avenue Pump Station	
30	CIP	100	Discharge from James Avenue Pump Station	
60	RCP	135	Federal Avenue Pump Station Outlet	
			Federal Avenue Pump Station Outlet	
			Discharge from Federal Avenue Pump Station	
			Discharge from Federal Avenue Pump Station	
			Discharge from Federal Avenue Pump Station	
50	CII	141	Discharge from Federal Avenue Fump Station	
15'X10'	RCB	120	Sippo Creek Pump Station	
24	CIP	5	Discharge from Sippo Creek Pump Station	
24	CIP	10	Discharge from Sippo Creek Pump Station	
24	CIP	20	Discharge from Sippo Creek Pump Station	
6'X6'	RCB	87	Gravity Arch Avenue Pump Station	
6'X6'	RCB	87	Gravity Arch Avenue Pump Station	
24	CIP	85	Discharge from Arch Avenue Pump Station	
24	CIP	85	Discharge from Arch Avenue Pump Station	
24	CIP	85	Discharge from Arch Avenue Pump Station	
48	RCP	90	Gravity Conduit through levee	
48	СМР	317	Gravity Conduit MH upstream of Levee	
			Sanitary Siphon-Conduit-Brookfield Interceptor	
			Sanitary Siphon-Conduit-Brookfield Interceptor	
20	DIP	460	Sanitary Siphon-Conduit-Brookfield Interceptor	
18	DIP	460	Sanitary Siphon-Conduit-Wooster Trunk	
			Sanitary Siphon-Conduit-Wooster Trunk Sanitary Siphon-Conduit-Wooster Trunk	
			Sanitary Siphon-Conduit-Wooster Trunk	
15		T-00	Santary Sipriori Conduit Woodter Hullik	
Ω	VCP	450	Sanitary Siphon-Conduit-Tuscarawas River	
			Sanitary Siphon-Conduit-Tuscarawas River	
	12 42 66 42 48 30 30 30 30 30 30 30 30 30 30	18 RCP 12 RCP? 42 RCP 66 RCP 42 RCP 48 RCP 30 CIP 48 RCP 60 RCP 60 RCP 30 CIP 30 CIP 30 CIP 30 CIP 48 RCB 24 CIP 25 CIP 26 CIP 27 CIP 28 CIP 29 CIP 29 CIP 20 CIP 20 CIP 20 CIP 20 CIP 21 CIP 22 CIP 24 CIP 25 CIP 26 CIP 27 CIP 28 CIP 29 CIP 29 CIP 20 CIP 20 CIP 20 CIP 21 CIP 22 CIP 24 CIP 25 CIP 26 CIP 27 CIP 28 CIP 29 CIP 29 CIP 20 CIP 20 CIP 20 CIP 20 CIP 21 CIP 21 CIP 22 CIP 23 CIP 24 CIP 25 CIP 26 CIP 27 CIP 28 CIP 29 CIP 20 CIP 20 CIP 20 CIP 20 CIP 21 CIP 21 CIP 22 CIP 23 CIP 24 CIP 25 CIP 26 CIP 27 CIP 28 CIP 29 CIP 29 CIP 20 CIP 20 CIP 20 CIP 20 CIP 20 CIP 21 CIP 21 CIP 22 CIP 24 CIP 25 CIP 26 CIP 27 CIP 28 CIP 29 CIP 20 CIP 20 CIP 20 CIP 20 CIP 20 CIP 20 CIP 21 CIP 22 CIP 24 CIP 25 CIP 26 CIP 27 CIP 28 CIP 2	Size (Inches) Material Length (Feet) 18 RCP 103 12 RCP? 175 42 RCP 95 66 RCP 93 42 RCP 360 48 RCP 97 30 CIP 100 30 CIP 100 30 CIP 100 60 RCP 135 60 RCP 135 30 CIP 141 20 12P 141 15'X10' RCB 120 24 CIP 5 24 CIP 20 6'X6' RCB 87 6'X6' RCB 87 24 CIP 85	

HUNTINGTON DISTRICT U.S. ARMY CORPS OF ENGINEERS CONTRACT NO. W91237-09-P-0133

CCTV AND LASER PROFILE INSPECTION SUMMARY

PIPES UNDER LEVEES

PIPE NO: Brookfield Siphon #49 PIPE SIZE: 20" LENGTH INSPECTED: 216ft

PROJECT: Massillon Levee TYPE: DIP INSPECTION DATE: 11/09/09

OVERALL CONDITION: NASSCO Grade 3: Moderate defects that will continue to deteriorate

GENERAL INSPECTION FINDING: Minor rust at joints, large sections of protective coating coming off in several areas. Not gate valves on inlet or outlet. Pipe slopes up on constant grade from inlet to outlet.

MAJOR DEFECTS

Brookfield Siphon 20" - Outlet			
Feet	Observation/Defect		
8.1ft	Minor rusting of joint at crown		
37.9ft	Lining missing from pipe walls		
58.7ft	Lining peeling away from invert of pipe		
94.9ft	Small piece of lining starting to peel away from		
	right wall		
126.3ft	3ft Large section of damaged lining		
165.3ft	Lining peeling from left haunch		
216.9ft	Pipe becomes full of debris		

*Inspected from outlet to inlet



Levee Embankments

For use during Initial and Continuing Eligibility Inspections of levee systems


Rated Item	Rating	Rating Guidelines	Location/ Remarks/ Recommendations
11. Culverts/ Discharge Pipes¹ (This item includes both concrete and		There are no breaks, holes, cracks in the discharge pipes/cul water leakage. The pipe shape is still essentially circular. A soil tight. Corrugated metal pipes, if present, are in good cor coating still in place (either asphalt or galvanizing) or have b which is still in good condition. Condition of pipes has been video taping or visual inspection methods within the past fiv is available for review by the inspector.	l joints appear to be closed and the dition with 100% of the original sen relined with appropriate material, verified using television camera
corrugated metal pipes.)		There are a small number of corrosion pinholes or cracks that repaired, but the entire length of pipe is still structurally some Pipe shape may be ovalized in some locations but does not a reversal. A limited number of joints may have opened and s joints should be repaired prior to the next inspection. Corrug showing corrosion and pinholes but there are no areas with that been verified using television camera video taping or visions past five years, and the report for every pipe is available for the same content of the s	d and is not in danger of collapsing. Spear to be approaching a curvature soil loss may be beginning. Any open ated metal pipes, if present, may be stal section loss. Condition of pipes at inspection methods within the
		Culvert has deterioration and/or has significant leakage; it is begun to collapse. Corrugated metal pipes have suffered 100 HOWEVER: Even if pipes appear to be in good condition, a inspection, an Unacceptable Rating will be assigned if the cousing television camera video taping or visual inspection me reports for all pipes are not available for review by the inspection.	% section loss in the invert. judged by an external visual ndition of pipes has not been verified hods within the past five years, and
		/A There are no discharge pipes/ culverts.	

Key: A = Acceptable. M = Minimally Acceptable; Maintenance is required. U = Unacceptable. N/A = Not Applicable. FDR = Flood Damage Reduction



¹ The decision on whether or not USACE inspectors should enter a pipe to perform a detailed inspection must be made at the USACE District level. This decision should be made in conjunction with the District Safety Office, as pipes may be considered confined spaces. This decision should consider the age of the pipe, the diameter of the pipe, the apparent condition of the pipe, and the length of the pipe. If a pipe is entered for the purposes of inspection, the inspector should record observations with a video camera in order that the condition of the entire pipe, including all joints, can later be assessed. Additionally, the video record provides a baseline to which future inspections can be compared.




















Massillon, Ohio Wooster Siphons Pipe #50, 51, 52

Gate valve in pipe 51 and 52 were frozen mid way, pipes could not be inspected.

			Pipes Inspected, Ma	assillon Levee	
Pipes	Size (Inches)	Material	Length (Feet)	Location	
23	18	RCP	103	West of RR with Flap Gate	
24	12	RCP?	175	Could not locate/unknown/does not exist	
25	42	RCP	95	Culvert through West Bank Levee opposite of Croose Avenue	
26	66	RCP	93	Culvert through East Bank Levee near control weir	
27	42	RCP	360	At inlet to siphon control weir	
28	48	RCP	97	James Avenue Pump Station Gravity Outlet	
29	30	CIP	100	Discharge from James Avenue Pump Station	
30	30	CIP	100	Discharge from James Avenue Pump Station	
31	30	CIP	100	Discharge from James Avenue Pump Station	
32	60	RCP	135	Federal Avenue Pump Station Outlet	
33	60	RCP	135	Federal Avenue Pump Station Outlet	
34	30	CIP	141	Discharge from Federal Avenue Pump Station	
35	30	CIP	141	Discharge from Federal Avenue Pump Station	
36	30	CIP	141	Discharge from Federal Avenue Pump Station	
37	15'X10'	RCB	120	Sippo Creek Pump Station	
38	24	CIP	5	Discharge from Sippo Creek Pump Station	
39	24	CIP	10	Discharge from Sippo Creek Pump Station	
40	24	CIP	20	Discharge from Sippo Creek Pump Station	
41	6'X6'	RCB	87	Gravity Arch Avenue Pump Station	
42	6'X6'	RCB	87	Gravity Arch Avenue Pump Station	
43	24	CIP	85	Discharge from Arch Avenue Pump Station	
44	24	CIP	85	Discharge from Arch Avenue Pump Station	
45	24	CIP	85	Discharge from Arch Avenue Pump Station	
46	48	RCP	90	Gravity Conduit through levee	
46b	48	СМР	317	Gravity Conduit MH upstream of Levee	
47	24	DIP	460	Sanitary Siphon-Conduit-Brookfield Interceptor	
48	14	DIP	460	Sanitary Siphon-Conduit-Brookfield Interceptor	
49	20	DIP	460	Sanitary Siphon-Conduit-Brookfield Interceptor	
50	18	DIP	460	Sanitary Siphon-Conduit-Wooster Trunk	
51	10	DIP	460	Sanitary Siphon-Conduit-Wooster Trunk (Could not be inspected)	
52	15	DIP	460	Sanitary Siphon-Conduit-Wooster Trunk (Could not be inspected)	
53	8	VCP	450	Sanitary Siphon-Conduit-Tuscarawas River	
54	10	VCP	450	Sanitary Siphon-Conduit-Tuscarawas River	









Massillon, Ohio Wooster Sanitary Sewer Siphons Pipe #50, 18" DIP

			Pipes Inspected, Ma	assillon Levee	
Pipes	Size (Inches)	Material	Length (Feet)	Location	
23	18	RCP	103	West of RR with Flap Gate	
24	12	RCP?	175	Could not locate/unknown/does not exist	
25	42	RCP	95	Culvert through West Bank Levee opposite of Croose Avenue	
26	66	RCP	93	Culvert through East Bank Levee near control weir	
27	42	RCP	360	At inlet to siphon control weir	
28	48	RCP	97	James Avenue Pump Station Gravity Outlet	
29	30	CIP	100	Discharge from James Avenue Pump Station	
30	30	CIP	100	Discharge from James Avenue Pump Station	
31	30	CIP	100	Discharge from James Avenue Pump Station	
32	60	RCP	135	Federal Avenue Pump Station Outlet	
33	60	RCP	135	Federal Avenue Pump Station Outlet	
34	30	CIP	141	Discharge from Federal Avenue Pump Station	
35	30	CIP	141	Discharge from Federal Avenue Pump Station	
36	30	CIP	141	Discharge from Federal Avenue Pump Station	
37	15'X10'	RCB	120	Sippo Creek Pump Station	
38	24	CIP	5	Discharge from Sippo Creek Pump Station	
39	24	CIP	10	Discharge from Sippo Creek Pump Station	
40	24	CIP	20	Discharge from Sippo Creek Pump Station	
41	6'X6'	RCB	87	Gravity Arch Avenue Pump Station	
42	6'X6'	RCB	87	Gravity Arch Avenue Pump Station	
43	24	CIP	85	Discharge from Arch Avenue Pump Station	
44	24	CIP	85	Discharge from Arch Avenue Pump Station	
45	24	CIP	85	Discharge from Arch Avenue Pump Station	
46	48	RCP	90	Gravity Conduit through levee	
46b	48	СМР	317	Gravity Conduit MH upstream of Levee	
47	24	DIP	460	Sanitary Siphon-Conduit-Brookfield Interceptor	
48	14	DIP	460	Sanitary Siphon-Conduit-Brookfield Interceptor	
49	20	DIP	460	Sanitary Siphon-Conduit-Brookfield Interceptor	
50	18	DIP	460	Sanitary Siphon-Conduit-Wooster Trunk	
51	10	DIP	460	Sanitary Siphon-Conduit-Wooster Trunk (Could not be inspected)	
52	15	DIP	460	Sanitary Siphon-Conduit-Wooster Trunk (Could not be inspected)	
53	8	VCP	450	Sanitary Siphon-Conduit-Tuscarawas River	
54	10	VCP	450	Sanitary Siphon-Conduit-Tuscarawas River	

HUNTINGTON DISTRICT U.S. ARMY CORPS OF ENGINEERS

CONTRACT NO. W91237-09-P-0133 CCTV AND LASER PROFILE INSPECTION SUMMARY

PIPES UNDER LEVEES

PIPE NO: Wooster Siphon #50 PIPE SIZE: 18" LENGTH INSPECTED: 108ft

PROJECT: Massillon Levee TYPE: DIP INSPECTION DATE: 11/11/09

OVERALL CONDITION: NASSCO Grade 4: Severe defects that will become grade 5 in the near

future.

GENERAL INSPECTION FINDING: Pipe is severely corroded above the waterline. Gate valve severely corroded. Was very difficult to move.

MAJOR DEFECTS

Wooster Siphon 18"- Outlet			
Feet	Observation/Defect		
2.0ft	Broken bell at crown		
3.5ft Severely corroded out gate valve			
3.5ft-108ft	Pipe above water line is severely corroded		
7.5ft Joint separation 1.75-inches			
20.0ft Joint separation approximately 1.75-inches			
108ft	Vertical offset at joint in crown viewable from 108		
	ft.		
108ft	Inspection discontinued		



Levee Embankments


For use during Initial and Continuing Eligibility Inspections of levee systems

Rated Item	Rating		Rating Guidelines	Location/ Remarks/ Recommendations
11. Culverts/ Discharge Pipes ¹ (This item includes both concrete and		A	There are no breaks, holes, cracks in the discharge pipes/ culverts that would result in significant water leakage. The pipe shape is still essentially circular. All joints appear to be closed and the soil tight. Corrugated metal pipes, if present, are in good condition with 100% of the original coating still in place (either asphalt or galvanizing) or have been relined with appropriate material, which is still in good condition. Condition of pipes has been verified using television camera video taping or visual inspection methods within the past five years, and the report for every pipe is available for review by the inspector.	
corrugated metal pipes.)		М	There are a small number of corrosion pinholes or cracks that could leak water and need to be repaired, but the entire length of pipe is still structurally sound and is not in danger of collapsing. Pipe shape may be ovalized in some locations but does not appear to be approaching a curvature reversal. A limited number of joints may have opened and soil loss may be beginning. Any open joints should be repaired prior to the next inspection. Corrugated metal pipes, if present, may be showing corrosion and pinholes but there are no areas with total section loss. Condition of pipes has been verified using television camera video taping or visual inspection methods within the past five years, and the report for every pipe is available for review by the inspector.	
		U	Culvert has deterioration and/or has significant leakage; it is in danger of collapsing or as already begun to collapse. Corrugated metal pipes have suffered 100% section loss in the invert. HOWEVER: Even if pipes appear to be in good condition, as judged by an external visual inspection, an Unacceptable Rating will be assigned if the condition of pipes has not been verified using television camera video taping or visual inspection methods within the past five years, and reports for all pipes are not available for review by the inspector.	
			There are no discharge pipes/ culverts.	

Key: A = Acceptable. M = Minimally Acceptable; Maintenance is required. U = Unacceptable. N/A = Not Applicable. FDR = Flood Damage Reduction



¹ The decision on whether or not USACE inspectors should enter a pipe to perform a detailed inspection must be made at the USACE District level. This decision should be made in conjunction with the District Safety Office, as pipes may be considered confined spaces. This decision should consider the age of the pipe, the diameter of the pipe, the apparent condition of the pipe, and the length of the pipe. If a pipe is entered for the purposes of inspection, the inspector should record observations with a video camera in order that the condition of the entire pipe, including all joints, can later be assessed. Additionally, the video record provides a baseline to which future inspections can be compared.



































Massillon, Ohio Wooster Siphons Pipe #51 and 52 10" and 15" DIP

Pipes could not be inspected due to the gate valves being froze mid way.

		Pipes Inspected, Ma	assilion Levee	
Size (Inches)	Material	Length (Feet)	Location	
18	RCP	103	West of RR with Flap Gate	
12	RCP?	175	Could not locate/unknown/does not exist	
42	RCP	95	Culvert through West Bank Levee opposite of Croose Avenue	
66	RCP	93	Culvert through East Bank Levee near control weir	
42	RCP	360	At inlet to siphon control weir	
			James Avenue Pump Station Gravity Outlet	
			Discharge from James Avenue Pump Station	
			Discharge from James Avenue Pump Station	
30	CIP	100	Discharge from James Avenue Pump Station	
60	RCP	125	Federal Avenue Pump Station Outlet	
			Federal Avenue Pump Station Outlet	
			Discharge from Federal Avenue Pump Station	
			Discharge from Federal Avenue Pump Station	
			Discharge from Federal Avenue Pump Station	
50	CII	141	Discharge from rederal Avenue Famp Station	
15'X10'	RCB	120	Sippo Creek Pump Station	
24	CIP	5	Discharge from Sippo Creek Pump Station	
24	CIP	10	Discharge from Sippo Creek Pump Station	
24	CIP	20	Discharge from Sippo Creek Pump Station	
6'X6'	RCB	87	Gravity Arch Avenue Pump Station	
6'X6'	RCB	87	Gravity Arch Avenue Pump Station	
24	CIP	85	Discharge from Arch Avenue Pump Station	
24	CIP	85	Discharge from Arch Avenue Pump Station	
24	CIP	85	Discharge from Arch Avenue Pump Station	
48	RCP	90	Gravity Conduit through levee	
48	СМР	317	Gravity Conduit MH upstream of Levee	
			Sanitary Siphon-Conduit-Brookfield Interceptor	
			Sanitary Siphon-Conduit-Brookfield Interceptor	
20	DIP	460	Sanitary Siphon-Conduit-Brookfield Interceptor	
18	DIP	460	Sanitary Siphon-Conduit-Wooster Trunk	
			Sanitary Siphon-Conduit-Wooster Trunk (Could not be inspected)	
			Sanitary Siphon-Conduit-Wooster Trunk (Could not be inspected)	
13	Pil	H00	paintary signore-conduit wooster trank (could not be inspected)	
Q	VCD	450	Sanitary Siphon-Conduit-Tuscarawas River	
			Sanitary Siphon-Conduit-Tuscarawas River Sanitary Siphon-Conduit-Tuscarawas River	
	12 42 66 42 48 30 30 30 30 60 60 60 30 30 30 30 45'X10' 24 24 24 24 24 24 24 24 24 24	18 RCP 12 RCP? 42 RCP 66 RCP 42 RCP 48 RCP 30 CIP 30 CIP 30 CIP 60 RCP 60 RCP 60 RCP 30 CIP 30 CIP 30 CIP 24 CIP 25 CIP 48 RCP 48 CMP 10 DIP 10 DIP 15 DIP	18 RCP 103 12 RCP? 175 42 RCP 95 66 RCP 93 42 RCP 360 48 RCP 97 30 CIP 100 30 CIP 100 30 CIP 100 60 RCP 135 60 RCP 135 30 CIP 141 30 CIP 141 30 CIP 141 31 CIP 141 32 CIP 141 34 CIP 141 55 CIP 100 66 RCB 120 66 RCB 120 67 RCB 120 67 RCB 120 67 RCB 87 67	

HUNTINGTON DISTRICT U.S. ARMY CORPS OF ENGINEERS CONTRACT NO. W91237-09-P-0133

CCTV AND LASER PROFILE INSPECTION SUMMARY

PIPES UNDER LEVEES

PIPE NO: Wooster Siphon #51-52 PIPE SIZE: 10-15" LENGTH INSPECTED: Oft

PROJECT: Massillon Levee TYPE: DIP INSPECTION DATE: 11/11/09

OVERALL CONDITION: NASSCO Grade 5: Gate valves frozen

GENERAL INSPECTION FINDING: Gate valves were frozen, pipe 50 showed signs of severe

corrosion above water line.

MAJOR DEFECTS

Wooster Siphon Pipe No. 51 and 52				
Feet	Observation/Defect			
0.0	Gate valves frozen, could not be moved			



Pump Stations

For use during Initial and Continuing Eligibility Inspections of pump stations

Intake and Discharge Pipelines A Intake and discharge pipelines have no corrosion and paint is intact, except for minor touch up regulated. Pipelines A Intake and discharge pipelines have minor corrosion and require bolts to be tightened. U Intake and discharge pipelines have minor corrosion and require bolts to be tightened. U Intake and discharge pipelines have major corrosion and require bolts to be tightened. U Intake and discharge pipelines have major corrosion and requires bolts to be tightened. Cates operators are in good working condition and are properly maintained. Still is free of sediment and other obstructions. Gates and lifera have been maintained and are fee of corrosion. Documentation provided during the impection. U Gates do not open or close and for operators have been damaged or have minor corrosion, and open and close with resistance or binding. Leakage quantity is controllable, but maintenance is required. Still is free of sediment and other obstructions. U Gates do not open or close and for operators do not function. Gate, stem, lifter and/or guides may be damaged or have major corrosion. NA There are no chance's idea gates. A Gates' valves are missing and the property of the p	Rated Item	Rating		Rating Guidelines	Location/ Remarks/ Recommendations
Coupling with anchors have minor leakage, corrosion and require bolts to be tightened.	Discharge		A	required. Pipe couplings and anchors have no leakage or corrosion.	
18. Shuce/ Slide Gates open and close freely to a tight seal or minor leakage. Gate open and close working Gates open and close freely to a tight seal or minor leakage. Gate operators are in good working Gates open and close freely to a tight seal or minor leakage. Gate operators are in good working condition and are properly maintained. Sill is free of sediment and other obstructions. Gates and/or operators have been damaged or have minor corrosion, and open and close with resistance or binding. Leakage quantity is controllable, but maintenance is required. Sill is free of sediment and other obstructions. U Gates do not open or close and/or operators do not function. Gate, stem, lifter and/or guides may be damaged or have major corrosion. N/A There are no shuce's lide gates. A Gates/ valves open and close easily with minimal leakage, have no corrosion damage, and have been exercised and lubricated as required. Gates/ valves will not fully open or close because of obstructions that can be easily removed, or have minor corrosion damage that requires maintenance. Gates/ valves are missing, have been damaged, or have deteriorated to the point that they need to be replaced. V.A There are no gases on discharge lines from pump station. Cranes operational and have been impected and load tested in accordance with applicable standards within the last year. Documentation is on hand. Cranes have not been impected or operationally tested within the past year, or there are visible signs of corrosion, oil leakage, etc. requiring maintenance. Cranes are not operational, and this may prevent the pump station from functioning as required. Not documentation available on cranes. All metal parts are protected from corrosion damage and show no rust, damage, or deterioration that would cause a safety concern. M Corrosion seen on metallic parts appears to be maintainable. Metallic parts are severely corroded and require replacement to prevent failure, equipment damage, or safety issues.	Pipelines		М		
Gates 1 A condition and are properly maintained. Still is free of sediment and other obstructions. Gates and lifters have been maintained and are free of corrosion. Documentation provided during the inspection. Gates and/or operators have been damaged or have minor corrosion, and open and close with resistance or binding. Leakage quantity is controllable, but maintenance is required. Still is free of sediment and other obstructions. Use damaged or have major corrosion. N/A There are no shuice/ slide gates. 19. Flap Gates/ Flap Valves/ Pinch Valves/ Pinch Valves/ Pinch Valves A Gates/ valves open and close easily with minimal leakage, have no corrosion damage, and have been exercised and lubuicated as required. M Gates/ valves will not fully open or close because of obstructions that can be easily removed, or have minor corrosion damage that requires maintenance. U Gates/ valves are missing, have been damaged, or have deteriorated to the point that they need to be replaced. N/A There are no gases on discharge lines from pump station. Cames are not operational, and have been impected and load tested in accordance with applicable standards within the last year. Documentation is on hand. M Cames are not operational, and this may prevent the pump station from functioning as required. No documentation available on cranes. N/A There are no cranes. All metal parts are protected from corrosion damage and show no rust, damage, or deterioration that would cause a safety concem. All metal parts are protected from corrosion damage and show no rust, damage, or deterioration that would cause a safety concem. All metal parts are protected from corrosion damage and show no rust, damage, or deterioration that would cause a safety concem. All metal parts are protected from corrosion damage and show no rust, damage, or deterioration that would cause a safety concem. All metal parts are protected from corrosion damage and show no rust, damage, or deterioration that would cause a safety concem. A corrosion seen on			U		
M resistance or binding. Leakage quantity is controllable, but maintenance is required. Sill is free of sediment and other obstructions. U Gates do not open or close and/or operators do not function. Gate, stem, lifter and/or guides may be damaged or have major corrosion. N/A There are no sluice/ slide gates. 19. Flap Calves/ Flap Valves/ Pinch Valves ² A Gates/ valves open and close easily with minimal leakage, have no corrosion damage, and have been exercised and lubricated as required. M Gates/ valves will not fully open or close because of obstructions that can be easily removed, or have minor corrosion damage that requires maintenance. U Gates/ valves are missing, have been damaged, or have deteriorated to the point that they need to be replaced. N/A There are no gates on discharge lines from pump station. Cranes are missing and been inspected and load tested in accordance with applicable standards within the last year. Documentation is on hand. M Granes have not been inspected or operationally tested within the past year, or there are visible signs of corrosion, oil leakage, etc, requiring maintenance. U Cranes are not operational, and this may prevent the pump station from functioning as required. No documentation available on cranes. N/A There are no cranes. A All metal parts are protected from corrosion damage and show no rust, damage, or deterioration that would cause a safety concern. (Equipment, All metal parts are protected from corrosion damage and show no rust, damage, or deterioration that would cause a safety concern. We detailic parts are severely corroded and require replacement to prevent failure, equipment damage, or safety issues.			A	condition and are properly maintained. Sill is free of sediment and other obstructions. Gates and lifters have been maintained and are free of corrosion. Documentation provided during the	
De damaged or have major corrosion.			М	resistance or binding. Leakage quantity is controllable, but maintenance is required. Sill is free of sediment and other obstructions.	
Pinch Valves A Gates/ valves open and close easily with minimal leakage, have no corrosion damage, and have been exercised and lubricated as required. M Gates/ valves will not fully open or close because of obstructions that can be easily removed, or have minor corrosion damage that requires maintenance. U Gates/ valves are missing, have been damaged, or have deteriorated to the point that they need to be replaced. N/A There are no gates on discharge lines from pump station. Cranes 2 A Cranes operational and have been inspected and load tested in accordance with applicable standards within the last year. Documentation is on hand. M Cranes have not been inspected or operationally tested within the past year, or there are visible signs of corrosion, oil leakage, etc, requiring maintenance. Cranes are not operational, and this may prevent the pump station from functioning as required. No documentation available on cranes. N/A There are no cranes. 21. Other Metallic Items (Equipment, Ladders, Platform M Corrosion seen on metallic parts appears to be maintainable. Metallic parts are severely corroded and require replacement to prevent failure, equipment damage, or safety issues.				be damaged or have major corrosion.	
Flap Valves/ Pinch Valves ² Been exercised and lubricated as required. Gates/ valves will not fully open or close because of obstructions that can be easily removed, or have minor correction damage that requires maintenance. U Gates/ valves are missing, have been damaged, or have deteriorated to the point that they need to be replaced. N/A There are no gates on discharge lines from pump station. Cranes operational and have been inspected and load tested in accordance with applicable standards within the last year. Documentation is on hand. M Cranes have not been inspected or operationally tested within the past year, or there are visible signs of corrosion, oil leakage, etc, requiring maintenance. U Cranes are not operational, and this may prevent the pump station from functioning as required. No documentation available on cranes. N/A There are no cranes. A All metal parts are protected from corrosion damage and show no rust, damage, or deterioration that would cause a safety concern. Equipment, Ladders, Platform M Corrosion seen on metallic parts appears to be maintainable. U Metallic parts are severely corroded and require replacement to prevent failure, equipment damage, or safety issues.			N/A	There are no sluice/ slide gates.	
M have minor corrosion damage that requires maintenance			A		
replaced. N/A There are no gates on discharge lines from pump station. Cranes ² A Cranes operational and have been inspected and load tested in accordance with applicable standards within the last year. Documentation is on hand. M Cranes have not been inspected or operationally tested within the past year, or there are visible signs of corrosion, oil leakage, etc, requiring maintenance. Cranes are not operational, and this may prevent the pump station from functioning as required. No documentation available on cranes. N/A There are no cranes. All metal parts are protected from corrosion damage and show no rust, damage, or deterioration that would cause a safety concern. (Equipment, Ladders, Platform M Corrosion seen on metallic parts appears to be maintainable. Metallic parts are severely corroded and require replacement to prevent failure, equipment damage, or safety issues.	Pinch Valves ²	_	М		
20. Cranes A Cranes operational and have been inspected and load tested in accordance with applicable standards within the last year. Documentation is on hand. M Cranes have not been inspected or operationally tested within the past year, or there are visible signs of corrosion, oil leakage, etc, requiring maintenance. U Cranes are not operational, and this may prevent the pump station from functioning as required. No documentation available on cranes. N/A There are no cranes. 21. Other Metallic Items (Equipment, Equipment, M Corrosion seen on metallic parts appears to be maintainable. Ladders, Platform U Metallic parts are severely corroded and require replacement to prevent failure, equipment damage, or safety issues.			U		
standards within the last year. Documentation is on hand. M Cranes have not been inspected or operationally tested within the past year, or there are visible signs of corrosion, oil leakage, etc, requiring maintenance. U Cranes are not operational, and this may prevent the pump station from functioning as required. No documentation available on cranes. N/A There are no cranes. 21. Other Metallic Items (Equipment, Equipment, M Corrosion seen on metallic parts appears to be maintainable. Ladders, Platform M Metallic parts are severely corroded and require replacement to prevent failure, equipment damage, or safety issues.			N/A		
signs of corrosion, oil leakage, etc, requiring maintenance. U Cranes are not operational, and this may prevent the pump station from functioning as required. No documentation available on cranes. N/A There are no cranes. All metal parts are protected from corrosion damage and show no rust, damage, or deterioration that would cause a safety concern. (Equipment, Ladders, Platform M Corrosion seen on metallic parts appears to be maintainable. U Metallic parts are severely corroded and require replacement to prevent failure, equipment damage, or safety issues.	20. Cranes ²		A		
V No documentation available on cranes.			М		
21. Other Metallic Items (Equipment, Ladders, Platform A All metal parts are protected from corrosion damage and show no rust, damage, or deterioration that would cause a safety concern. M Corrosion seen on metallic parts appears to be maintainable. Ladders, Or safety issues.			U		
Items (Equipment, Ladders, Platform A that would cause a safety concern. M Corrosion seen on metallic parts appears to be maintainable. Metallic parts are severely corroded and require replacement to prevent failure, equipment damage, or safety issues.			N/A	There are no cranes.	
Ladders, Platform Metallic parts are severely corroded and require replacement to prevent failure, equipment damage, or safety issues.			A		
Platform U or safety issues.	(Equipment,		M	Corrosion seen on metallic parts appears to be maintainable.	
Anchors, etc) N/A There are no other significant metallic items.	Platform			or safety issues.	
	Anchors, etc)		N/A	There are no other significant metallic items.	


Key: A = Acceptable. M = Minimally Acceptable; Maintenance is required. U = Unacceptable. N/A = Not Applicable. FDR = Flood Damage Reduction

² Proper operation of this item must be demonstrated during the inspection.



¹ Proper operation of the gates (full open and closed) must be demonstrated during the inspection if no documentation is available. Be aware of both manual and electrical operators.

Massillon, Ohio Tuscarawas Sanitary Sewer Siphon Pipe #53 and 54



Material RCP RCP? RCP?	Pipes Inspected, Ma Length (Feet) 103	Location West of RR with Flap Gate	
RCP RCP?	103		
RCP?	103	West of RR with Flap Gate	
	475	process or the ment hap care	
RCP	175	Could not locate/unknown/does not exist	
	95	Culvert through West Bank Levee opposite of Croose Avenue	
RCP	93	Culvert through East Bank Levee near control weir	
RCP	360	At inlet to siphon control weir	
		James Avenue Pump Station Gravity Outlet	
		Discharge from James Avenue Pump Station	
		Discharge from James Avenue Pump Station	
CIP	100	Discharge from James Avenue Pump Station	
RCP	135	Federal Avenue Pump Station Outlet	
		Federal Avenue Pump Station Outlet	
		Discharge from Federal Avenue Pump Station	
		Discharge from Federal Avenue Pump Station	
		Discharge from Federal Avenue Pump Station	
CII	141	Discharge from rederal Avenue rump station	
RCB	120	Sippo Creek Pump Station	
CIP	5	Discharge from Sippo Creek Pump Station	
CIP	10	Discharge from Sippo Creek Pump Station	
CIP	20	Discharge from Sippo Creek Pump Station	
RCB	87	Gravity Arch Avenue Pump Station	
RCB	87	Gravity Arch Avenue Pump Station	
CIP	85	Discharge from Arch Avenue Pump Station	
CIP	85	Discharge from Arch Avenue Pump Station	
CIP	85	Discharge from Arch Avenue Pump Station	
RCP	90	Gravity Conduit through levee	
СМР	317	Gravity Conduit MH upstream of Levee	
		Sanitary Siphon-Conduit-Brookfield Interceptor	
		Sanitary Siphon-Conduit-Brookfield Interceptor	
DIP	460	Sanitary Siphon-Conduit-Brookfield Interceptor	
DIP	460	Sanitary Siphon-Conduit-Wooster Trunk	
		Sanitary Siphon-Conduit-Wooster Trunk (Could not be inspected)	
		Sanitary Siphon-Conduit-Wooster Trunk (Could not be inspected)	
DII	700	Sameary Sipriori Conduit Woodter Hunk (Codia not be inspected)	
VCP	450	Sanitary Siphon-Conduit-Tuscarawas River	
		Sanitary Siphon-Conduit-Tuscarawas River	
	RCP RCP CIP CIP RCP RCP CIP CIP	RCP 97 CIP 100 CIP 100 CIP 100 CIP 100 RCP 135 RCP 135 RCP 135 CIP 141 CIP 141 CIP 141 CIP 141 RCB 120 CIP 5 CIP 20 RCB 87 RCB 87 RCB 87 RCB 87 RCB 87 RCB 87 RCB 85 CIP 85 CIP 85 CIP 30 CIP 30 CIP 460 DIP 460	

Pump Stations

For use during Initial and Continuing Eligibility Inspections of pump stations


Intake and Discharge Pipelines A Intake and discharge pipelines have no corrosion and paint is intact, except for minor touch up regulated. Pipelines A Intake and discharge pipelines have minor corrosion and require bolts to be tightened. U Intake and discharge pipelines have minor corrosion and require bolts to be tightened. U Intake and discharge pipelines have major corrosion and require bolts to be tightened. U Intake and discharge pipelines have major corrosion and requires bolts to be tightened. Cates operators are in good working condition and are properly maintained. Still is free of sediment and other obstructions. Gates and lifera have been maintained and are fee of corrosion. Documentation provided during the impection. U Gates do not open or close and for operators have been damaged or have minor corrosion, and open and close with resistance or binding. Leakage quantity is controllable, but maintenance is required. Still is free of sediment and other obstructions. U Gates do not open or close and for operators do not function. Gate, stem, lifter and/or guides may be damaged or have major corrosion. NA There are no chance's idea gates. A Gates' valves are missing and the property of the p	Rated Item	Rating		Rating Guidelines	Location/ Remarks/ Recommendations
Coupling with anchors have minor leakage, corrosion and require bolts to be tightened.	Discharge		A	required. Pipe couplings and anchors have no leakage or corrosion.	
18. Shuce/ Slide Gates open and close freely to a tight seal or minor leakage. Gate open and close working Gates open and close freely to a tight seal or minor leakage. Gate operators are in good working Gates open and close freely to a tight seal or minor leakage. Gate operators are in good working condition and are properly maintained. Sill is free of sediment and other obstructions. Gates and/or operators have been damaged or have minor corrosion, and open and close with resistance or binding. Leakage quantity is controllable, but maintenance is required. Sill is free of sediment and other obstructions. U Gates do not open or close and/or operators do not function. Gate, stem, lifter and/or guides may be damaged or have major corrosion. N/A There are no shuce's lide gates. A Gates/ valves open and close easily with minimal leakage, have no corrosion damage, and have been exercised and lubricated as required. Gates/ valves will not fully open or close because of obstructions that can be easily removed, or have minor corrosion damage that requires maintenance. Gates/ valves are missing, have been damaged, or have deteriorated to the point that they need to be replaced. V.A There are no gases on discharge lines from pump station. Cranes operational and have been impected and load tested in accordance with applicable standards within the last year. Documentation is on hand. Cranes have not been impected or operationally tested within the past year, or there are visible signs of corrosion, oil leakage, etc. requiring maintenance. Cranes are not operational, and this may prevent the pump station from functioning as required. Not documentation available on cranes. All metal parts are protected from corrosion damage and show no rust, damage, or deterioration that would cause a safety concern. M Corrosion seen on metallic parts appears to be maintainable. Metallic parts are severely corroded and require replacement to prevent failure, equipment damage, or safety issues.	Pipelines		М		
Gates 1 A condition and are properly maintained. Still is free of sediment and other obstructions. Gates and lifters have been maintained and are free of corrosion. Documentation provided during the inspection. Gates and/or operators have been damaged or have minor corrosion, and open and close with resistance or binding. Leakage quantity is controllable, but maintenance is required. Still is free of sediment and other obstructions. Use damaged or have major corrosion. N/A There are no shuice/ slide gates. 19. Flap Gates/ Flap Valves/ Pinch Valves/ Pinch Valves/ Pinch Valves A Gates/ valves open and close easily with minimal leakage, have no corrosion damage, and have been exercised and lubuicated as required. M Gates/ valves will not fully open or close because of obstructions that can be easily removed, or have minor corrosion damage that requires maintenance. U Gates/ valves are missing, have been damaged, or have deteriorated to the point that they need to be replaced. N/A There are no gases on discharge lines from pump station. Cames are not operational, and have been impected and load tested in accordance with applicable standards within the last year. Documentation is on hand. M Cames are not operational, and this may prevent the pump station from functioning as required. No documentation available on cranes. N/A There are no cranes. All metal parts are protected from corrosion damage and show no rust, damage, or deterioration that would cause a safety concem. All metal parts are protected from corrosion damage and show no rust, damage, or deterioration that would cause a safety concem. All metal parts are protected from corrosion damage and show no rust, damage, or deterioration that would cause a safety concem. All metal parts are protected from corrosion damage and show no rust, damage, or deterioration that would cause a safety concem. All metal parts are protected from corrosion damage and show no rust, damage, or deterioration that would cause a safety concem. A corrosion seen on			U		
M resistance or binding. Leakage quantity is controllable, but maintenance is required. Sill is free of sediment and other obstructions. U Gates do not open or close and/or operators do not function. Gate, stem, lifter and/or guides may be damaged or have major corrosion. N/A There are no sluice/ slide gates. 19. Flap Calves/ Flap Valves/ Pinch Valves ² A Gates/ valves open and close easily with minimal leakage, have no corrosion damage, and have been exercised and lubricated as required. M Gates/ valves will not fully open or close because of obstructions that can be easily removed, or have minor corrosion damage that requires maintenance. U Gates/ valves are missing, have been damaged, or have deteriorated to the point that they need to be replaced. N/A There are no gates on discharge lines from pump station. Cranes are missing and been inspected and load tested in accordance with applicable standards within the last year. Documentation is on hand. M Granes have not been inspected or operationally tested within the past year, or there are visible signs of corrosion, oil leakage, etc, requiring maintenance. U Cranes are not operational, and this may prevent the pump station from functioning as required. No documentation available on cranes. N/A There are no cranes. A All metal parts are protected from corrosion damage and show no rust, damage, or deterioration that would cause a safety concern. (Equipment, All metal parts are protected from corrosion damage and show no rust, damage, or deterioration that would cause a safety concern. We detailic parts are severely corroded and require replacement to prevent failure, equipment damage, or safety issues.			A	condition and are properly maintained. Sill is free of sediment and other obstructions. Gates and lifters have been maintained and are free of corrosion. Documentation provided during the	
De damaged or have major corrosion.			М	resistance or binding. Leakage quantity is controllable, but maintenance is required. Sill is free of sediment and other obstructions.	
Pinch Valves A Gates/ valves open and close easily with minimal leakage, have no corrosion damage, and have been exercised and lubricated as required. M Gates/ valves will not fully open or close because of obstructions that can be easily removed, or have minor corrosion damage that requires maintenance. U Gates/ valves are missing, have been damaged, or have deteriorated to the point that they need to be replaced. N/A There are no gates on discharge lines from pump station. Cranes 2 A Cranes operational and have been inspected and load tested in accordance with applicable standards within the last year. Documentation is on hand. M Cranes have not been inspected or operationally tested within the past year, or there are visible signs of corrosion, oil leakage, etc, requiring maintenance. Cranes are not operational, and this may prevent the pump station from functioning as required. No documentation available on cranes. N/A There are no cranes. 21. Other Metallic Items (Equipment, Ladders, Platform M Corrosion seen on metallic parts appears to be maintainable. Metallic parts are severely corroded and require replacement to prevent failure, equipment damage, or safety issues.				be damaged or have major corrosion.	
Flap Valves/ Pinch Valves ² Been exercised and lubricated as required. Gates/ valves will not fully open or close because of obstructions that can be easily removed, or have minor correction damage that requires maintenance. U Gates/ valves are missing, have been damaged, or have deteriorated to the point that they need to be replaced. N/A There are no gates on discharge lines from pump station. Cranes operational and have been inspected and load tested in accordance with applicable standards within the last year. Documentation is on hand. M Cranes have not been inspected or operationally tested within the past year, or there are visible signs of corrosion, oil leakage, etc, requiring maintenance. U Cranes are not operational, and this may prevent the pump station from functioning as required. No documentation available on cranes. N/A There are no cranes. A All metal parts are protected from corrosion damage and show no rust, damage, or deterioration that would cause a safety concern. Equipment, Ladders, Platform M Corrosion seen on metallic parts appears to be maintainable. U Metallic parts are severely corroded and require replacement to prevent failure, equipment damage, or safety issues.			N/A	There are no sluice/ slide gates.	
M have minor corrosion damage that requires maintenance			A		
replaced. N/A There are no gates on discharge lines from pump station. Cranes ² A Cranes operational and have been inspected and load tested in accordance with applicable standards within the last year. Documentation is on hand. M Cranes have not been inspected or operationally tested within the past year, or there are visible signs of corrosion, oil leakage, etc, requiring maintenance. Cranes are not operational, and this may prevent the pump station from functioning as required. No documentation available on cranes. N/A There are no cranes. All metal parts are protected from corrosion damage and show no rust, damage, or deterioration that would cause a safety concern. (Equipment, Ladders, Platform M Corrosion seen on metallic parts appears to be maintainable. Metallic parts are severely corroded and require replacement to prevent failure, equipment damage, or safety issues.	Pinch Valves ²	_	М		
20. Cranes A Cranes operational and have been inspected and load tested in accordance with applicable standards within the last year. Documentation is on hand. M Cranes have not been inspected or operationally tested within the past year, or there are visible signs of corrosion, oil leakage, etc, requiring maintenance. U Cranes are not operational, and this may prevent the pump station from functioning as required. No documentation available on cranes. N/A There are no cranes. 21. Other Metallic Items (Equipment, Equipment, M Corrosion seen on metallic parts appears to be maintainable. Ladders, Platform U Metallic parts are severely corroded and require replacement to prevent failure, equipment damage, or safety issues.			U		
standards within the last year. Documentation is on hand. M Cranes have not been inspected or operationally tested within the past year, or there are visible signs of corrosion, oil leakage, etc, requiring maintenance. U Cranes are not operational, and this may prevent the pump station from functioning as required. No documentation available on cranes. N/A There are no cranes. 21. Other Metallic Items (Equipment, Equipment, M Corrosion seen on metallic parts appears to be maintainable. Ladders, Platform M Metallic parts are severely corroded and require replacement to prevent failure, equipment damage, or safety issues.			N/A		
signs of corrosion, oil leakage, etc, requiring maintenance. U Cranes are not operational, and this may prevent the pump station from functioning as required. No documentation available on cranes. N/A There are no cranes. All metal parts are protected from corrosion damage and show no rust, damage, or deterioration that would cause a safety concern. (Equipment, Ladders, Platform M Corrosion seen on metallic parts appears to be maintainable. U Metallic parts are severely corroded and require replacement to prevent failure, equipment damage, or safety issues.	20. Cranes ²		A		
V No documentation available on cranes.			М		
21. Other Metallic Items (Equipment, Ladders, Platform A All metal parts are protected from corrosion damage and show no rust, damage, or deterioration that would cause a safety concern. M Corrosion seen on metallic parts appears to be maintainable. Ladders, Or safety issues.			U		
Items (Equipment, Ladders, Platform A that would cause a safety concern. M Corrosion seen on metallic parts appears to be maintainable. Metallic parts are severely corroded and require replacement to prevent failure, equipment damage, or safety issues.			N/A	There are no cranes.	
Ladders, Platform Metallic parts are severely corroded and require replacement to prevent failure, equipment damage, or safety issues.			A		
Platform U or safety issues.	(Equipment,		M	Corrosion seen on metallic parts appears to be maintainable.	
Anchors, etc) N/A There are no other significant metallic items.	Platform			or safety issues.	
	Anchors, etc)		N/A	There are no other significant metallic items.	


Key: A = Acceptable. M = Minimally Acceptable; Maintenance is required. U = Unacceptable. N/A = Not Applicable. FDR = Flood Damage Reduction

² Proper operation of this item must be demonstrated during the inspection.




¹ Proper operation of the gates (full open and closed) must be demonstrated during the inspection if no documentation is available. Be aware of both manual and electrical operators.





































Massillon, Ohio Tuscarawas Sanitary Sewer Siphon Pipe #53, 8-inch VCP

HUNTINGTON DISTRICT

U.S. ARMY CORPS OF ENGINEERS

CONTRACT NO. W91237-09-P-0133

CCTV AND LASER PROFILE INSPECTION SUMMARY

PIPES UNDER LEVEES

PIPE NO: Tuscarawas Siphon #53 PIPE SIZE: 8" LENGTH INSPECTED: 5ft

PROJECT: Massillon Levee TYPE: VCP INSPECTION DATE: 11/11/09

OVERALL CONDITION: NASSCO Grade 4: Several defects that will become grade 5 in the near


future.


GENERAL INSPECTION FINDING: Gate valves broken and no longer in service at outlet, diversion board rotten out in inlet, ladders severely corroded/missing, severe corrosion at outlet, heavy debris, questionable severe offset joint at outlet.

MAJOR DEFECTS

Siphon Pipe No. 54						
Feet Observation/Defect						
2.0 Severe corrosion at outlet						







```
INSPECTION SETUP
         PROJ NO. W91237-09-P-0133
                         SIPHON
DNSCREEN:
B" DIP TUSCARAWAS SIPHON
          View from outlet end
```




```
INSPECTION SETUP
         : PROJ NO. W91237-09-P-0133
                          SIPHON
DNSCREEN:
B" DIP TUSCARAWAS SIPHON
              Severe offset joint at Tuscarawas Siphon 8" outlet
```







```
INSPECTION SETUP
         PROJ NO. W91237-09-P-0133
                        SIPHON
NSCREEN:
DIP TUSCARAWAS SIPHON
            Severe offset joint at Tuscarawas Siphon 8" outlet
```



Massillon, Ohio Tuscarawas Sanitary Sewer Siphon Pipe #54, 10-inch VCP

HUNTINGTON DISTRICT

U.S. ARMY CORPS OF ENGINEERS

CONTRACT NO. W91237-09-P-0133

CCTV AND LASER PROFILE INSPECTION SUMMARY

PIPES UNDER LEVEES

PIPE NO: Tuscarawas Siphon #54 PIPE SIZE: 10" LENGTH INSPECTED: 33ft

PROJECT: Massillon Levee TYPE: VCP INSPECTION DATE: 11/11/09


 ${\bf OVERALL\ CONDITION:\ NASSCO\ Grade\ 4:\ Several\ defects\ that\ will\ become\ grade\ 5\ in\ the\ near}$

future.

GENERAL INSPECTION FINDING: Gate valves broken and no longer in service at outlet, diversion board rotten out in inlet, ladders severely corroded/missing, several offset joints, joint materials sealant missing.

MAJOR DEFECTS

Siphon Pipe No. 54					
Feet	Observation/Defect				
2.0	Joint offset, possible crack in bell				
13.6	Several offset joints visible down grade				
15.0	Joint separation 0.91-inches				
18.3	Joint separation 1.26-inches				
18.3	Several offset joints visible down grade				
19.7	Offset joint in invert				
24.0	Pipe bends to the left/down river				
32.0	Grade begins to flatten out				
33.1	End inspection due to high water				





INSPECTION SETUP NO.W91237-09-P-0133 PROJ SIPHON LLON OH. ONSCREEN: 10" DIP TUSCARAWAS SIPHON

Tuscarawas Siphon Pipe #54 inlet











































Appendix A

Nassco PACP Coding
Condition Grading System

NASSCO'S PIPELINE ASSESSMENT & CERTIFICATION PROGRAM (PACP)©

Section 4—Continuous Defect Coding

"TRULY" 4-1
"Truly" continuous defects run
along the sewer without any
interruption for more than 3 feet.

Examples:
- Longitudinal Fractures

- Cracks

"REPEATED" 4-1 "Repeated" continuous defects occur at regular intervals along the sewer. These occur at pipe joints and include: -Encrustation -Open Joints -Circumferential Fractures

Section 5—Structural Defect Coding (Module 6A)

C CRACK 5-1

CL Longitudinal 5-2

CC Circumferential 5-2

CM Multiple 5-2

CS Spiral 5-2

F FRACTURE 5-7

FL Longitudinal 5-7

FC Circumferential 5-7

FM Multiple 5-7

FS Spiral 5-7

B BROKEN 5-15
BSV -Soil Visible Beyond Defect
BV V -Void Visible Beyond Defect

H HOLE 5-17

HSV -Soil Visible 5-17

Beyond Defect

HV V -Void Visible 5-17

Beyond Defect

D DEFORMED 5-19

DV Deformed 5-19

Vertically (brick)

DH Deformed 5-19

Horizontally (brick)

X COLLAPSE 5-23

XP Pipe Collapse 5-23

XB Brick Collapse 5-23

J JOINT 5-27

JO Joint Offset 5-27
(Displaced)

JS Joint Separated 5-27
(Open)

JA Joint Angular 5-27

 S SURFACE

 DAMAGE
 5-32

 SAV Aggregate
 Visible
 5-32

 SAVM -Mechanical
 5-33

 SAVC -Chemical Attack
 5-33

 SAVZ -Not Evident
 5-33

SURFACE

 SURFACE

 DAMAGE
 5-32

 SAP Aggregate
 Projecting
 5-32

 SAPM
 -Mechanical
 5-33

 SAPC
 -Chemical Attack
 5-33

 SAPZ
 -Not Evident
 5-33

 S URFACE

 DAMAGE
 5-32

 SAM
 Aggregate

 Missing
 5-32

 SAMM
 -Mechanical
 5-33

 SAMC
 -Not Evident
 5-33

 SAMZ
 -Not Evident
 5-33

 S SURFACE

 DAMAGE 5-32

 SRV Reinforcement

 Visible 5-32

 SRVM -Mechanical 5-33
 5-33

 SRVC -Chemical Attack 5-33
 5-33

 SRVZ -Not Evident 5-33

 SURFACE

 DAMAGE
 5-32

 SRP
 Reinforcement

 Projecting
 5-32

 SRPM
 -Mechanical
 5-33

 SRPC
 -Chemical Attack
 5-33

 SRPZ
 -Not Evident
 5-33

 S SURFACE

 DAMAGE 5-32

 SRC Reinforcement
 Corroded
 5-32

 SRCM -Mechanical
 5-33

 SRCC -Chemical Attack
 5-33

 SRCZ -Not Evident
 5-33

S SURFACE
DAMAGE 5-32

SMW Missing Wall 5-33
SMWC --Chemical Attack 5-33

SMWZ -Not Evident

 DAMAGE
 5-32

 SSS
 Surface Spalling
 5-33

 SSSM
 -Mechanical
 5-33

 SSSC
 -Chemical Attack
 5-33

 SSSZ
 -Not Evident
 5-33

 DAMAGE
 5-32

 SZ
 Other
 5-33

 SZM
 -Mechanical
 5-33

 SZC
 -Chemical Attack
 5-33

 SZZ
 -Not Evident
 5-33

SURFACE

S SURFACE
DAMAGE 5-32
SCP Corrosion (metal pipe) 5-33

LF LINING
FAILURE 5-46
LFD Detached Lining 5-46
LFB Blistered Lining 5-46
LFCS Service Cut Shifted 5-46
LFAC Abandoned
Connection 5-46

LF LINING
FAILURE 5-46
(continued)
LFOC Overcut Service 5-46
LFUC Undercut Service 5-46
LFBK Buckled Lining 5-46
LFW Wrinkled Lining 5-46
LFZ Other 5-46

WF WELD
FAILURE 5-58
WFL Longitudinal 5-58
WFC Circumferential 5-58
WFM Multiple 5-58
WFS Spiral 5-58
WFZ Unidentified 5-58

RP POINT
REPAIR 5-64
RPR Pipe Replaced 5-64
RPRD -Defective 5-64
RPP Patch Repair 5-64
RPPD -Defective 5-64

 RP POINT (cont)

 REPAIR 5-64

 RPL Localized Lining
 5-64

 RPLD -Defective 5-64
 5-64

 RPZ Other 5-64
 5-64

 RPZD -Defective 5-64
 5-64

BRICKWORK 5-70

DB Displaced 5-70

MB Missing 5-70

D1 Dropped Invert 5-70

BRICKWORK 5-70
townment

MM Missing Mortar 5-70
S Small 5-70
M -Medium 5-71
L -Large 5-71

Updated November 2007

NASSCO'S PIPELINE ASSESSMENT & CERTIFICATION PROGRAM (PACP)©

Section 4—Continuous Defect Coding

"TRULY" 4-1
"Truly" continuous defects run along the sewer without any interruption for more than 3 feet. Examples:
- Longitudinal Fractures

"REPEATED" 4.1
"Repeated" continuous defects occur at regular intervals along the sewer. These occur at pipe joints and include:
-Encrustation
-Open Joints
-Circumferential Fractures

Section 5—Structural Defect Coding (Module 6A)

C CRACK 5-1

CL Longitudinal 5-2
CC Circumferential 5-2
CM Multiple 5-2
CS Spiral 5-2

Cracks

F FRACTURE 5-7

FL Longitudinal 5-7

FC Circumferential 5-7

FM Multiple 5-7

FS Spiral 5-7

B BROKEN 5-15

BSV -Soil Visible Beyond Defect

BV V -Void Visible Beyond Defect

H HOLE 5-17

HSV -Soil Visible 5-17

Beyond Defect

HV V -Void Visible 5-17

Beyond Defect

D DEFORMED 5-19

DV Deformed 5-19

Vertically (brick)

DH Deformed 5-19

Horizontally (brick)

X COLLAPSE 5-23

XP Pipe Collapse 5-23

XB Brick Collapse 5-23

J JOINT 5-27

JO Joint Offset 5-27

(Displaced)

JS Joint Separated 5-27

(Open)

JA Joint Angular 5-27

 SURFACE

 DAMAGE
 5-32

 SRI
 Roughness

 Increased
 5-32

 SRIM
 -Mechanical
 5-33

 SRIC
 -Chemical Attack
 5-33

 SRIZ
 -Not Evident
 5-33

 S SURFACE

 DAMAGE
 5-32

 SAV Aggregate
 Visible
 5-32

 SAVM -Mechanical
 5-33

 SAVC -Chemical Attack
 5-33

 SAVZ -Not Evident
 5-33

 SURFACE

 DAMAGE
 5-32

 SAP Aggregate
 Projecting
 5-32

 SAPM -Mechanical
 5-33

 SAPC -Chemical Attack
 5-33

 SAPZ -Not Evident
 5-33

S SURFACE
DAMAGE 5-32
SAM Aggregate
Missing 5-32
SAMM -Mechanical 5-33
SAMC -Chemical Attack 5-33
SAMZ -Not Evident 5-33

 SURFACE

 DAMAGE 5-32

 SRV
 Reinforcement

 Visible
 5-32

 SRVM
 -Mechanical
 5-33

 SRVC
 -Chemical Attack
 5-33

 SRVZ
 -Not Evident
 5-33

 SURFACE

 DAMAGE
 5-32

 SRP
 Reinforcement

 Projecting
 5-32

 SRPM
 -Mechanical
 5-33

 SRPC
 -Chemical Attack
 5-33

 SRPZ
 -Not Evident
 5-33

 S SURFACE

 DAMAGE 5-32

 SRC
 Reinforcement

 Corroded
 5-32

 SRCM
 -Mechanical
 5-33

 SRCZ
 -Not Evident
 5-33

S SURFACE DAMAGE 5-32

 SMW
 Missing Wall
 5-33

 SMWM
 -Mechanical
 5-33

 SMWC
 -Chemical Attack
 5-33

 SMWZ
 -Not Evident
 5-33

S SURFACE DAMAGE 5-32

SSS Surface Spalling 5-33 SSSM -Mechanical 5-33 SSSC -Chemical Attack 5-33 SSSZ -Not Evident 5-33 S SURFACE DAMAGE 5-32

 SZ
 Other
 5-33

 SZM
 -Mechanical
 5-33

 SZC
 -Chemical Attack
 5-33

 SZZ
 -Not Evident
 5-33

S SURFACE DAMAGE 5-32 SCP Corrosion (metal pipe) 5-33 LF LINING
FAILURE 5-46
LFD Detached Lining 5-46
LFDE Defective End 5-46
LFB Blistered Lining 5-46
LFCS Service Cut Shifted 5-46
LFAC Abandoned
Connection 5-46

LF LINING
FAILURE 5-46
(combined)
LFOC Overcut Service 5-46
LFUC Undercut Service 5-46
LFBK Buckled Lining 5-46
LFW Wrinkled Lining 5-46
LFZ Other 5-46

WF WELD
FAILURE 5-58
WFL Longitudinal 5-58
WFC Circumferential 5-58
WFM Multiple 5-58
WFS Spiral 5-58
WFZ Unidentified 5-58

RP POINT
REPAIR 5-64
RPR Pipe Replaced 5-64
RPRD -Defective 5-64
RPP Patch Repair 5-64
RPPD -Defective 5-64

 RP
 POINT (cont)

 REPAIR
 5-64

 RPL
 Localized Lining

 5-64
 Feb

 RPLD
 -Defective
 5-64

 RPZ
 Other
 5-64

 RPZD
 -Defective
 5-64

 RPZD
 -Defective
 5-64

BRICKWORK 5-70

DB Displaced 5-70

MB Missing 5-70

D1 Dropped Invert 5-70

 BRICKWORK
 5-70

 manifulace)
 5-70

 MM Missing Mortar 5-70
 5-70

 S -Small
 5-70

 M Medium
 5-71

 L - Large
 5-71

Updated November 2007

Family	Group	Descriptor	Modifier	Code	Structural Grade	O&M Grade
Structural	Crack (C)	Circumferential (C)		CC	1	
		Longitudinal (L)		CL	2	
		Multiple (M)		CM	3	
		Spiral (S)		CS	2	
Structural	Fracture (F)	Circumferential (C)		FC	2	
on dotard.	radiale (r)	Longitudinal (L)		FL	3	
		Multiple (M)		FM	4	
		Spiral (S)		FS	3	
Structural	Pipe Failures (Silent)	Broken (B)		В	1 clock pos - 3, 2 clock pos - 4, >=3 clock pos - 5	
Otraotarar	1 12 1 2 1 2 1 2 1 2 1 2 1 2 1 2 1 2 1	Broken (B)	Soil Visible (SV)	BSV	5	
		Broken (B)	Void Visible (V V)	BVV	5	
		Hole (H)		Н	1 clock pos - 3, 2 clock pos - 4, >= 3 clock pos - 5	
		Hole (H)	Soil Visible (SV)	HSV	5	
		Hole (H)	Void Visible (V V)	HVV	5	
Structural	Collapse (X)	Pipe (P)	Void Visible (V V)	XP	5	
Structural	Collapse (X)	Brick (B)		XB	5	
Structural	Deformed (D)	(Pipe) (P)		D	<=10% - 4,>10% - 5	
Structural	Delofffled (D)	Brick (B)	Horizontally (H)	DH	5	
		Brick (B)	Vertically (V)	DV	5	
Structural	Joint (J)	Offset (displaced) (O)	Med (M)	JOM	1	
Olluciulai	oonit (o)	Onset (displaced) (O)	Large (L)	JOL	2	
		Separated (open) (S)	Med (M)	JSM	1	
		openator (open) (o)	Large (L)	JSL	2	
		Angular (A)	Med (M)	JAM	1	
		3.50.70.	Large (L)	JAL	2	
	Surface Damage Chemical (S)	Roughness Increased (RI)	C	SRIC	1	
	(0)	Surface Spalling (SS)	C	SSSC	2	
		Aggregate Visible (AV)	C	SAVC	3	
	*	Aggregate Projecting (AP)	C	SAPC	3	
		Aggregate Missing (AM)	C	SAMC	4	
		Reinforcement Visible (RV)	C	SRVC	5	
		Reinforcement Corroded (RC)		SRCC	5	

Family	Group	Descriptor	Modifier	Code	Structural Grade	O&M Grade
		Patch Repair (P)	Defective (D)	RPPD	4	
		Pipe Replaced (R)		RPR		
		Pipe Replaced (R)	Defective (D)	RPRD	4	
		Other (Z)		RPRZ		
		Other (Z)		RPRZD		
Structural	Brickwork (Silent)	Displaced (DB)		DB	3	
Structural	Blickwork (Siletti)	Missing (MB)		MB	4	
		Dropped Invert (DI)		DI	5	
		Missing Mortar	Slight	MMS	2	
		Wildering Wester	Medium	MMM	3	
			Large	MML	3	
O&M	Deposits Attached (DA)	Encrustation (E)		DAE		<=10% - 2, <=20% - 3 <=30% - 4, >30% - 5
		Grease (G)		DAGS		<=10% - 2, <=20% - 3 <=30% - 4, >30% - 5
		Ragging (R)		DAR		<=10% - 2, <=20% - 3 <=30% - 4, >30% - 5
		Other (Z)		DAZ		<=10% - 2, <=20% - 3 <=30% - 4, >30% - 5
· ·	Deposits Settled (DS)	Hard/Compacted (C)		DSC		<=10% - 2, <=20% - 3 <=30% - 4, >30% - 5
		Fine (F)		DSF		<=10% - 2, <=20% - 3 <=30% - 4, >30% - 5
		Gravel (G)		DSGV		<=10% - 2, <=20% - 3 <=30% - 4, >30% - 5
		Other (Z)		DSZ		<=10% - 2, <=20% - 3 <=30% - 4, >30% - 5
	Deposits Ingress (DN)	Fines silt/sand (F)		DNF		<=10% - 2, <=20% - 3 <=30% - 4, >30% - 5
		Gravel (GV)		DNGV		<=10% - 2, <=20% - 3 <=30% - 4, >30% - 5

Family	Group	Descriptor	Modifier	Code	Structural Grade	O&M Grade
		Missing Wall (MW)	C	SMWC	5	
		Other (Z)	C	SZC		
	Surface Damage Mechanical (M)	Roughness Increased (RI)	M	SRIM	1	
		Surface Spalling (SS)	M	SSSM	2	
		Aggregate Visible (AV)	M	SAVM	3	
		Aggregate Projecting (AP)	M	SAPM	3	
		Aggregate Missing (AM)	M	SAMM	4	
		Reinforcement Visible (RV)	M	SRVM	5	
		Reinforcement Corroded (RC)	M	SRCM	5	
		Missing Wall (MW)	M	SMWM	5	
		Other (Z)	M	SZM	N/A	
	Surface Damage Not Evident (Z)	Roughness Increased (RI)	Z	SRIZ	1	
		Surface Spalling (SS)	Z	SSSZ	2	
		Aggregate Visible (AV)	Z	SAVZ	3	
		Aggregate Projecting (AP)	Z	SAPZ	3	
		Aggregate Missing (AM)	Z	SAMZ	4	
		Reinforcement Visible (RV)	Z	SRVZ	5	
		Reinforcement Corroded (RC)	Z	SRCZ	5	
		Missing Wall (MW)	Z	SMWZ	5	
		Other (Z)	Z	SZZ	N/A	
	Surface Damage (Metal Pipes)	Corrosion (CP)		SCP	3	
Structural	Lining Failure (LF)	Detached (D)		LFD	3	
		Defective End (DE)		LFDE	3	
		Blistered (B)		LFB	3	
		Service Cut Shifted (CS)		LFCS	3	
	4	Abandoned Connection (AC)		LFAC		
		Overcut Service (OC)		LFOC	3	
		Undercut Service (UC)		LFUC	3	
		Buckled (BK)		LFBK	3	
		Wrinkled (W)		LFW	3	
		Other (Z)		LFZ		
Structural	Weld Failure (WF)	Circumfrential (C)		WFC	2	
		Longitudinal (L)		WFL	2	
		Multiple (M)		WFM	3	
		Spiral (S)		WFS	2	
Structural	Point Repair (RP)	Localized Lining (L)		RPL		
		Localized Lining (L)	Defective (D)	RPLD	4	
		Patch Repair (P)		RPP		

Family	Group	Descriptor	Modifier	Code	Structural Grade	O&M Grade
110000000		Other (Z)		DNZ		<=10% - 2, <=20% - 3, <=30% - 4, >30% - 5
0011	B / B)	Fig. (F)	Derrel /D)	RFB		2
O&M	Roots (R)	Fine (F)	Barrel (B)	RFL		1
			Lateral (L) Connection (C)	RFC		1
	Boots (B) at a Laist		N/A	RF		1
	Roots (R) at a Joint	Ton (T)	Barrel (B)	RTB		3
		Tap (T)	Lateral (L)	RTL		2
			Connection (C)	RTC		2
	Beets (B) et a leist		N/A	RT		2
	Roots (R) at a Joint	Madium (M)	Barrel (B)	RMB		4
		Medium (M)	Lateral (L)	RML		3
			Connection (C)	RMC		3
	Deets (D) et a Joint		N/A	RM		3
	Roots (R) at a Joint	Ball (B)	Barrel (B)	RBB		5
		Dall (D)	Lateral (L)	RBL		4
			Connection (C)	RBC		4
	Docto (D) at a Joint		N/A	RB		4
0014	Roots (R) at a Joint	Weeper (W)	IN/A	IW		2
O&M	Infiltration (I)	Dripper (D)		ID		3
		Runner (R)		IR		4
		Gusher (G)		IG		5
		Gustier (G)		10		
O&M	Obstacles/Obstructions (OB)	Brick or Masonry (B)		OBB		<=10% - 2, <=20% - 3, <=30% - 4, >30% - 5
		Pipe Material in Invert (M)		ОВМ		<=10% - 2, <=20% - 3, <=30% - 4, >30% - 5
		Object Protruding Thru Wall (I)		ОВІ		<=10% - 2, <=20% - 3, <=30% - 4, >30% - 5
		Object Wedged in Joint (J)		ОВЈ		<=10% - 2, <=20% - 3, <=30% - 4, >30% - 5
		Object Thru Connection (C)		ОВС		<=10% - 2, <=20% - 3, <=30% - 4, >30% - 5

Family	Group	Descriptor	Modifier	Code	Structural Grade	O&M Grade
		External Pipe or Cable In Sewer (P)		OBP		<=10% - 2, <=20% - 3, <=30% - 4, >30% - 5
		Built Into Structure (S)		OBS		<=10% - 2, <=20% - 3, <=30% - 4, >30% - 5
		Construction Debris (N)		OBN		<=10% - 2, <=20% - 3, <=30% - 4, >30% - 5
		Rocks (R)		OBR		<=10% - 2, <=20% - 3, <=30% - 4, >30% - 5
		Other Objects (Z)		OBZ		<=10% - 2, <=20% - 3, <=30% - 4, >30% - 5
O&M	Vermin (V)	Rat (R)		VR		2
355 Sept. 1		Cockroach (C)		VC		1
		Other (Z)		VZ		1
Construction Features	Tap (T)	Factory Made (F)		TF		
			Capped (C)	TFC		
			Defective (D)	TFD		2
			Intruding (I)	TFI		<=10% - 2, <=20% - 3 <=30% - 4, >30% - 5
			Active (A)	TFA		
		Break-In/Hammer (B)		TB		
			Capped (C)	TBC		2
			Defective (D)	TBD		3
			Intruding (I)	ТВІ		<=10% - 2, <=20% - 3 <=30% - 4, >30% - 5
			Active (A)	TBA		
		Saddle (S)		TS		
			Capped (C)	TSC		
			Defective (D)	TSD		2
			Intruding (I)	TSI		<=10% - 2, <=20% - 3 <=30% - 4, >30% - 5
			Active (A)	TSA		

Family	Group	Descriptor	Modifier	Code	Structural Grade	O&M Grade
Construction Features	Intruding Seal Material (IS)			IS		
		Sealing Ring (SR)		ISSR		<=10% - 2, <=20% - 3, <=30% - 4, >30% - 5
			Hanging	ISSRH		<=10% - 2, <=20% - 3, <=30% - 4, >30% - 5
			Broken	ISSRB		<=10% - 2, <=20% - 3, <=30% - 4, >30% - 5
		Grout (GT)		ISGT		<=10% - 2, <=20% - 3, <=30% - 4, >30% - 5
		Other (Z)		ISZ		<=10% - 2, <=20% - 3, <=30% - 4, >30% - 5
Construction Features	Line (L)	Left (L)		LL		<=10 Deg - 1, <=20 Deg 2, >20 Deg - 4
		Left/UP (LU)		LLU		<=10 Deg - 1, <=20 Deg 2, >20 Deg - 4
		Left/Down (LD)		LLD		<=10 Deg - 1, <=20 Deg 2, >20 Deg - 4
		Right (R)		LR		<=10 Deg - 1, <=20 Deg 2, >20 Deg - 4
		Right/Up (RU)		LRU		<=10 Deg - 1, <=20 Deg 2, >20 Deg - 4
		Right/Down (RD)		LRD		<=10 Deg - 1, <=20 Deg 2, >20 Deg - 4
		Up (U)		LU		<=10 Deg - 1, <=20 Deg 2, >20 Deg - 4
		Down (D)		LD		<=10 Deg - 1, <=20 Deg 2, >20 Deg - 4
Construction	Access Points (A)					

Family	Group	Descriptor	Modifier	Code	Structural Grade	O&M Grade
		Cleanout (CO)		ACO		
			Mainline (M)	ACOM		
			Property (P)	ACOP		
			House (H)	ACOH		
		Discharge Point (DP)		ADP		
		Junction Box (JB)		AJB		
		Meter (M)		AM		
		Manhole (MH)		AMH		
		Other Special Chamber (OC)		AOC		
		Tee Connection (TC)		ATC		
		WW Access Device (WA)		AWA		*
		Wet Well (WW)		AWW		
Other	Miscellaneous (M)	Camera Underwater (CU)		MCU		4
Jiner	Miscellarieous (M)	The state of the s		IVICO		7
		Dimension/Diam/Shape Change (SC)		MSC		
		General Observation (GO)		MGO		
		General Photograph (GP)		MGP		
		Material Change (MC)		MMC		
		Lining Change (LC)		MLC		
		Joint Length Change (JL)		MJL		
		Survey Abandoned (SA)		MSA		
		Water Level (WL)		MWL		
		Water Level (WL)	(S)	MWLS		<=30% - 2, <=50% - 3, >50% - 4
		Water Mark (WM)	V-7	MWM		>=50% 4, >=75% 5
		Dye Test (Y)		MY		
		2,01001(1)	Visible (V)	MYV		5
			Not Visible (N)	MYN		3