## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	0/0/01	IF SO, HOW AND LOCATION FROM	265′					
HOUSE NO.	1212	FIRST MANHOLE DOWN STREAM						
SIZE OF PIPE USED	2*	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT						
WAS LATERAL AT CURB?	yes	CURB LINE AND DEPTH						
WAS ATTACHED TO MAIN	yes	NAME OF CONTRACTOR	H & W					
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.								
1212 Harion SE								
2° Service Lateral—	-valve & bax	265.						
		2° Sewage Force Hain						
·		Marion S.E.						
SIGNED	ı	FILED AT ENGINEER'S	OFFICE					
	Inspector for City							
	ů.							
REMARKS								

## Nº 11329

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

		1445	SSILLON, OHIO,	July	24
RECEIVED OF	Mille		A Tile	FEE OF \$	
FOR WHICH PERMISSION IS GR	ANTED	H+W	Contractors	Fig. (4)	Problem
TO TAP		SEWER ON	THE ( )	North	· · · · · ·
OF MALICIA	AVE SE	AVE. ST. TYPE OF S	STREET 55	asohalt	
THE PREMISES BEING LOT NO.	<u>Part</u>	06 298	, HOUSE NO	W	2
WORK TO BE DONE IN ACCORD	ANCE WITH ORDINA	NCE NO. 19.1971 D	OULY PASSED BY THE C	TY COUNCIL, AND RU	ILES OF THE
DEPARTMENT OF PUBLIC SERV	ICE.	,			
NAME OF CONTRACTOR	<u> </u>	W			

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.