FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

Nº 2219

House No. Distance from first manhole down stream to ditch at curb line and depth Was lateral at curb? Was attached to main Show by diagram relation of lateral to wall of building served.				om m	If so how and location first manhole down stre	0/18/20	Date Inspected
Name of Contractor Show by diagram relation of lateral to wall of building served.	~			Distance from first manhole down stream to ditch at		6"	
Show by diagram relation of lateral to wall of building served.					Name of Contractor	rb? Hex	Was lateral at cu
1 19 2 1 19					Name of Contractor	main	Was attached to
11N 2 1 19		A second of			wall of building served.	n relation of lateral to	Show by diagram
JUN 2 1 19					swell and the first		
JUN 2 1 19							
EtakBlanes Dun 2 1 19							
JUN 2 1 19							
JUN 2 1 19					Land Carlotter Comment		el dilloyet a
JUN 2 1 19							
an a difficult of Variable Bush Bush Bush Community Comm	nne	บบม ดี 1 10		e promotive services	amend a management	5-6/1	4
Signed Filed at Engineer's Office JUN 2 1 13	120	JUN 2 1 19	r's Office	d at Enginee	ri Fi	and I so	Signed ///

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2219

PERMIT TO TAP SEWER

	Massillon, O., 15 19 26
Received of Witten	V
	hoften
to tap dand any sewe	er, on the side
of Journey	Ave., the premises being Lot. No. 2570 St.
House No. 834. Work to be done in a	accordance with Ordinance No. 2323, duly passed
by the City Council, and Rules of the Departmen	nt of Public Service.
Name of Contractor & Hittman	