FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED Date Inspected If so how and location from first manhole down stream... House No. 816 Distance from first manhole down stream to ditch at Size of pipe used 4 AM curb line and depth. Was lateral at curb? Was attached to main ... Show by diagram relation of lateral to wall of building served. Other Type of Street Life A. A. E. E. E. . 2323, duly passed by the City Louncil, and Ruser of Inspector for City

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

## Nº 2770 PERMIT TO TAP SEWER

		shole down mente troin hist mante		a activities a warm or promise or commence and a		aus id
Rece	ived of	Trumpe.	rand l	Deshon	fee of {	\$ <b>.2</b> ,
for which pe	ermission is gra	nted 13.	ucq. W	leichert		VALUE OF THE OWNER
ti Palis virus turi Muser		Section 1 to the second section of the section of t	Some Some was all		tiffer a figure of the control of	za.W
to tap	Jann	(a/)	sewer, on	the — — S	idalot matyais 70.	ر ۱۹۵۵ مر
of	Dunca	11 5.W	/, Ave	Type of Street	as pha	//
	6th ST S	SW	St.			
the premises	being Lot. No	1903	3377	House No	816	
Work to be	done in accord	ance with Ordina	nce No. 2323,	duly passed by	the City Council	and I
					작가요? 그는 중 중 중심인	

NOTE. This permit covers work outside of building only. Any work inside walls of bui is subject to Massillon Board of Health Regulations.