FOLLOWING DATA TO BE ANSWERED BY INSPECTOR • AND SIGNED WHEN RETURNED

Date Inspected Dec 6	If so how and location from first manhole down stream Distance from first manhole	
Size of pipe used 6.000	down stream to ditch at curb line and depth.	
Was lateral at curb? Apl A. Was attached to main.	Name of Contractor Wind Horn (1940)	DE06
Show by diagram relation of lateral to	그리고 그리 프로그램은 그리고 있는 그리고 있는 것이 없네 그를 받았다.	
ilouse No		n ee
uly passed by the Cay Council, and Kal	Wast to be Jone in secondance with Ordinaince No. 2323, d	
Signed A. P. Bayest	MH > 0 Houseles as	Vorla 3
Remarks Lateral Cry	for City A Clark to to to to the part could	26 14 12 =

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2852	PERMIT TO	TAP SEWER
		O bermont will
Received of	olugiam ran inchi pressi C. T. L. M.	fee of \$
for which permission is	in Maria properties (Contractor Line Maria	Beachniperplacement 2017
	sewer, on the solves and find to the or lors Ave., Type of	
23rd ST SW the premises being Lot.	, 10274 S t.	
	cordance with Ordinance No. 2323, duly pa	ssed by the City Council, and Rul

Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and Rul the Department of Public Service.

the Department of Public Service

Name of Contractor

NOTE. This permit covers work outside of building only. Any work inside walls of build is subject to Massillon Board of Health Regulations.