FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED Nº 3135

line on House

Date Inspected Dic / P	I so how and location from first manhole down stream
House No. 823	Distance from first manhole down stream to ditch at
Size of pipe used 6	curb line and depth
Was lateral at curb? 1920	
Was attached to main	Name of Contractor & M. Hostetler
Was arrached to main	第2018年2月 - 秦朝秦秦皇 中国中国的新疆中央部队的共和国的共和国的国际和国际的国际和国际共和国的国际政策,并且由于自己的国际政策,但是国际政策的国际政
was attached to main	l to wall of building served.
Show by diagram relation of lateral	Total Contraction of the Contrac
Show by diagram relation of lateral	Total Contraction of the Contrac
Show by diagram relation of lateral	42 ft Pipe
Show by diagram relation of lateral	15 July 2 ft. Pipe
Show by diagram relation of lateral	42 ft Pipe

lepivase oridua eo seri

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 3135

PERMIT TO TAP SEWER

1 (2) how use lecture from Ass. marrie clown girean	Massillon, O., 19
Received of Assertant moderation	telle fee of \$ 2
for which permission is granted	1.74-stille
to tap sewe:	r, on the night Early 1997
of 17 18 11 11 25	Ave., Type of Street A.L. St.;
the premises being Lot No. (25/2)	, House No. <u>& 2.2</u>
Work to be done in accordance with Ordinance No.	. 2323, duly passed by the City Council, and Ru
the Department of Public Service.	
Name of Contractor	

NOTE. This permit covers work outside of building only. Any work inside walls of bu is subject to Massillon Board of Health Regulations.