N^o 3951 — AND SIGNED WHEN RETURNED

DATE INSPECTED 3/19/	IF SO HOW AND LOCATION FROM 136	
House No. 3749		
	DISTANCE FROM FIRST MANHOLE	
SIZE OF PIPE USED 6	CURB LINE AND DEPTH	d
Was Lateral at curb? X		
WAS LATERAL AT CURB? /-/-	。《福德·西·克·克·克·克·克·克·克·克·克·克·克·克·克·克·克·克·克·克·	
Was attached to main /		
	N OF LATERAL TO WALL OF BUILDING SERVED.	dup
	一个,这个人的一个人,我们就是一个人的一个人的一个人的一个人的一个人的一个人的一个人的一个人的一个人的一个人的	
	LINCOLN.WAY. IV.W.	
	TE	1
가 있다는 한 사이 하고 있는 것이 되는 것 같아 사람들이 되었다. 사용하는 것 같은 것은 것이 되었다.		
	\$ Terminal Control of the Property of the Pro	
	ار سرا	
iliyali sat ya dipeka yibadi.	the constitution of the co	
MAY E	- 13 6 malana - 20 -) many 1 - 13 from	
A sharper to the lateral translation of		
$I \cup I \cup I$		3-19-3
	FILED AT ENGINEER'S OFFICE	
SIGNED INSPECTOR FO	OR CITY	ng palamag sala gayl, sa papagagaga

in se how and located from	- 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1
Mante mas anning time i	Massillon, Ohio,
RECEIVED OF	entaile FEE OF \$2
Hrania (faireir)	0320 3919 90 3512
TO TAP GEWER.	ON THE MAIN TO MAIN
	AVE., Type of Street
	\$ 57.
THE PREMISES BEING LOT NO	

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.