FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 5-27-4/ If so how and location from 0/ +1,4+
OHO COLHERAS FIRST MANHOLE DENNY STREAM CO DUT IN S 11 CC
House No. New house
DISTANCE FROM FIRST MANHOLE OWN STREAM TO DITCH-AT TO DITCH-AT
SIZE OF PIPE USED 6 CURB LINE AND DEPTH
WAS LATERAL AT CURBAS BACK OTOUTS
NAME OF CONTRACTOR SMOFT
gê Was attached to main 국가 및 문화를 하다는 등 한학교로 극복하는 사람들 등 다시는 🙀 🧸 🔭 다시는 다시를 하는 것이다.
Show by diagram relation of lateral to wall of building served. F RES
29ter9/8'Deepatourb
Lateral, 7' Deepathouse
Latera/35.3 Long house to connection
Lateral 40.5 Long house to ourb
CUT6
COMPL STATE DEPARTMENT OF THE SERVICE SERVICES SERVICES
WILLOW AVENE
SIGNED VILLE OK GCW - AUG
REMARKS: Soil Redolay + Mat Kontobot Cuth.
REMARKS: 10 11 11 11 11 11 11 11 11 11 11 11 11

	N_{\odot}^{0} 4268 PERMIT TO TAP SEWER
9 600	RECEIVED OF TOTAL AND THE PROPERTY OF THE PROP
4	FOR WHICH PERMISSION IS GRANTED A COMPANY OF THE PROPERTY OF T
	TO TAP SEWER. ON THE AVE., TYPE OF STREET ST.,
6	THE PREMISES BEING LOT No. $\frac{7773}{}$, House No. $\frac{227}{}$
le l	Work to be done in accordance with Ordinance No. 2323, duly passed by the City Counci Rules of the Department of Public Service.
	Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.