## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

보는 보고 있는 <b>경험으로 경험 회원에 가는 소설을 가는 보고 있는 것이 되었다. 그런 </b>
DATE INSPECTED 1/- 13-4/ IF SO HOW AND LOCATION FROM TO FOUT (4) From face of
House No. 1246 Outing+reet
DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT  SIZE OF PIPE USED 4 CURB LINE AND DEPTH
Was Lateral at cure? JeS.
Was attached to main NAME OF CONTRACTOR ON PAIDINE A
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED. W Res.
Lateral 5 Deep at our 6
hateral 6,5 Deepathouse, [Porch 1.)
Lateral33'Longhouse to curb.
AND THE COLUMN AND THE TENDERS OF THE TRANSPORT OF THE COURSE OF THE COLUMN THE COLUMN THE COLUMN THE COLUMN THE TENDERS OF THE COLUMN THE TENDERS OF THE TRANSPORT OF THE TENDERS OF THE
Lincoln Way E.
SIGNED Julius molson FILED AT ENGINEER'S OFFICE 11-17-41 OKGO
INSPECTOR FOR CITY
REMARKS, SOULE (SOM) MO (1/0)

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE Nº 4295 PERMIT TO TAP SEWER WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL RULES OF THE DEPARTMENT OF PUBLIC SERVICE. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.