## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM DISTANCE FROM FIRST MANHOLE 6'dech DOWN STREAM TO DITCH AT SIZE OF PIPE USED CURB LINE AND DEPTH WAS LATERAL AT CURB? 15 WAS ATTACHED TO MAIN <u>ソとう</u> SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED OAK. AVE

SIGNED U DIMONITATION FILED AT ENGINEER'S OFFICE

REMARKS:

OK TOOL

## Nº 4488

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

RECEIVED O	- Gennes-E	Massillon, Ohio,	/ 
FOR WHICH PERM	$\mathcal{H}_{\mathcal{U}}$	-2118-Bi	Noll
TO TAP	SEWER	ON THE	
of <u>(</u> 0	AVE. TYPE	TAU SO HOITAUIR IN HURI EOF STREET	1
THE PREMISES BEI	0100	House No. 22	9.9
网络克雷斯 医多生乳管 化多二甲二烷	E IN ACCORDANCE WITH ORDINANC	E No. 2323. DULY PABSED BY	THE CITY CO
	E IN ACCORDANCE WITH ORDINANC! PARTMENT OF PUBLIC SERVICE.	E No. 2323. DULY PABSED BY	THE CI

Note. This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.