FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

HOUSE NO. 429		DISTANCE FROM FIRST MANHOLE
BIZE OF PIPE USED	''	DOWN STREAM TO DITCH AT 227 - 26" dee
WAS LATERAL AT CURB?_	110	ASTRIACO O RECESSADOS NEROS ESTA
WAS ATTACHED TO MAIN	Ves.	NAME OF CONTRACTOR D. Earley
		TERAL TO WALL OF BUILDING SERVED.
	11 IN 5.	+ 5 W.
The second secon	Ν.	Energy shows each some and
		E. Curb Tine Y
		在这个意思的,我们就是不是一个的情况,我们就是一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个
		M/4- 227: 2'6'deg/ 11-1
10	5/	MH- 227: 26'deed 11-1 OW: CUTO line FILED AT ENGINEER'S OFFICE TY Ver W. CUTO: Relay job.
	CZZ	FUED AT ENGINEERIC OFFICE

Nº 4527 PERMIT TO TAP SEWER

		Teta Holtabs	ii, tha Rode			1977 PARE - 1
	والمنافذ والمنافضة والمتابية والمتاب	Listandra sograf	i migneri ki seki	MASSILLO	N, OHIO,	<u>/- / </u>
1	RECEIVED OF	Del	Lester	EALL	24	FEE OF S
		1984 2007000	OF SKAPES STO		4.11	
	OR WHICH PERMIS	SION IS GRANT		A)	1108	Purkiral aleku , jeudstva erkk
OF	1/-	EUZ:		YER, ON THE	estra issoluții L	Caro va vous
	IE PREMISES BEING	a LOT NO	3/43		louse No	420 11
	ORK TO BE DONE JLES OF THE DEPA	三 电波性电影 化二十二烷基苯酚	帽子 5年,年,然后却为4,是,	NCE NO. 232	3. DULY PASSED	BY THE CITY COUNC

Note. This permit covers work outside of building only. Any work i walls of building is subject to Massillon Board of Health Regulations.