FOLLOWING DATA TO BE ANSWERED BY INSPECTOR 3

DATE INSPECTED $6 - 20 - 45$	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 653	DISTANCE FROM FIRST MANHOLE. DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? I'M. M. M.	NAME OF CONTRACTOR Smart
SHOW BY DIAGRAM RELATION OF LA	TERAL TO WALL OF BUILDING SERVED
navon viid esir va lassima vilaine best cal	Tobasium of the sound and a second and an estimate and an esti
SIGNED John Hans INSPECTOR FOR CI	FILED AT ENGINEER'S OFFICE OF 7=2

Nº 4539

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

		ra matarta eta eta Mara	e mostopa Pejodá. Bendesjorálna o M	ASSILLON, OHIO,	il erosy.	6
	RECEIVED OF	acab	12 - Total			of \$ <i>G</i>
FOR	WHICH PERMISSION	TA HOVED DI	To Elle			0.252
		ndronatures.			Zecionoas	
70 T	Sente	77.7%	AVE., TYPE O			74780 E. S.
•	PREMISES BEING LO	TNG 102	10	. House No	- 6.5%	
	K TO BE DONE IN		TH ORDINANCE N		ASSED BY THE	CITY COUNT
RuL	ES OF THE DEPARTM	and the state of the second second		1		
1100	E OF CONTRACTOR					

Note. This permit covers work outside of building only. Any work i walls of building is subject to Massillon Board of Health Regulations.