FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 5-22-46	- IF SO HOW AND LOCATION FROM FIRST MANHOLE DEMEN STREAM
HOUSE NO. 1320	
SIZE OF PIPE USED 6 9/	DISTANCE FROM FIRST MANHOLE DESCRIPTION STREAM TO DITCH AT CURB LINE AND DEPTH 7' de e/s
WAS LATERAL AT CURB? / CS	
WAS ATTACHED TO MAIN Ves	NAME OF CONTRACTOR B/UESTONE
SHOW BY DIAGRAM RELATION OF LA	TERAL TO WALL OF BUILDING SERVED.
Johnson ST	
	18/5-78ech
상용하는 사람들이 발목하는 것으로 발표를 통해 되었다. 호텔 기가 있을 보다 보기를 보고 있는 것으로 보고 있습니다.	
	716:4
11 51	
SIGNED ALL CLAND	FILED AT ENGINEER'S OFFICE
INSPECTOR FOR CI	
REMARKS:	1 5-24-16 Z

Nº 4633

Nº 4633 OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

			gody seed stag	Caros refer on 191 Minorodus Monto			HI HTHOTEL
		RECEIVED O	. Q. K	7. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1.	MASSILLON, OHI		
•	FOR		SA MARTIN OF	OFFA THE LOUISING			
	гок то та			SEWEI	ONTHE		TELUAYAN TELUTAKAN
		CF Y	giomeinus so	ÁVE. TY	tau yo Holya.	an organization	
	OF	PREMISES BEI		386	. House		,
· · ·			E IN ACCORDANCE				E CITY COUNC
				Le Crouer			

NAME OF CONTRACTOR TO KILLING LATER

Note. This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.