FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 8-3/-	46 IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	74'
ноиse no. <u>1520</u>	FIRST MANNULE DOWN SIREAM //	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	ol: 5deeh
WAS LATERAL AT CURE?	er en	264.44 (2003) - 100 - 10
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR	
SHOW BY DIAGRAM RELATION O	F LATERAL TO WALL OF BUILDING SERVED.	
Johnson	1,50 SE.	6
	And the supervision of the super	, 1/(
representative property and an experience of the	The Francisco Principal Color of the color	4/1
	The state of the second section of the section of the second section of the section of the second section of the section of	를 보냈다. 보통 등 보통 이번 하는데 보이 시 등 보통 등을 보냈다. 하나 없다.
		10
	MA.	4 /115
SIGNED OF THE	M.H. 19	5 / 115 / 5 / 15 / 15 / 15 / 15 / 15 /
SIGNED INSPECTOR F	MH. 19	5 / 115 / 5 / 15 / 15 / 15 / 15 / 15 /

4661

Nº 4661

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

		i de la compania de La compania de la co	en de la companie de La companie de la comp	Massillon, O		eleks svog
	RECEIVED OF	Dora				- - FEE OF \$
	WHICH PERMIS		Dir	a Bl	mesto	~e
		ntary				art
		sm Al				+
$\int_{-\infty}^{\infty} t$		Lot No.	51., 5344			570
INE	-NEMISS SEIMU					

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNTRILES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Valuestin

Note. This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.