## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 8-30-	15 SO HOW AND LOCATION FROM 275 9. Jean
House No. 1727-172	DISTANCE FROM FIRST MANHOLE
SIZE OF PIPE USED	DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?	NAME OF CONTRACTOR Blues Tane
adefalde kladalakki kashki sebadi ala ake da fada higali kecasasi a aasasa sa a 👫 🏲	F LATERAL TO WALL OF BUILDING SERVED.
Service of the servic	18 78 54
γ	->
	0 275 5/7!
SIGNED John Eh	FILED AT ENGINEER'S OFFICE 9/19/6/7
REMARKS:	rofi collised of degles si estilical to ellow

 $N_0$ 

4966

## office of the director of public servici 4966 PERMIT TO TAP SEWER

	A LUCAR PROPERTY &	iosa, veting 500-51		6/21
RECEIVED C	mas 1	AN E	Massillon, Ohio,	FEE OF SZ
	ESSION IS GRANTED	esa esta de la comoción de la comoci	ne	gree uses so dale :
TO TAP		SEWER.	ON THE	Tabasettai east Zagendatta east
of 15th	118	AVE., TYPE	CALLED MOITALES	fut
THE PREMISES BEI	NG LOT NO L		73_, House No_	1727-17
taraga kacamatan kecamatan ber	进入的 人名西瓦克 格 医特殊点		E No. 2323, DULY PA	SSED BY THE CITY COUN
RULES OF THE DE	partment of Publi	SERVICE.	otone	

Note. This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.