FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 6-7-50	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	6'decf
WAS LATERAL AT CURB?		
WAS ATTACHED TO MAIN $\frac{V\mathcal{CJ}}{}$	NAME OF CONTRACTOR Boger	
SHOW BY DIAGRAM RELATION OF LATE	ERAL TO WALL OF BUILDING SERVED.	
Lake Ave	NE, " Commence of the second o	6.
	Not on main. Found Y'z' East and connected	Boger started
	46.	I here
	•	
SIGNED John Elmer	FILED AT ENGINEER'S OFFICE_	6-21-50
REMARKS: Lateral neve	r conn. to main. Troub	le here. Lateral
duqup at Main by	, Remley 4-11-51 and con	nocted, R. Fronze

 N_{0}

5444

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

14 16 3**N** 9 8 4 5 4 4 4 1

国。在北京建筑工程(A. C.A.S. Park V. F. F. C. V.

PERMIT TO TAP SEWER

•		61	
MAS	ssillon, Ohio,	//	
RECEIVED OF Atkan Oklan	Land	FEE OF) 00
FOR WHICH PERMISSION IS GRANTED TO THE	8 1 m	- K	
TO TAPSEWER, ON T	HE S		SIDE
OF TAKE THE OF ST., TYPE OF S	The state of the state of	lo d	SIDE
THE PREMISES BEING LOT NO. \$ 550-49	, HOUSE NO	148	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO.	. 2323, DULY PASS	SED BY THE CITY CO	DUNCIL, AND
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.			

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.