Nº 5566

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 7-13-55 IF SO HOW AND FIRST MANHOLE	LOCATION FROM
HOUSE NO. 453	
	TO DITCH AT DEPTH Y'dech
WAS LATERAL AT CURBY	in elektrologikan oleh delak di kedia kedi elektrologikan di kedikan di kedikan di kedikan di kedikan di kedik Kedikan
WAS ATTACHED TO MAIN Ves NAME OF COI	NTRACTOR Remley
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL O	
18 TH 57, N. W.	7/2:4
	e de la companya de l
	Charles which was the charles made about
Material Section 2015	and the first of the common and an arrangement of the first of the common and the
SIGNED John Etimer	FILED AT ENGINEER'S OFFICE
	is described at Engineer's Office: 2-6-51
REMARKS:	

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

	#1 N? #1 5566 10 (2747) #81		//	7
		MASSIL	LON, OHIO,	<u> 30 - </u>
	RECEIVED OF	2 m ley		FFE OF \$/2
F(FOR WHICH PERMISSION IS GRANTED	talph)	Schin	Der
Ţ	TO TAP LAND	SEWER, ON THE_	W	ing dalah berasil Kabupatèn Kabupatèn
	or 18-12 71 W	AVE. TYPE OF STRE	9 1 / 1 / 2 / 2 / 2 / 2 / 2 / 2 / 2 / 2 /	J. 101
	THE PREMISES BEING LOT NO. 5/4	7-46	HOUSE NO 15	 [9

NAME OF CONTRACTOR / Compley

Note. This permit covers work outside of building only. Any work it walls of building is subject to Massillon Board of Health Regulations.