FOLLOWING DATA TO BE ANSWERED BY INSPECTOR 2 --AND SIGNED WHEN RETURNED.

DATE INSPECTED 9-8-5/	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?	andre de la Colonia de la Colonia de la Calenda de la Martina de la Colonia de la Colonia de la Colonia de la C En la Colonia de la Colonia
WAS ATTACHED TO MAIN	- NAME OF CONTRACTOR Diana
SHOW BY DIAGRAM RELATION OF LATE	ERAL TO WALL OF BUILDING SERVED.
Erie Sti	5.
1000 - 10	<u>and the property of the formation of the property of the prop</u>
	118 13
	6 Hidechard
SIGNED John Edward	FILED AT ENGINEER'S OFFICE 9-11-51
	Trotti de til er senjabe ti paiblicit la eller
REMARKS:	

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 5679

PERMIT TO TAP SEWER

and the state of t
Massillon, Ohio,
AU = AU + AU +
RECEIVED OF FEE OF \$
FOR WHICH PERMISSION IS GRANTED TO COURCEMENT
A STATE OF THE STA
TO TAP Sanday SEWER, ON THE - and
The second of the land of the second of the
OFAVE TYPE OF STREET
Pho Fire
THE PREMISES BEING LOT NO. 4 15 3 HOUSE NO. 1500

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCE RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Note. This permit covers work outside of building only. Any work is walls of building is subject to Massillon Board of Health Regulations.