No. 5779 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

	·	
DATE INSPECTED 4-24-52	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 2922		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	9 Let
WAS LATERAL AT CURB7 / <	o Colombia (Colombia de Seria de Seria de Colombia de Colombia de Colo mbia de Colombia d	
WAS ATTACHED TO MAIN $\frac{\sqrt{79}}{}$	NAME OF CONTRACTOR PIAN A	,
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED.	
Lincoln W	. In the Control of t	6 4.don
	e de la composition de la compansa d La compansa de la compansa del compansa de la compansa del compansa de la compansa del la compansa de l	5 2 9 dey
SIGNED John Man	FILED AT ENGINEER'S OFFICE	5/3/52
The state of the second	ja dias 60 ar negdar si uniking la tiinv	
REMARKS:		

Nº 5779

PERMIT TO TAP SEWER

	0 Massillon, Ohio, 4-2 2
	RECEIVED OF Community Store FEE OF \$ 2.0
	FOR WHICH PERMISSION IS GRANTED Community Store T Dround
	TO TAP Sanday SEWER, ON THE north
	of Lin al 17 al AVE. TYPE OF STREET Hand senfance
	THE PREMISES BEING LOT NO. 1834 184 04, HOUSE NO. 2922
v.	WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL

Note. This permit covers work outside of building only. Any work it walls of building is subject to Massillon Board of Health Regulations.