Nº 5845

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 8-8-52	IF SO HOW AND LOCATION FROM 17
HOUSE NO. 47/	DISTANCE FROM FIRST MANHOLE OF THE VEHICLE OF THE V
WAS LATERAL AT CURB?	CURB LINE AND DEPTH
WAS ATTACHED TO MAIN YES	NAME OF CONTRACTOR L. 17 / byecht
SHOW BY DIAGRAM RELATION OF LATE	9/
	Carver 3'dup
	2 8' dep 6 1 47'
	TY CONTROL OF STREET AT ENGINEER'S OFFICE 6-28-53
REMARKS:	

Nº 5845

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	e nepro sitello pos possibilis se conocidad. Caracteristica se se como constru	South and the second of the second section of		
BEEROOM SERVICE TO THE PROPERTY OF THE PROPERT	Liva da in de M	ASSILLON, OHIO,	July 30	i i i i
				uc kur
RECEIVED OF GATSON PA		nerion Comra	ny FEE OF	5 <u>20 0 0 1</u>
FOR WHICH PERMISSION IS GRANTED	mana, and the	The second section of the second section of the second section of the second section s		
TO TAP Sanitary		THE West		
(4) 「日本の日本の日本の日本の日本の日本の日本の日本の日本の日本の日本の日本の日本の日	ning di pangangan di pangangan Tahunggan kangangan di pangangan		1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1	
THE PREMISES BEING LOT NO. 10-34	•	, HOUSE NO	471	
WORK TO BE DONE IN ACCORDANCE WI		O. 2323, DULY FASS	SED BY THE CIT	Y COUNC

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.