FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

•		
DATE INSPECTED 12-11-52	IF SO HOW AND LOCATION FROM TO PED IN	14 Cor. 130
HOUSE NO. /3/7		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURBE		
WAS ATTACHED TO MAIN CUt in	- NAME OF CONTRACTOR DIANA	
SHOW BY DIAGRAM RELATION OF LAT	ERAL TO WALL OF BUILDING SERVED.	
ang kananggan panggan panggan Panggan panggan pangga	£10's	
in the first of the second of	7' Deep	
en e	V	
Autopine and American are survey provided in 1960 in 19 Au	The second state of the se	SZ' Dec
	S. Gutter ot Forest Ave.	12
and the state of the	Mary Sewer with the se seems	4-MH
DE Ann		Q 60 C
SIGNED INSPECTOR FOR C	FILED AT ENGINEER'S OFFICE 12	-27-52
the transfer of the second for the	វិទ្ធី នេះស៊ីម៉ែននេះ ពីរ៉ា ៤៦ បន្ទមស៊ីនីមន្ត្រីម៉ែ ក្នុងស៊ីម៉ូនែនេះ វិក្ខា ស៊ីនែនេះ	
DEMARKS.	and the second of the second o	The state of the s

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

	9 5892	PERMIT	TO TAP SEW	VER
·	sie en malvidele La Maria de La	Bere mark ceine (j.) Bereker mark Mags i	LLON, OHIO.	
F	RECEIVED OF	11.0 A 11.		EE OF \$ 2
FOR WH	ICH PERMISSION IS GRANTED			
то тар_	a Lan	SEWER, ON THE		
OF	Turing Layer		reet to the total	yar kipitka k
THE PRE	MISES BEING LOT NO. 215	5-86-87	_, HOUSE NO)
-Work T	O BE DONE IN ACCORDANCE	WITH ORDINANCE No. 2	323, DULY PASSED BY TH	IE CITY COU
RULES O	OF THE DEPARTMENT OF PUBLI	GERVICE. H. DIZA	1D	

Nº 5892

Note. This permit covers work outside of building only. Any work i walls of building is subject to Massillon Board of Health Regulations.