## 6140

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 11-9-5-3	IF SO HOW AND LOCATION FROM		
HOUSE NO. 516 Rucas		-	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	· ::	
WAS LATERAL AT CURB?	in the Community of the	n ngwi kara L	A second of
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR	Beaver	Const. Co,
SHOW BY DIAGRAM RELATION OF LATER	RAL TO WALL OF BUILDING SERVED		Gargar Hou
		13/2 deep	IR IN BACK
and the same of the National			y <del>≥</del>
	tij in de leder van de tranjer versjeptett. V		
		7'duep	
SIGNED LEVOY Lat	FILED AT ENGINE	ER'S OFFICE	House on Esth St.
REMARKS:	and the resistance problem is the first first	ë to disselly	23/33

## Nº 6140

## PERMIT TO TAP SEWER

RECEIVED OF BEDUER Const	SSILLON, OHIO, 11-9-53 1
FOR WHICH PERMISSION IS GRANTED 4 1 W	Lecler
TO TAP SEWER, ON TO  OF 84 At & W  AVE., TYPE OF ST.,	The state of the s
THE PREMISES BEING LOT NO. 3463	HOUSE NO. 516 Read
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. RULES OF THE DEPARTMENT OF PUBLIC SERVICE. Round	

Note. This permit covers work outside of building only. Any work i walls of building is subject to Massillon Board of Health Regulations.