## Nº 6351

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 6-23-53	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 6-49		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT	81000
WAS LATERAL AT CURB? Yes	CURB LINE AND DEPTH	
WAS ATTACHED TO MAIN	NAME OF CONTROL OF A	bank Pul
SHOW BY DIAGRAM RELATION OF LAT	ERAL TO WALL OF BUILDING SERVED.	10 10
<ul> <li>LOSS CONTRACTOR</li> </ul>		
and the second of	Baran Kalang Biling ing kabupatèn dalah dalah dalah berbaran berba	91
6 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	The second of the second secon	16'
	Service of the service of the second	
		36' -8 du
n U		
SIGNED TOY INSPECTOR FOR C	FILED AT ENGINEER'S OFFICE	( 140'
REMARKS:	South of the state	6-4-58

## Nº 6351

## PERMIT TO TAP SEWER

5/
MASSILLON, OHIO, 15
RECEIVED OF Les Hatler) FEE OF 5 2 M
FOR WHICH PERMISSION IS GRANTED (1) D. Bullach
TO TAP SEWER, ON THE
of 27th nw AVE. TYPE OF STREET dert
THE PREMISES BEING LOT NO. PA 7/8 178 HOUSE NO. 57/9
Work to be done in accordance with Ordinance No. 2323, duly passed by the City Counci
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.
NAME OF CONTRACTOR Carban + Rengley

Note. This permit covers work outside of building only. Any work is walls of building is subject to Massillon Board of Health Regulations.