Nº 6399

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 9-12-55	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?	and a supplied to the first of the state of the state of the supplied to the state of the state of the state of
WAS ATTACHED TO MAIN Old La	NAME OF CONTRACTOR William & Pringley
SHOW BY DIAGRAM RELATION OF LATER	RAL TO WALL OF BUILDING SERVED.
House Burnt down	14
Years ago Building	The state of the s
	a manifer on a visit and a second of the second of the second
2 New House But con-	the track of the constitution of the constitut
neetina Plumbling to	V 1 Level / 5
old sewer Lateral	south south
GIVING PPRO, MERSURYN	177 You Fsewer
SIGNED / OTNSPECTOR FOR CIT	FILED AT ENGINEER'S OFFICE
/ / UINSPECTOR FOR CIT	10-8-55 - 10-8-55
REMARKS:	

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

Nº 6399

Note. This permit covers work outside of building only. Any work is walls of building is subject to Massillon Board of Health Regulations.