

N^o 9194

✓ FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED Aug 18 74

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

Found by old record

HOUSE NO. 108

SIZE OF PIPE USED 6

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB? _____

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR

Wadsworth

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



all line replaced

section street 5x6

through SE

SIGNED

JCH

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Repair

Nº 9194

OFFICE OF THE DIRECTOR OF PUBLIC SER
PERMIT TO TAP SEWER

MASSILLON, OHIO, *Aug. 18*

RECEIVED OF *Haldiburn* FEE OF \$ *25.00*

FOR WHICH PERMISSION IS GRANTED *John W. Haldiburn*

Repair
TO TAP *Sanitary* SEWER ON THE *North*

OF *Doughty Ave. S.E.* AVE.
ST. TYPE OF STREET *Black Top*

THE PREMISES BEING LOT NO. *2371*, HOUSE NO. *108*

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND R
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR *Haldiburn*

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.