

Project Information

Surveyor Name	Matthew W. Adams	Certificate Number	00000000
Owner		Customer	City of Massillon
Drainage Area		PO Number	
Pipe Segment Reference	Jamestown Pump Station	Date	11/5/2019 10:47
Street	Jamestown	City	Massillon
Comments			

Manhole

Upstream MH	Downstream Pipe #27	Rim to Invert (U)	
Grade to Invert (U)		Rim to Grade (U)	
Downstream MH	Upstream Pipe # 27	Rim to Invert (D)	
Grade to Invert (D)		Rim to Grade (D)	
Sewer Use	Stormwater Pipe	Direction of Survey	Upstream

Pipe

Height (Diameter)	(42)	Width	
Shape	Circular	Material	Reinforced Concrete Pipe
Lining Method	Cured-In-Place Pipe	Pipe Joint Length	
Total Length		Length Surveyed	396.3
Year Laid		Year Renewed	

Misc

Flow Control		Media Label	DVD
Purpose		Sewer Category	
Pre-Cleaning	No Pre-Cleaning	Date Cleaned	
Weather		Location Code	
Additional Info		Location Details	

Custom

Number of Taps	0	Number of Roots	0
Num Cracks / Fractures	0	Number of Broken / Holes / Collapse	0
Number of Deposits	2	Custom6	
Custom7		Struct Grade	
OM Grade		Overall Grade	

Pacp 6

Reverse Setup ID		Sheet (Group) Number	
Imperial Units (US)	True	Pressure Value	
Work Order		Project	
		Completed	Yes

Project:

Date: 11/5/2019 10:47:00 AM

Street: Jamestown

Length Surveyed: 396.3

Pacp Quick Overall Rating: 413Z

Height (Diameter): (42)

Street: Jamestown

Pipe Segment Reference: Jamestown Pump Station

Upstream MH: Downstream Pipe #27

Downstream MH: Upstream Pipe # 27

Direction of Survey: Upstream

Material: Reinforced Concrete Pipe

Distance	Fault Observation	Picture
0.0	Access Point Special Chamber Remarks: Jamestown Pump Station	 MH Downstre 11/5/2019 TO MH Upstream 10:50 Access Point SpecJamestown Pump St 0 FT
0.0	Miscellaneous Water Level	 MH Downstre 11/5/2019 TO MH Upstream 11:07 Video Paused Miscellaneous Water Level 4.0 FT. 0 FT
4.0	Lining Feature Wrinkled Position: 12 To 12	 MH Downstre 11/5/2019 TO MH Upstream 11:10 Lining Feature Wrinkled 4.0 FT. 4 FT
8.0	Lining Feature Wrinkled Position: 12 To 7 Remarks: at right bend in pipe	 MH Downstre 11/5/2019 TO MH Upstream 11:12 Lining Feature Wrat right bend in 8 FT
9.9	Miscellaneous General Observation Remarks: pipe turns 90degrees to the right	 MH Downstre 11/5/2019 TO MH Upstream 11:17 Miscellaneous Genpipe turns 90degr 9.9 FT

Distance	Fault Observation	Picture
24.2	Lining Feature Wrinkled Position: 7 Remarks: longitudinal wrinkle	
25.0	Deposits Attached Other Position: 5 To 7 Remarks: silt built up on haunches Maint Weight: 2	
48.9	Lining Feature Wrinkled Position: 2 Remarks: longitudinal	
55.3	Lining Feature Wrinkled Position: 7 Cont Defect: S02 Remarks: longitudinal	
80.8	Lining Feature Blistered Position: 6 To 7 Cont Defect: S03 Remarks: longitudinal	
126.5	Infiltration Stain Position: 12 Remarks: possible infiltration into liner Maint Weight: 1	

Distance	Fault Observation	Picture
148.8	Infiltration Stain Position: 12 Remarks: possible infiltration into liner Maint Weight: 1	
173.3	Lining Feature Other Position: 11 To 1 Remarks: possible tear in liner	
184.4	Lining Feature Blistered Position: 6 To 7 Cont Defect: F03 Remarks: longitudinal	
194.0	Lining Feature Blistered Position: 6 To 7 Cont Defect: S04 Remarks: longitudinal	
270.3	Deposits Settled Other Position: 5 To 7 Remarks: heavy silt Maint Weight: 2	
271.3	Miscellaneous General Observation Remarks: debris too thick for tractor to drive through	

Distance	Fault Observation	Picture
292.1	Lining Feature Wrinkled Position: 7 Cont Defect: F02 Remarks: longitudinal	
307.5	Line Up Remarks: line turns into incline Maint Weight: 4	
396.3	Access Point Other Remarks: Upstream Jamestown End Inspection	
396.3	Lining Feature Blistered Position: 6 To 7 Cont Defect: F04 Remarks: longitudinal	

Project:

Date: 11/5/2019 10:47:00 AM

Street: Jamestown

Length Surveyed: 396.3

Pacp Quick Overall Rating: 413Z

Height (Diameter): (42)

Street: Jamestown

Pipe Segment Reference: Jamestown
Pump Station

Upstream MH: Downstream Pipe #27


Downstream MH: Upstream Pipe # 27


Direction of Survey: Upstream

Material: Reinforced Concrete Pipe

Severity
Light
Moderate
Average
Heavy
Severe

ID Number: Upstream Pipe # 27





Created with the  report generator

Videos Created for Session

_Downstream-Upstream_1152019-1050_U_29141.avi Size: 2.00 GB

Created with the  report generator