

Project Information

Surveyor Name	Matthew W. Adams	Certificate Number	00000000
Owner		Customer	City of Massillon
Drainage Area		PO Number	
Pipe Segment		Date	11/6/2019 13:18
Reference		City	Massillon
Street	Jamestown		
Comments			

Manhole

Upstream MH	Pump Ciphon #30	Rim to Invert (U)	
Grade to Invert (U)		Rim to Grade (U)	
Downstream MH	Pump Pipe Outlet #30	Rim to Invert (D)	
Grade to Invert (D)		Rim to Grade (D)	
Sewer Use	Stormwater Pipe	Direction of Survey	Downstream

Pipe

Height (Diameter)	(30)	Width	
Shape	Circular	Material	Ductile Iron Pipe
Lining Method	None	Pipe Joint Length	
Total Length		Length Surveyed	46.6
Year Laid		Year Renewed	

Misc

Flow Control		Media Label	DVD
Purpose		Sewer Category	
Pre-Cleaning	No Pre-Cleaning	Date Cleaned	
Weather		Location Code	
Additional Info		Location Details	

Custom

Number of Taps	0	Number of Roots	0
Num Cracks / Fractures	0	Number of Broken / Holes / Collapse	0
Number of Deposits	0	Custom6	
Custom7		Struct Grade	
OM Grade		Overall Grade	

Pacp 6

Reverse Setup ID		Sheet (Group) Number	
Imperial Units (US)	True	Pressure Value	
Work Order		Project	
		Completed	No

Project:

Date: 11/6/2019 1:18:00 PM

Street: Jamestown

Length Surveyed: 46.6

Pacp Quick Overall Rating: 4133

Height (Diameter): (30)

Street: Jamestown

Pipe Segment Reference:

Upstream MH: Pump Ciphon #30

Downstream MH: Pump Pipe Outlet #30

Direction of Survey: Downstream

Material: Ductile Iron Pipe

Distance	Fault Observation	Picture
0.0	Access Point Special Chamber Remarks: Pump Station Siphon #2	 A photograph showing the interior of a circular access point. The walls are made of reddish-brown material, possibly brick or concrete. A large, dark, circular opening is visible in the center. Text overlay: MH Pump Sip 11/6/2019 TO MH Pump Pip 13:20 Access Point Spec Pump Station Siph 0 FT
0.0	Miscellaneous Water Level	 A photograph showing a close-up of a pipe joint. The pipe is dark and appears to be made of metal. A small, dark, rectangular object is visible near the joint. Text overlay: MH Pump Sip 11/6/2019 TO MH Pump Pip 13:24 Miscellaneous Water Level 0 FT
7.2	Miscellaneous General Observation Remarks: joint sealed	 A photograph showing a close-up of a pipe joint. The pipe is dark and appears to be made of metal. A small, dark, rectangular object is visible near the joint. Text overlay: MH Pump Sip 11/6/2019 TO MH Pump Pip 13:24 Miscellaneous Gen joint sealed 7.2 FT
10.0	Joint Separated Large	 A photograph showing a close-up of a pipe joint. The pipe is dark and appears to be made of metal. A large, dark, rectangular object is visible near the joint. Text overlay: MH Pump Sip 11/6/2019 TO MH Pump Pip 13:26 Joint Separated Large 10.0 FT
10.0	Surface Damage Corrosion Position: 5 To 7 Joint	 A photograph showing a close-up of a pipe joint. The pipe is dark and appears to be made of metal. A large, dark, rectangular object is visible near the joint. Text overlay: MH Pump Sip 11/6/2019 TO MH Pump Pip 13:27 Surface Damage Corrosion 10.0 FT

Distance	Fault Observation	Picture
37.6	Surface Damage Corrosion Position: 5 To 7 Joint	
42.6	Surface Damage Other Position: 12 To 12 Joint Remarks: coating is chipping away	
46.3	Surface Damage Corrosion Position: 12 To 12 Joint Remarks: surface coating is erroding away	
46.6	Access Point Special Chamber Remarks: Pump Siphon #2 Outlet	

Project:

Date: 11/6/2019 1:18:00 PM

Street: Jamestown

Length Surveyed: 46.6

Pacp Quick Overall Rating: 4133

Height (Diameter): (30)

Street: Jamestown

Pipe Segment Reference:

Upstream MH: Pump Ciphon #30

Downstream MH: Pump Pipe Outlet #30

Direction of Survey: Downstream

Material: Ductile Iron Pipe

Severity


Light

Moderate

Average

Heavy

Severe



Videos Created for Session

_Pump Siphon 2-Pump Pipe Outlet 2_1162019-1320_D_12499.avi Size: 327 MB

Created with the  report generator