

Project Information

Surveyor Name	Matthew W. Adams	Certificate Number	00000000
Owner		Customer	City of Massillon
Drainage Area		PO Number	
Pipe Segment Reference		Date	11/6/2019 12:21
Street	Jamestown	City	Massillon
Comments			

Manhole

Upstream MH	Pump Ciphon #29	Rim to Invert (U)	
Grade to Invert (U)		Rim to Grade (U)	
Downstream MH	Pump Pipe Outlet #29	Rim to Invert (D)	
Grade to Invert (D)		Rim to Grade (D)	
Sewer Use	Stormwater Pipe	Direction of Survey	Downstream

Pipe

Height (Diameter)	(30)	Width	
Shape	Circular	Material	Ductile Iron Pipe
Lining Method	None	Pipe Joint Length	
Total Length		Length Surveyed	46.3
Year Laid		Year Renewed	

Misc

Flow Control		Media Label	DVD
Purpose		Sewer Category	
Pre-Cleaning	No Pre-Cleaning	Date Cleaned	
Weather		Location Code	
Additional Info		Location Details	

Custom

Number of Taps	0	Number of Roots	0
Num Cracks / Fractures	0	Number of Broken / Holes / Collapse	0
Number of Deposits	0	Custom6	
Custom7		Struct Grade	
OM Grade		Overall Grade	

Pacp 6

Reverse Setup ID		Sheet (Group) Number	
Imperial Units (US)	True	Pressure Value	
Work Order		Project	
		Completed	No

Project:

Date: 11/6/2019 12:21:00 PM

Street: Jamestown

Length Surveyed: 46.3

Pacp Quick Overall Rating: 4133

Height (Diameter): (30)

Street: Jamestown




Pipe Segment Reference:


Upstream MH: Pump Ciphon #29

Downstream MH: Pump Pipe Outlet #29

Direction of Survey: Downstream

Material: Ductile Iron Pipe

Distance	Fault Observation	Picture
0.0	Access Point Special Chamber Remarks: pump siphon #1	 A photograph of a circular access point with a red frame. The text overlay includes 'MH Pump Sip 11/6/2019', 'TO MH Pump Pip 12:28', and 'Access Point Spec Pump Siphon #1 0 FT'.
0.0	Miscellaneous Water Level	 A photograph of a circular access point with a red frame. The text overlay includes 'MH Pump Sip 11/6/2019', 'TO MH Pump Pip 12:28', and 'Miscellaneous Water Level 6.3 FT. 0 FT'.
6.5	Joint Separated Medium	 A photograph of a pipe joint with a visible separation. The text overlay includes 'MH Pump Sip 11/6/2019', 'TO MH Pump Pip 12:32', and 'Joint Separated Medium 6.5 FT. 6.5 FT'.
9.2	Joint Separated Medium	 A photograph of a pipe joint with a visible separation. The text overlay includes 'MH Pump Sip 11/6/2019', 'TO MH Pump Pip 12:33', and 'Joint Separated Medium 9.2 FT. 9.2 FT'.
12.0	Joint Separated Medium	 A photograph of a pipe joint with a visible separation. The text overlay includes 'MH Pump Sip 11/6/2019', 'TO MH Pump Pip 12:34', and 'Joint Separated Medium 12.1 FT. 12 FT'.

Distance	Fault Observation	Picture
20.5	Miscellaneous General Observation Remarks: joint sealed	
27.4	Miscellaneous General Observation Remarks: joint sealed	
31.2	Miscellaneous General Observation Remarks: joint sealed	
37.2	Miscellaneous General Observation Remarks: joint sealed	
39.5	Miscellaneous General Observation Remarks: joint sealed	
42.1	Miscellaneous General Observation Remarks: joint sealed	

Distance	Fault Observation	Picture
42.1	Surface Damage Surface Spalling Position: 12 To 12	
45.0	Surface Damage Surface Spalling Position: 12 To 12	
46.3	Joint Separated Large	
46.3	Access Point Special Chamber Remarks: Pump Siphon Outlet #1	

Project:

Date: 11/6/2019 12:21:00 PM

Street: Jamestown

Length Surveyed: 46.3

Pacp Quick Overall Rating: 4133

Height (Diameter): (30)

Street: Jamestown

Pipe Segment Reference:

Upstream MH: Pump Ciphon #29

Downstream MH: Pump Pipe Outlet #29

Direction of Survey: Downstream

Material: Ductile Iron Pipe

Severity

Light

Moderate

Average

Heavy

Severe

ID Number: Pump Ciphon #29

(0.0) AOC - Access Point Special Chamber
Remark: pump siphon #1

(0.0) MWL - Miscellaneous Water Level

(6.5) JSM - Joint Separated Medium

(9.2) JSM - Joint Separated Medium

(12.0) JSM - Joint Separated Medium

(20.5) MGO - Miscellaneous General Observation
Remark: joint sealed

(27.4) MGO - Miscellaneous General Observation
Remark: joint sealed

(31.2) MGO - Miscellaneous General Observation
Remark: joint sealed

(37.2) MGO - Miscellaneous General Observation
Remark: joint sealed

(39.5) MGO - Miscellaneous General Observation
Remark: joint sealed


(42.1) MGO - Miscellaneous General Observation
Remark: joint sealed

(42.1) SSS - Surface Damage Surface Spalling -
Position: 12 To 12

(45.0) SSS - Surface Damage Surface Spalling -
Position: 12 To 12

(46.3) JSL - Joint Separated Large

(46.3) AOC - Access Point Special Chamber
Remark: Pump Siphon Outlet #1



Total Distance: 46.3



ID Number: Pump Pipe Outlet #29

Created with the  report generator

Videos Created for Session

_Pump Siphon 1-Pump Pipe Outlet 1_1162019-1227_D_7021.avi Size: 354 MB

Created with the  report generator