

Project Information

Surveyor Name	Matthew W. Adams	Certificate Number	00000000
Owner		Customer	City of Massillon
Drainage Area		PO Number	
Pipe Segment		Date	11/6/2019 13:49
Reference		City	Massillon
Street	Jamestown		
Comments			

Manhole

Upstream MH	Pump Ciphon #31	Rim to Invert (U)	
Grade to Invert (U)		Rim to Grade (U)	
Downstream MH	Pump Pipe Outlet #31	Rim to Invert (D)	
Grade to Invert (D)		Rim to Grade (D)	
Sewer Use	Stormwater Pipe	Direction of Survey	Downstream

Pipe

Height (Diameter)	(30)	Width	
Shape	Circular	Material	Ductile Iron Pipe
Lining Method	None	Pipe Joint Length	
Total Length		Length Surveyed	47.1
Year Laid		Year Renewed	

Misc

Flow Control		Media Label	DVD
Purpose		Sewer Category	
Pre-Cleaning	No Pre-Cleaning	Date Cleaned	
Weather		Location Code	
Additional Info		Location Details	

Custom

Number of Taps	0	Number of Roots	0
Num Cracks / Fractures	0	Number of Broken / Holes / Collapse	0
Number of Deposits	0	Custom6	
Custom7		Struct Grade	
OM Grade		Overall Grade	

Pacp 6

Reverse Setup ID		Sheet (Group) Number	
Imperial Units (US)	True	Pressure Value	
Work Order		Project	
		Completed	No

Project:

Date: 11/6/2019 1:49:00 PM

Street: Jamestown

Length Surveyed: 47.1

Pacp Quick Overall Rating: 4134

Height (Diameter): (30)

Street: Jamestown

Pipe Segment Reference:

Upstream MH: Pump Ciphon #31

Downstream MH: Pump Pipe Outlet #31

Direction of Survey: Downstream

Material: Ductile Iron Pipe

Distance	Fault Observation	Picture
0.0	Access Point Special Chamber Remarks: Jamestown Pump Siphon #3	 A photograph showing the interior of a circular access point. The walls are made of reddish-brown material, possibly brick or concrete, and show signs of wear and discoloration. The center is dark, suggesting a deep opening. Text overlays include 'MH Pump Sip 11/6/2019', 'TO MH Pump Pip 13:52', and 'Access Point SpecJamestown Pump Si 0 FT'.
0.0	Miscellaneous Water Level	 A photograph showing the interior of a circular access point, similar to the first one. The walls are reddish-brown. Text overlays include 'MH Pump Sip 11/6/2019', 'TO MH Pump Pip 13:55', and 'Miscellaneous Water Level 5.3 FT. 0 FT'.
9.8	Surface Damage Corrosion Position: 12 To 12 Joint	 A close-up photograph of the pipe surface showing significant corrosion and surface damage. The metal is pitted and discolored. Text overlays include 'MH Pump Sip 11/6/2019', 'TO MH Pump Pip 13:58', and 'Surface Damage Corrosion 9.8 FT. 9.8 FT'.
38.0	Joint Separated Large	 A photograph showing a large separation at a pipe joint. The pipe is dark and the joint is clearly visible as a gap. Text overlays include 'MH Pump Sip 11/6/2019', 'TO MH Pump Pip 14:03', and 'Joint Separated Large 38.0 FT. 38 FT'.
38.0	Surface Damage Corrosion Position: 5 To 7 Joint	 A close-up photograph of the pipe surface showing significant corrosion and surface damage, similar to the previous image. Text overlays include 'MH Pump Sip 11/6/2019', 'TO MH Pump Pip 14:03', and 'Surface Damage Corrosion 38.0 FT. 38 FT'.

Distance	Fault Observation	Picture
42.9	Joint Separated Medium	
42.9	Surface Damage Corrosion Position: 5 To 7 Joint	
47.1	Access Point Special Chamber Remarks: Siphon Pump #3 Outlet	

Project:

Date: 11/6/2019 1:49:00 PM

Street: Jamestown

Length Surveyed: 47.1

Pacp Quick Overall Rating: 4134

Height (Diameter): (30)

Street: Jamestown

Pipe Segment Reference:

Upstream MH: Pump Ciphon #31

Downstream MH: Pump Pipe Outlet #31

Direction of Survey: Downstream

Material: Ductile Iron Pipe

Severity

Light

Moderate

Average

Heavy

Severe

ID Number: Pump Ciphon #31

(0.0) AOC - Access Point Special Chamber
Remark: Jamestown Pump Siphon #3

(0.0) MWL - Miscellaneous Water Level

(9.8) SCP - Surface Damage Corrosion - Position:
12 To 12

(38.0) JSL - Joint Separated Large


(38.0) SCP - Surface Damage Corrosion -
Position: 5 To 7

(42.9) JSM - Joint Separated Medium

(42.9) SCP - Surface Damage Corrosion -
Position: 5 To 7

(47.1) AOC - Access Point Special Chamber
Remark: Siphon Pump #3 Outlet

Total Distance: 47.1



ID Number: Pump Pipe Outlet #31

Created with the  report generator

Videos Created for Session

_Pump Siphon 3-Pump Pipe Outlet 3_1162019-1351_D_49852.avi Size: 356 MB

Created with the  report generator