

Project Information

Surveyor Name	Matthew W. Adams	Certificate Number	00000000
Owner		Customer	City of Massillon
Drainage Area		PO Number	
Pipe Segment Reference		Date	11/6/2019 16:34
Street	West of RR W/Flap Gate	City	Massillon
Comments			

Manhole

Upstream MH	Upstream Pipe # 23	Rim to Invert (U)	
Grade to Invert (U)		Rim to Grade (U)	
Downstream MH	Downstream Pipe # 23	Rim to Invert (D)	
Grade to Invert (D)		Rim to Grade (D)	
Sewer Use	Stormwater Pipe	Direction of Survey	Upstream

Pipe

Height (Diameter)	(8)	Width	
Shape	Circular	Material	Reinforced Concrete Pipe
Lining Method	None	Pipe Joint Length	
Total Length		Length Surveyed	110.1
Year Laid		Year Renewed	

Misc

Flow Control		Media Label	DVD
Purpose		Sewer Category	
Pre-Cleaning	No Pre-Cleaning	Date Cleaned	
Weather		Location Code	
Additional Info		Location Details	

Custom

Number of Taps	0	Number of Roots	0
Num Cracks / Fractures	0	Number of Broken / Holes / Collapse	0
Number of Deposits	0	Custom6	
Custom7		Struct Grade	
OM Grade		Overall Grade	

Pacp 6

Reverse Setup ID		Sheet (Group) Number	
Imperial Units (US)	True	Pressure Value	
Work Order		Project	
		Completed	Yes

Project:

Date: 11/6/2019 4:34:00 PM

Street: West of RR W/Flap Gate

Length Surveyed: 110.1

Pacp Quick Overall Rating: 0000

Height (Diameter): (8)

Street: West of RR W/Flap Gate

Pipe Segment Reference:

Upstream MH: Upstream Pipe # 23

Downstream MH: Downstream Pipe # 23

Direction of Survey: Upstream

Material: Reinforced Concrete Pipe

Distance	Fault Observation	Picture
0.0	Access Point Manhole Remarks: Upstream West of RR	 A photograph looking down into a manhole. The walls are dark and the bottom is obscured by darkness. Text overlay: MH Upstream 11/6/2019 TO MH Downstre 17:13. Bottom text: Access Point ManUpstream West of 0 FT.
0.0	Miscellaneous Water Level	 A photograph looking down into a manhole. The bottom is covered with a layer of water and some debris. Text overlay: MH Upstream 11/6/2019 TO MH Downstre 17:27. Bottom text: Miscellaneous Water Level 66.5 FT.
0.0	Miscellaneous General Observation Remarks: rocks in invert	 A photograph looking down into a manhole. The bottom is covered with a layer of water and many small rocks. Text overlay: MH Upstream 11/6/2019 TO MH Downstre 17:27. Bottom text: Miscellaneous Gen. rocks in invert 0 FT.
110.1	Access Point End of Pipe Remarks: Flap Gate	 A photograph looking down into a manhole. The bottom is covered with a layer of water and many small rocks. A flap gate is visible. Text overlay: MH Upstream 11/7/2019 TO MH Downstre 11:16. Bottom text: Access Point End 110.1 FT. Flap Gate.

Project:

Date: 11/6/2019 4:34:00 PM

Street: West of RR W/Flap Gate

Length Surveyed: 110.1

Pacp Quick Overall Rating: 0000

Height (Diameter): (8)

Street: West of RR W/Flap Gate

Pipe Segment Reference:

Upstream MH: Upstream Pipe # 23

Downstream MH: Downstream Pipe # 23

Direction of Survey: Upstream

Material: Reinforced Concrete Pipe

Severity

Light

Moderate

Average

Heavy

Severe


(0.0) AMH - Access Point Manhole Remark:
Upstream West of RR

(0.0) MWL - Miscellaneous Water Level

(0.0) MGO - Miscellaneous General Observation
Remark: rocks in invert

(110.1) AEP - Access Point End of Pipe Remark:
Flap Gate

Total Distance: 110.1



ID Number: Downstream Pipe # 23

ID Number: Upstream Pipe # 23

Created with the  report generator

Videos Created for Session

_Upstream West of RR-Downstream West of RR_1162019-1713-9976.avi Size: 250 MB

_Upstream West of RR-Downstream West of RR_1172019-1114-9310.avi Size: 45.3 MB

Created with the  report generator