	FOLLOWING DATA TO BE ANSWERED BY INSPECTOR	し
Nº 2372	AND SIGNED WHEN RETURNED	
	I TIMBUT 2782 gg	
Date Inspected OC1-18	If so how and location from first manhole down stream	
House No. /5-13	Distance from first manhole	
Size of pipe used im	down stream to ditch at curb line and depth	
Was lateral at curb?		
Was attached to main	Name of Contractor 6 has Strong	
Show by diagram relation of late	ral to wall of building served.	
	Programa St. St. Johns	
	10 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
	135 M Vige	
	west - Main sewer	
	8-17-001 1-1-1	n Destaurant

Signed A. J. Bayd Filed at Engineer's Office OCT 1 91926

Remarks Lateral connected to lateral at curt 38% It from

Strait line on Ho

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

N	• 2372 PENIV	HI IO TAI SEWER
	o how and location from a manings down strong	
	sionae izai mori sani	Massillon, O., <u>Oct 16 7/</u> 2011
	niaso ina sait	oud fee of \$ 200
for w	hich permission is granted	1. Johnsons es benomen reliki
at a direct		ewer, on the 2001
to tap		
of	E. Walnut	Ave., the premises being Lot. No. <u>32.2</u> St

House No. 1522. Work to be done in accordance with Ordinance No. 2323, duly part by the City Council, and Rules of the Department of Public Service.

Name of Contractor Busiles Storie