The state of the same	TIVIFIED BESS OF THE	
Date Inspected <u>Lec L</u>	If so how and location from first manhole down stream	
House No. 1300	Distance from first manhole	
Size of pipe used	Distance from first manhole down stream to ditch at curb line and depth	Tacep
Was lateral at curb?		
	Name of Contractor	4
Was lateral at curb? Was attached to main Show by diagram relation of late		м
Was attached to mainShow by diagram relation of late	eral to wall of building served.	n.
Was attached to mainShow by diagram relation of late	eral to wall of building served.	n
Was attached to main	eral to wall of building served.	n.
Was attached to main Show by diagram relation of late	eral to wall of building served.	Mitha
Was attached to main Show by diagram relation of late	eral to wall of building served.	M.H.

GERMOTER MERWICEROR OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER 2396 for which permission is granted __sewer, on the _Ave., the premises being Lot. No. 4368

Name of Contractor *H. H.*