FOLLOWING DATA TO BE ANSWERED BY INSPECTOR N°_{\cdot} 4126 AND SIGNED WHEN RETURNED

DATE INSPECTED 6/18/46	If so how and location from First Manhole Down Stream
House No. 43/	DISTANCE FROM FIRST MANHOLE
SIZE OF PIPE USED	CURB LINE AND DEPTH
WAS LATERAL AT CURB?	and the second of the second of the second
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR
SHOW BY DIAGRAM RELATION OF LAT	TERAL TO WALL OF BUILDING SERVED. LINCOLN INAY, E
ling tight and the man and the reversible.	
	1 4 d
$oldsymbol{v}_{i}$	The same of the second
general vital ser ve aseses vocases on	205.8.6
MHJ	TO THE LEADING OF FUEL SERVICE.
	Tilled Line (All Maria Morganteed Rosanae)
· SIGNED INSPECTOR FOR CITY	FILED AT ENGINEER'S OFFICE
i kalandari kalan da bara da kalandari karan kalandari karan kalandari kalandari kalandari baran bilan bilan b Kalandari	was the same that INCIDE AL LIAL

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE 4126 PERMIT TO TAP SEWER THE PREMISES BEING LOT NO WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL RULES OF THE DEPARTMENT OF PUBLIC SERVICE. Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.