FOLLOWING DATA TO BE ANSWERED BY INSPECTOR 4188AND SIGNED WHEN RETURNED DATE INSPECTED 2-11-41 FIRST MANHOLE DOWN STREAM DOWN STREAM TO DITCH AT CURB LINE AND DEPTH WAS LATERAL AT CURB? NO 1. WAS ATTACHED TO MAIN SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED. Maln Sewer line runs Through Lincoln Park. 18" Deep at house 5' Deep at Connection ECTOR FOR CITY FEE 20 REMARKS 43 lateral oft of Mainline 16 New Jateral to house

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE NO. 4188 PERMIT TO TAP SEWER

P. L.	Massillon, Ohio,
RECEIVED OF	FEE OF \$
	goseo willig film whether he will
FOR WHICH PERMISSION IS GRANTED	. Williams .
La moral John	will for
	A A TO SAIL SAIL SAIL SAIL
TO TAP Soulder	SEWER ON THE
James a like	MANE, TYPE OF STREET GRAND
OF	AVE., TYPE OF STREET
THE PREMISES BEING LOT No	, House No. 5/4
WORK TO BE DONE IN ACCORDANCE WITH ORD	DINANCE NO. 2323, DULY PASSED BY THE CITY CO
RULES OF THE DEPARTMENT OF PUBLIC SERV	经整理保险 经最级股份 医电影 医电影 医阴影 医阴影 医阴影性 经收益 化二氯甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基
NAME OF CONTRACTOR	
TVAME OF CONTRACTOR 177	
Cill Lift to Ny Engineer's Oreion	outside of building only. Any work in
INATO I DIE NOPMIT CATIOPE WATE	CONTRICE OF DIVIDING ONLY AND WORK IN