"New Lateral FOLLOWING DATA TO BE ANSWERED BY INSPECTOR Nº 4320 AND SIGNED WHEN RETURNED DATE INSPECTED 4-13-42 IF SO HOW AND LOCATION FROM NO MIMER-SUFEMENT DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT-SIZE OF PIPE USED CURB LINE AND DEPTH Was Lateral at curb? No Yes. Was attached to main Hub. Saddle $f_{i+S}t$ Lateral 9.5 Deep at main Saving Lateral 9,5 Deep at curb Lateralg.s. Deep at Bldg. DHUDD YND BREVERBERRY JUD LINCOLN WAYE. FILED AT ENGINEER'S OFFICE Hori SIGNED REMARKS: + Marking top of out & Soil clay soud + Gravel. 1/8 Bendator Cellar dug: no fondation up.

$N_{\odot}^{0}=4320$ PERMIT TO TAP SEWER

	ROBERT INCOME THE PROPERTY OF
	Massillon, Ohio, 15
RECEIVED OF	Production Tests of State of S
FOR WHICH PERMIS	SION IS GRANTED
то тар	SEWER. ON THE
or	AVE., TYPE OF STREET ST.,
THE PREMISES BEIN	
	IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL

Name of Contractor

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.