" <u>New Jateta</u> ""
Note that the second following data to be answered by inspector of the second following data to be answered by inspector and signed when returned $/$
DATE INSPECTED 5-14-42 IF SO HOW AND LOCATION FROM 136 OUT IN STEED
House No. Distance from first manhole Down-stream-to ditch-at Size of Pipe used Curb line and depth
Was lateral at cure? YS, NAME OF CONTRACTOR P.E. B.CKO
Show by diagram relation of lateral to wall of building served. Res. Lateral 7'Deep at Cutbline
Lateral 6 Deep at House Lateral 40 Long House Too urbline Lateral 40 Long House Too urbline
A MOST OF THE STREET OF THE ST
Lindenstaw.
SIGNED WILLIAM FILED AT ENGINEER'S OFFICE 6KGGW May 1412-
Remárks.

y 8600 0d. 3/8/42 Vay in water # 90 OFFICE OF THE DIRECTOR OF PUBLIC SERVICE $\mathbf{M}^{\mathbf{0}} = \mathbf{4325}$ PERMIT TO TAP SEWER MASSILLON, OHIO WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL RULES OF THE DEPARTMENT OF PUBLIC SERVICE. Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.