## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE IN	SPECTED 9/25/42	FIRST MANHOLE DOWN STREAM	1
House N	10. 1054		
Maria Na 🖘		DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH	<u>'                                    </u>
Was Lat	ERAL AT CURB? NO	GETHARD IN ACCORD REMAINS HOW NOW	
Was att	ACHED TO MAIN	NAME OF CONTRACTOR L. POLONE.	
Show by	DIAGRAM RELATION O	OF LATERAL TO WALL OF BUILDING SERVED.	
	-5-	3 H57 NE.	
	74		
	Als remains at		
day conductly	nit knip <b>vi</b> er tima issei	The state of the second of the second with Ordenses No. 21	
	No.	The The Character of the solution of the second of the sec	MA
	5 4	60. —	$\sim$
	1 10'd. 1		U
SIGNED	/ INSPECTOR FOR C	FILED AT ENGINEER'S OFFICE GCW - 5e	PT 29
	. Tahhed of	nomain. Sanda soil.	

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE 4364 PERMIT TO TAP SEWER

		1 — 1 — 1 — 1 — 1 — 1 — 1 — 1 — 1 — 1 —	MASSILL	ON, OHIO,	// 2-3 /
RECEIVED C	or Yandinin ( AT	ing ng Nguyana Sagara	To A	· · · · · · · · · · · · · · · · · · ·	FEE OF \$ 2
OR WHICH PERM	ISSION IS GRANT	ED	(P.JK)	a fort	
O TAP	),, <i>J</i> .	rakoo so se	WER, ON THE	iii waana yar	93990A7440
<sub>F</sub> Դ -	A YL	1/2, 5	A	PE OF STREET	dint.
		Y Z PA SASS	AVE., T	PE UP SIREEI.	
HE PREMISES BE	ING LOT No.		17.51	, House No.	1254

This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.