Kepair Job	
Nº 4905	ING DATA TO BE ANSWERED BY INSPECTOR Z
DATE INSPECTED 1-10-47	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 835 SIZE OF PIPE USED # "	DISTANCE FROM FIRST MANHOLE TO USTISCER DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? WAS ATTACHED TO MAIN	NAME OF CONTRACTOR Remisey
SHOW BY DIAGRAM RELATION OF LATE  4 -P/6 C C S 6	At 4" Pipe relaid under sidewa
conduit was laid	d been damaged when Telephone under side walk. Repair made
by Telephone Co	Was not properly relaid Bells
is about 18" Deepo	line of pipe not uniform. Late and is just west of driveway.  FILED AT ENGINEER'S OFFICE 2-4-47
MSFECTOR FOR CITY	rancestal simily big 1000 100 100 100 100 100 100 100 100 1

## $\mathbf{N}$ ? $\mathbf{4905}$

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	1/9/20 3150
T. P. J.	ssillon, Ohio,1
RECEIVED OF	FEE OF \$-
FOR WHICH PERMISSION IS GRANTED	
TO TAPSEWER, ON	TO BOTTA STATEMATORS TO WORLD THE
OF LINE ST., TYPE OF	STREET COMPANY
THE PREMISES BEING LOT NO. 1753	, House No
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO	2323. DULY PASSED BY THE CITY COUNC

RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

Note. This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.