Nº 5509

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 9-25-50	_ IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 2994		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	Thech
WAS LATERAL AT CURBY YES	A transfer of the second of	ere
WAS ATTACHED TO MAIN Y25	- NAME OF CONTRACTOR ASTON	
SHOW BY DIAGRAM RELATION OF LAT	ERAL TO WALL OF BUILDING SERVED.	
ALLEN. AVE		
en en la companya de la companya de La companya de la co		
		1 77 de 188 (
SIGNED OF EAST COLOR	FILED AT ENGINEER'S OFFI	The state of the s
INSPECTOR FOR	DITY A COMMENT OF THE PART ENGINEER'S OFFI	
REMARKS:	niko la kota talak kilonga tilonga tilonga popular tilonga tilonga tilonga tilonga tilonga tilonga tilonga til Tilonga tilonga tilong	Graphical Control of the Control of

THE WAR LIFER WINDA IN THE OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

•	en e	Terrologiski skrapjišti		9/	ウ シ コンカール
	The second of th		MASSILLON, C	оніо, <i>Го</i>	7/19
D:	ECEIVED OF	· undo	22)	V. The second second	FEE OF S
	$\Delta = 0.00$	INTEDUTY	endy	Carel	Co
то тар	11		er, on the	71	
OF	2002)	n Wave. T	YPE OF STREET	aroi.	on of the second
∴THE PREM	ISES BEING LOT NO.	7737		ISÉ NO. <u>33</u>	24
		, ,		· · · · · · · · · · · · · · · · · · ·	,

Rules of the Department of Public Service.

Note. This permit covers work outside of building only. Any work is walls of building is subject to Massillon Board of Health Regulations.