FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 12-14-50 HOUSE NO. 1860	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH 7 DEEP
WAS LATERAL AT CURBY YES	NAME OF CONTRACTOR $Boger$
SHOW BY DIAGRAM RELATION OF LATE	ERAL TO WALL OF BUILDING SERVED.
	not starte
ng dia nganggapan katalong nga panggapan na katalong nga panggapan na katalong nga panggapan na katalong nga p Panggapanggapanggapan nga panggapan na katalong nga panggapan na katalong nga panggapan na katalong nga pangga	The Ci Deep
	7 Deep 1/24 TApprox. E. Cu.
PF fault	257? Main Sewer in Jet.
SIGNED INSPECTOR FOR CI	TY THE CONTROL OF TH
REMARKS:	

5536

Nº 5536 PERMIT TO TAP SEWER

RECEIVED OF RECEIVED OF RECEIVED OF RECEIVED OF SEWER, ON THE ST., TYPE OF STREET SANDAY. THE PREMISES BEING LOT NO. 8107 - 48108, HOUSE NO. 1860 WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL

Note. This permit covers work outside of building only. Any work is walls of building is subject to Massillon Board of Health Regulations.

RULES OF THE DEPARTMENT OF PUBLIC SERVICE.