## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 7-7-30	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 346		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	7' dech
WAS LATERAL AT CURE? Y = 5	. No como la la companya de la comp	,
WAS ATTACHED TO MAIN Veg	NAME OF CONTRACTOR AS Ton	
	ATERAL TO WALL OF BUILDING SERVED.	
254	25T, N.W.	
uning disembalah di kecamatan di Kecamatan di Kecamatan di Kecama	The state of the s	L-1/2/ ~ 64
4	4	\ \dag{\dag{\dag{\dag{\dag{\dag{\dag{\d
eam yellige a ser elakakı inc. seliklati e	All in the segretar and in the allowing the present and the property	\ \frac{1}{2}
v i	proceeding seed on a consideration and the seed of the	18/ 7'8
·		
1 1 2		and the same of the same of
/ INSPECTOR FOR	FILED AT ENGINEER'S OFFICE	Section 18 1
Z s Malbutt distinct A the area.  REMARKS:	All legithers Most resistive at periodical to other and	
DEMONICIO:	. :	<u> </u>

## FFICE OF THE DIRECTOR OF PUBLIC SERVICE

## PERMIT TO TAP SEWER Work to be done in accordance with Ordinance No. 2323, Duly passed by the City Council RULES, OF THE DEPARTMENT OF PUBLIC SERVICE.

Note. This permit covers work outside of building only. Any work is walls of building is subject to Massillon Board of Health Regulations.