Nº 5772

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 4-2/- 52	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 2.//		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH 25	E'E" boef
WAS LATERAL AT CURB? Ve S	and a constant of the control of the second	•
WAS ATTACHED TO MAIN / e 5	NAME OF CONTRACTOR Dia Ha	
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED.	
Erthe Ave	8	. •
ing a maganah di Milia da kabanah da kabanah Kabanah da kabanah da k	67.7	
and the property of the property of the property of	es la marti aforma aportario estar en el secolo del la companya del la company	radock
	7 2	25
4		- A
1 1 50		
SIGNED INSPECTOR FOR CIT	FILED AT ENGINEER'S OFFICE 5	<u> 3/52                                     </u>
The Augustian State of the State of	ากเกียงเมื่อ er couldny ไม่ priidfing ใกกรายงา	7

## Nº 5772 PERMIT TO TAP SEWER

ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR (C 9 1) LOCATE

Note. This permit covers work outside of building only. Any work it walls of building is subject to Massillon Board of Health Regulations.