## Nº 5807 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 5-16-52	IF SO HOW AND LOCATION FROM	7'deel
HOUSE NO. 1810	DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH	
WAS LATERAL AT CURB7	<ul> <li>Description of the control of the state of the section of the control of the contro</li></ul>	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR // A 17 17	
SHOW BY DIAGRAM RELATION OF LATE		
Lincolp	1. Way. E.	20
e pentro de la companya de la estada de la companya de la estada de la estada de la estada de la estada de la e La estada de la est	And the second s	14
SIGNED O La Plan	6 (A)	12/57
INSPECTOR FOR CO	The state of the s	20102

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

the state of the s	16
RECEIVED OF Mes Hud // ann	FEE OF \$
FOR WHICH PERMISSION IS GRANTED WIND MICH SERVICE	
TO TAP Santon SEWER ON THE north	
of Lin Way AVE., Type of Street pan	uch
ST.,	1810
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED RULES OF THE DEPARTMENT OF PUBLIC SERVICE.	BY THE CITY COUNCE

Note. This permit covers work outside of building only. Any work is walls of building is subject to Massillon Board of Health Regulations.

Fred Hann