N9 6245

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

/		*
DATE INSPECTED	IF SO HOW AND LOCATION FROM	
and the same of the	FIRST MANHOLE DOWN STREAM	
HOUSE NO.	and the second s	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH 2 6 2	5' Det
WAS LATERAL AT CURBY YOS	in following the second section of the second sections of the second section section sections of the second section sections of the second section sections of the second section sections of the section section sections of the section section section sections of the section section section sections of the section sec	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR	Penly
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED.	(A)
. Politica de La <u>Maria de La Carta de Maria de </u>		
		1
		1
		page 1
	The state of the s	
	3 7	
	*** \ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \	
() a Mada	0 214	
SIGNED INSPECTOR FOR CI	FILED ATTENDINEERS OFFICE	
on the state of th	Vastification toofine of gribiliad at allow 🧪	
REMARKS:	· ·	

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

$m A \sim 10^{10} N_{\odot}^{0} \sim 6245$ where $m M_{\odot}$

PERMIT TO TAP SEWER

Massillon, Ohio, 15
RRA
RECEIVED OF FEE OF 5 -
11 Fall Tool
FOR WHICH PERMISSION IS GRANTED
TO TAP SEWER, ON THE 7
of Dennison Dave Type of STREET (100)
THE PREMISES BEING LOT NO. 8522 , HOUSE NO. 826
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Lender

Note. This permit covers work outside of building only. Any work is walls of building is subject to Massillon Board of Health Regulations.