## Nº 6377 AND SIGNED WHEN RETURNED.

•		**
DATE INSPECTED 7-/3-5	1. 30 HOW AND LOCATION PROM	
	FIRST MANHOLE DOWN STREAM	•
HOUSE NO. /84/		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH	7'Deep
WAS LATERAL AT CURB? Yes	ginto de la cidada de Alega de Gerego de Alega de Servicio. Algunos	
WAS ATTACHED TO MAIN	— NAME OF CONTRACTOR A	Irana
SHOW BY DIAGRAM RELATION OF	LATERAL TO WALL OF BUILDING SERVED.	
ilo di kabulatan kabupaten ke	sa karaban sa pining karabanan sa arabah sa sa kaban sa	
	Commence of the second	
<b>11</b>	1/ 6	15.
	The state of the s	
The state of the s	we that the death extensions the way	
	1.8 /5	e Setting
	1 7 1	•
		- The state of the
$\sim 10$ .	9, 191	And the Control of th
SIGNED CON Fathern	FILLED AT ENGINEER'S OFFICE	8-4-55
INSPECTOR F	OR CITY	
REMARKS: LAY & GYZVE		•
· · · · · · · · · · · · · · · · · · ·	· · · · · · · · · · · · · · · · · · ·	

## Nº 6377

## PERMIT TO TAP SEWER

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

(MASSILLON, OHIO, 7//3/55 19
RECEIVED OF FEE OF S
FOR WHICH PERMISSION IS GRANTED When I here
TO TAP SAME SEWER, ON THE WEST
of Windson Rahar Type of STREET asplalt
THE PREMISES BEING LOT NO. 106 40 + 106 41, HOUSE NO. 1841

Work to be done in accordance with Ordinance No. 2323, duly passed by the City Counc Rules of the Department of Public Service.

Note. This permit covers work outside of building only. Any work is walls of building is subject to Massillon Board of Health Regulations.