## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR Nº 6408 AND SIGNED WHEN RETURNED.

HOUSE NO. 336		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH 20	8'0 2010
WAS LATERAL AT CURBI YES	ing the state of t	
WAS ATTACHED TO MAIN	- NAME OF CONTRACTOR	I wance
SHOW BY DIAGRAM RELATION OF LAT	FERAL TO WALL OF BUILDING SERVED.	
		3,
	*	1-7 curp
and the state of t	情况,如此时间的表现的是有可能的,如此时间的自由,如此所以的对象,以此的对象,是不知识的数据等。	1
< N		2 <b>0</b> `
< N. →	· · · · · · · · · · · · · · · · · · ·	χ <b>ο</b> `
$\langle N. \rangle$	· · · · · · · · · · · · · · · · · · ·	

## PERMIT TO TAP SEWER

THE REPORT OF 16408 Market Harmon  $_{
m N}$ 

MASSILLON, OHIO,
RECEIVED OF G. P. ALAMAN FEE OF S. G.
FOR WHICH PERMISSION IS GRANTED HOTELY BONE,
TO TAP SEWER, ON THE
OF 37th n(u) AVE TYPE OF STREET dut
THE PREMISES BEING LOT NO. 334-West View House No. 336
Work to be done in accordance with Ordinance No. 2323, duly passed by the City Counci
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.
NAME OF CONTRACTOR OF BIAMON
Note. This permit covers work outside of building only. Any work in

walls of building is subject to Massillon Board of Health Regulations.