Nº \_6813

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

HOUSE NO. 239	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE  LIDOWN STREAM TO DITCH AT  CURB LINE AND DEPTH  67 upli	team 4 7 Dec
WAS LATERAL AT CURB? Ye		
	NAME OF CONTRACTOR	Urban
SHOW BY DIAGRAM RELATION OF	LATERAL TO WALL OF BUILDING SERVED.	
	사 교통 프랑이는 사람들은 한국에 가지 않는데 함께 보는 것이 되는 것이다. 전기를 가지 않는데 하는데 하는데 하는데 하는데 하는데 하는데 하는데 하는데 하는데 하	
(1) 1		1 12 76 West
	ini (dansa di bergada di 1997) kalimpia dan di dan di baji kaji dabandi dibi dan jugaha peli. Ti baji da di pengandi da di dan di Bergana dan baji kaji da baji da di dan di dan di dan di dan di dan di dan	1 40
	[1] 그리고 이를 시작하는 경험이는 이번 발표, (Registrate) 등 경기를 모르는 당시하는 이름을 기가 하는 이번 등을 받았다. 중점에 들었다. 이번 등 기가 있다.	
		10 7 June 17
SIGNED RAYYO	Than FILED AT ENGINEER'S DEFICE	
(NSPECTOR	FOR CITY	
REMARKS	e former i de la filosofia de Maria de Compositorios de Maria de Mar	

Nº 6813

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

MASSILLON, OHIO, 200, 19
RECEIVED OF ANALL BULLALLY FEE OF \$ 2
FOR WHICH PERMISSION IS GRANTED RANGE TO THE STATE OF STA
TO TAP DAIL SEWER ON THE South
of 3 nd NE forwillowst. Type of STREET Oiled
THE PREMISES BEING LOT NO. 1718 , HOUSE NO. 1239 23

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCI RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR HARRY AS Medical

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.