Nº 7150

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

| DATE INSPECTED 9-9- | IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM | |
|---|--|-----------------------------------|
| HOUSE NO. 966 | | |
| SIZE OF PIPE USED | DISTANCE FROM FIRST MANHOLE MERSURMENT SIVEN DOWN STREAM TO DITCH ATC CURB LINE AND DEPTH TOUND 81/E0FMH @ N. | .BG E. Almeria 14 rs KoverLowr |
| WAS LATERAL AT CURB? | <u>/as</u> | 2 1/2 se |
| WAS ATTACHED TO MAIN | 1/0 NAME OF CONTRACTOR | 1 hans |
| SHOW BY DIAGRAM RELATION | OF LATERAL TO WALL OF BUILDING SERVED. | |
| | | |
| | 2 be | e p K |
| es a summar and a | . If we have a constraint of the constraint 49^{\prime} | J 3 |
| | ク· ドフル1 | A |
| N. | OVERCOOL / 500/8. | |
| 10 - | | ρ _/ |
| SIGNED INSPECT | OR FOR CITY FILED AT ENGINEER'S OFFICE | - |
| REMARKS | er da fato de la viva en fato de lifeta de talencia de trabajo de l'esta fin dividir la colonia. La colonia | |

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 7150 PERMIT TO TAP SEWER

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.